

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG21005951/AUCE2**Date:** 02/11/2021**REFERENCE**

Insured/Claimant:	PHANG SAY LANG	Policy No:	2070103255	
Date of Loss:	10/05/2021	Nature of Claim:	OD	Claim No: 3938814218SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMT6971Z		
Make & Model:	AUDI Q3 SPORTBACK, 1.4 TFSI S TRONIC (17) (A)	Engine No:	CZD892874
Reg. Date:	14/07/2020 (Man. Year: 2020)	Chassis No:	WAUZZZF38L1094384
Colour:	Black	Odometer:	15208 km
Engine Capacity:	1395 cc		
Market Value/New Car Price:	S\$148,000.00		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/65 R17	Rear Tyre Size:	215/65 R17
Front Left Side:	Falken 6 mm	Rear Left Side:	Falken 6 mm
Front Right Side:	Falken 6 mm	Rear Right Side:	Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	15,665.00	8,738.24	6,926.76	44.22
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,252.00	4,802.00	3,450.00	41.81
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	23,917.00	13,540.24	10,376.76	43.39
- Excess (\$\$)	400.00	400.00	0.00	0.00
(\$\$)	23,517.00	13,140.24	10,376.76	44.12
+ GST 7.00/7.00% (\$\$)	1,646.19	919.82	726.37	44.12
Nett Amount (\$\$)	25,163.19	14,060.06	11,103.13	44.12

INSPECTION

Date of Assignment:	19/05/2021	
Date Inspected:	18/05/2021	Inspected At: Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	5.0 days	

Adjuster: ADRIAN LING**Manager:** Tan Hui Zhen

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	1,335.00 FS	*1,068.00 FS
2	1		*FRONT BUMPER CONNECTING PC	Not Necessary	145.00 FS	*- FS
3	1		*FRONT BUMPER FIXING PARTS	Not Necessary	414.00 FS	*- FS
4	1		*FRONT BUMPER CLOSING ELEMENT RH	Not Necessary	59.00 FS	*- FS
5	1		*FRONT BUMPER CLOSING ELEMENT	Not Necessary	190.00 FS	*- FS
6	1		*FRONT BUMPER SPOILER	Deformed	763.00 FS	*610.00 FS
7	1		*AIR GUIDE GRILLE BLACK INNER RH	Deformed	153.00 FS	*122.00 FS
8	1		*FRONT BUMPER OUTER TRIM - GREY RH	Cut	164.00 FS	*130.80 FS
9	1		*FRONT PARKING AID SENSOR SUPPORT RH	Not Necessary	25.00 FS	*- FS
10	1		*FRONT FOAM FILLER	Not Necessary	102.00 FS	*- FS
11	1		*FRONT BUMPER REINFORCEMENT BEAM	Not Necessary	916.00 FS	*- FS
12	1		*FRONT BUMPER GUIDE SECTION RH	Damaged	39.00 FS	*30.48 FS
13	1		*SIGNAL HORN LOW TONE	Not Necessary	130.00 FS	*- FS
14	1		*SPRING SHACKLE RH	Not Necessary	22.00 FS	*- FS
15	1		*FRONT SENSOR	Not Necessary	0.00 FS	*- FS
			(NPA)			
16	4		*FRONT SENSOR SEAL RING	Not Necessary	14.00 FS	*- FS
17	1		*FRONT FENDER RH	Dented	1,286.00 FS	*1,028.80 FS
18	1		*FRONT FENDER ATTACHMENTS PARTS	Not Necessary	63.00 FS	*- FS
19	1		*FRONT FENDER BRACE RH	Bent	88.00 FS	*69.76 FS
20	1		*FRONT FENDER BRACKET RH	Damaged	32.00 FS	*24.88 FS
21	1		*WHEEL HOUSING LINER	Not Necessary	0.00 FS	*- FS
			(NPA)			
22	1		*WHEEL HOUSING LINER ATTACHMENTS PARTS	Not Necessary	101.00 FS	*- FS
23	1		*WHEEL HOUSING COVER RH	Not Necessary	16.00 FS	*- FS
24	1		*HEADLIGHT MOUNTING RH	Not Necessary	118.00 FS	*- FS
25	1		*LED HEADLIGHT	Cracked	5,589.00 FS	*4,471.20 FS
26	1		*LED WITH HEAT SINK	Not Necessary	781.00 FS	*- FS
27	1		*POWER MODULE FOR HEADLIGHT	Not Necessary	758.00 FS	*- FS
28	1		*HOSE	Not Necessary	24.00 FS	*- FS
29	1		*HEADLIGHT LIFT CYLINDER RH	Not Necessary	210.00 FS	*- FS
30	1		*LIFT CYLINDER HOSE	Not Necessary	80.00 FS	*- FS
31	2		*WHEEL COVER FRONT LH / RH	N/S Necessary / O/S Cut	1,072.00 FS	*857.60 FS
32	1		*DOOR COVER FRONT RH	Repair	370.00 FS	*- FS
33	1		*SUNDRIES	Necessary	250.00 FS	*40.32 FS
34	1		*FRONT BUMPER INNER TRIM - GREY RH	Cut	356.00 FS	*284.40 FS

F=Franchise part. S=SpcNett.

Total Parts (\$) **15,665.00** **8,738.24**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO REMOVE AND TRANSFER RHS HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	400.00	250.00
3	TO DISMANTLE AND REINSTALL RHS FRONT DOOR PANEL TRIM. TO REMOVE AND REINSTALL RHS WING MIRROR ASSY TO FACILITATE RESPRAY OF RHS FRONT DOOR	New	280.00	280.00
4	TO DISMANTLE AND RENEW FRONT BUMPER, RHS FRONT FENDER AND RHS HEADLIGHT. REORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	2,400.00	1,000.00
5	TO RESPRAY FRONT BUMPER, FRONT BUMPER LOWER SPOILER, RHS FRONT FENDER, RHS FRONT DOOR AND BOTH FRONT WHEEL ARCH TRIMS	New	4,500.00	2,600.00
6	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (\$\$)			8,252.00	4,802.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >