



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBP 3605C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
2	FRONT FORK TUBE ASSY (CONSISTENT)	SERVICEABLE	640.00	-
1	FORK UNDER BRACKET (CONSISTENT)	NOT NECESSARY	205.00	-
1	FRONT WHEEL RIM (CONSISTENT)	BENT	320.00	280.00
1	FRONT RIM SHAFT (CONSISTENT)	NOT NECESSARY	95.00	-
1	FRONT RIM BEARING (CONSISTENT)	NECESSARY	52.00	38.00
1	FRONT BRAKE DISC (CONSISTENT)	NOT NECESSARY	185.00	-
1	HEADLAMP (CONSISTENT)	CUT	280.00	250.00
1	HANDLE -BAR (CONSISTENT)	SERVICEABLE	102.00	-
1	HANDLE -BAR END (O/S) (CONSISTENT)	CUT	95.00	30.00
1	HANDPHONE HOLDER (CONSISTENT)	CUT	85.00	50.00
1	SET SIDE MIRRORS (CONSISTENT)	CUT	110.00	110.00
1	BASKET (CONSISTENT)	CUT	65.00	65.00
1	FRONT HORN INNER COVER CENTRE BLACK (CONSISTENT)	TO REPAIR SEE LABOUR	78.00	-
1	FRONT SIGNALS (N/S) (CONSISTENT)	BROKEN	150.00	70.00
1	BRAKE LEVER (CONSISTENT)	CUT	65.00	65.00
1	SET FAIRING ASSY (CONSISTENT)	CRACKED	560.00	560.00
1	BRAKE PEDAL (CONSISTENT)	TO REPAIR SEE LABOUR	65.00	-
1	GEAR PEDAL (CONSISTENT)	BENT	58.00	58.00
1	MASTER PUMP (CONSISTENT)	CUT	285.00	285.00
1	SET REAR FOOTREST (CONSISTENT)	NOT NECESSARY	88.00	-
1	REAR FOOTREST BRACKET (CONSISTENT)	NOT NECESSARY	98.00	-
1	EXHAUST ASSY (CONSISTENT)	DENTED / BENT	520.00	425.00
1	EXHAUST PROTECTOR -FRONT (CONSISTENT)	SERVICEABLE	52.00	-
1	EXHAUST PIPE END COVER (CONSISTENT)	CUT	65.00	65.00
1	REAR FENDER (CONSISTENT)	DEFORMED	105.00	105.00
1	REAR SIGNAL (N/S) (CONSISTENT)	BROKEN	140.00	70.00
	LESS 10% DISCOUNT		-456.30	-252.60
			4,106.70	2,273.40



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>SPECIAL NETT ITEMS</u>			
1	SET NUMBER PLATE (SN) (CONSISTENT)	FRT NECESSARY / REAR BENT	28.00	20.00
2	FORK OILS (SN) (CONSISTENT)	NOT NECESSARY	30.00	-
2	FORK OIL SEALS (SN) (CONSISTENT)	NOT NECESSARY	56.00	-
1	SET STEERING CONE (SN) (CONSISTENT)	NOT NECESSARY	98.00	-
1	E.R.P IU (SN) (CONSISTENT)	SERVICEABLE	175.00	-
1	SET STICKER (SN) (CONSISTENT)	NECESSARY	95.00	95.00
			482.00	115.00
	<u>LABOUR</u>			
	TO PROVIDE TOWING SERVICE (LOD).	NOT NECESSARY	50.00	-
	TO CHECK WIRING AND RESET HEADLAMP FOCUSING.	NOT NECESSARY	80.00	-
	TO PROVIDE LABOUR.INCLUSIVE OF THE REPAIR OF FRONT HORN INNER COVER CENTRE BLACK AND BRAKE PEDAL .		480.00	280.00
	TO REPAIR BODY FRAME.	NOT NECESSARY	350.00	-
			960.00	280.00
GRAND TOTAL			5,548.70	2,668.40

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			2,100.00
---	--	--	-----------------

Report Ref No. CC4/ASM21005964/Upa3q2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.