

## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT SOMPO INSURANCE SINGAPORE PL CS3/SMO21005965/Kvf3e2 Ref: 50 RAFFLES PLACE #03-03 SINGAPORE LAND Date: 24/06/2021 **TOWER SINGAPORE 048623** Code: SMO 1. Policy Particulars :- (THIRD PARTY CLAIM) Insured Veh. **GBJ 675B** SJM 1860R Veh. Inspected Policy No. D20MTPCVE003458 Coverage (\$) 0.00 Claim No. CMTD2101528/SYH Excess (\$) 0.00 **GRACE TEO** 19/05/2021 **Assign From Assign Date Vehicle Particulars & Condition** 2. HONDA FIT (A) c.c 1339 Make & Model HIDDEN 2008 Engine No. Year of Reg. GE61105544 METALLIC WHITE Chassis No. Colour 217398 KM Odometer Steering IN ORDER **IN ORDER** SPORTS RIM **Brakes** Modification GOOD General 3. **Conditions of Tyres** Size Make **Balance** R/H Front Tyre 195/55 R15 MICHELIN 3 mm 195/55 R15 **MICHELIN** L/H Front Tyre 3 mm 195/55 R15 **MICHELIN** R/H Rear Tyre 3 mm **MICHELIN** L/H Rear Tyre 195/55 R15 3 mm **Description of Damages** 4. THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION. 5. **General Information** 13/05/2021 20/05/2021 ( 09:50 AM ) **Accident Date** Inspect Date / Time LYE DESIGNS Survey held at 10, AMK AUTOPOINT, 04-04 ANG MO KIO IND PARK 2A, SINGAPORE 568047 5a. Remarks A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$1,500-\$2,500

Report Ref No. CS3/SMO21005965/Kvf3e2

**Estimate Days of Repair** 

Inspected By

5b.

KONG SENG CHEONG

**Licensed Appraiser** 

**ESTIMATED NORMAL PERIOD FOR REPAIR:** 

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

3 Working Days

REGD Auto Consultant-SAE, Licensed Appraiser