

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

India International Insurance Pte Ltd  
64 Cecil Street, #04-00 IOB Building  
Singapore 049711

**Our File No:** CS/III21005967/KVF3E2

**Date:** 16/07/2021

### REFERENCE

Insured/Claimant: Flotech Controls Pte Ltd Policy No: D18MCV0001978\_02  
Date of Loss: 03/05/2021 Nature of Claim: OD Claim No: MCV2021D0001893

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBB2280K**  
Make & Model: MITSUBISHI CANTER, 3.0 D (A) Engine No: 4M42A64102  
Reg. Date: 06/10/2008 (Man. Year: 2008) Chassis No: FB70BBA10637  
Colour: White Odometer: 129563 km  
Engine Capacity: 2977 cc  
Market Value/New Car Price: S\$14,000.00  
Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

### CONDITION OF TYRES

Front Tyre Size: 195 R15X8 Rear Tyre Size: 205/65 R15  
Front Left Side: Bridgestone 8 mm Rear Left Side: Michelin 5/5 mm  
Front Right Side: Bridgestone 8 mm Rear Right Side: Michelin 5/5 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,496.00	245.00	1,251.00	83.62
Miscellaneous Items	11.00	11.00	0.00	0.00
Labour	2,050.00	1,130.00	920.00	44.88
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>3,557.00</b>	<b>1,386.00</b>	<b>2,171.00</b>	<b>61.03</b>
<b>- Excess (S\$)</b>	0.00	600.00	-600.00	
<b>(S\$)</b>	3,557.00	786.00	2,771.00	77.90
<b>+ GST 7.00/7.00% (S\$)</b>	248.99	55.02	193.97	77.90
<b>Nett Amount (S\$)</b>	<b>3,805.99</b>	<b>841.02</b>	<b>2,964.97</b>	<b>77.90</b>

### INSPECTION

Date of Assignment: 19/05/2021 Present Location: BH Auto Services Pte Ltd (Sin Ming)  
BH Auto Services Pte Ltd (Sin Ming)  
Date Inspected: 25/05/2021 Inspected At: Blk 1 Sin Ming Industrial Estate Sector C,  
#01/111/113/115/117  
Singapore 575636  
Estimated Period of Repair: 4.0 days

**Adjuster:** KENNETH KONG

**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	(Last Synchronised: 16 Jul 2021)	
<b>Parts:</b>	N/A	MITSUBISHI CANTER 3.0 D (A) (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for GBB2280K)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*Front Headlamp Set RH (WCP)	Serviceable	330.00 F	*- F	
2	1		*Front Signal lamp RH (WCP)	Broken	55.00 F	*55.00 F	
3	1		*Front Side lamp RH (WCP)	Broken	50.00 F	*25.00 F	
4	1		*Front Bumper (WCP)	Bent	120.00 F	*120.00 F	
5	1		*Front Fender RH (WCP)	Repair	250.00 F	*- F	
6	1		*Stepper Garnish RH (WCP)	Serviceable	45.00 F	*- F	
7	1		*Door RH (WCP)	Repair	450.00 F	*- F	
8	1		*Sticker Door RH	Necessary	60.00 F	*25.00 FS	
					<b>Sub Total (\$\$)</b>	<b>1,360.00</b>	<b>225.00</b>
					<b>+ Margin on L,N Items 10.00/10.00% (\$\$)</b>	136.00	20.00
					<b>Total Parts (\$\$)</b>	<b>1,496.00</b>	<b>245.00</b>

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<b>Miscellaneous Items</b>				
1	1	OD/TP Case (Insurer)	11.00	11.00
			<b>Sub Total (\$\$)</b>	<b>11.00</b>

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	Provide skill labour to remove all damaged parts, panel beat, cut & weld if necessary and align all panel and reinstall all damaged parts. (Front)	New	800.00	500.00
2	Provide skill labour & material to putty all damaged parts & panel & to respray with 2K paint with oven spray booth facilities	New	900.00	550.00
3	Dismantle and transfer door fittings and mechanism to new door	New	200.00	60.00
4	Provide skill and labour to disconnect and check electrical wiring for signal light	New	150.00	20.00
			<b>Gross Labour Cost (\$\$)</b>	<b>1,130.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >