

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI21005968/AVF3N2**Date:** 20/08/2021REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMHCSNW00004432001
<b>Claimant Vehicle No :</b>	SKV1238D	<b>Insured Vehicle No :</b>	SMC9757X
Date of Loss:	07/05/2021	Nature of Claim:	TP
		Claim No:	SNM21D202678

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SKV1238D</b>		
Make & Model:	AUDI A5, 2.0 SB TFSI S TRONIC (DESIGN) (A)	Engine No:	CVK076459
Reg. Date:	14/02/2019 (Man. Year: 2019)	Chassis No:	WAUZZZF59KA026627
Colour:	White	Odometer:	61303 km
Engine Capacity:	1984 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	245/40R18	Rear Tyre Size:	245/40R18
Front Left Side:	Goodyear 6 mm	Rear Left Side:	Goodyear 6 mm
Front Right Side:	Goodyear 6 mm	Rear Right Side:	Goodyear 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	5,218.00	4,751.20	466.80	8.95
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,752.00	2,152.00	600.00	21.80
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>7,970.00</b>	<b>6,903.20</b>	<b>1,066.80</b>	<b>13.39</b>
<b>+ GST 7.00/7.00% (S\$)</b>	557.90	483.22	74.68	13.39
<b>Nett Amount (S\$)</b>	<b>8,527.90</b>	<b>7,386.42</b>	<b>1,141.48</b>	<b>13.39</b>

INSPECTION

Date of Assignment:	19/05/2021		
Date Inspected:	19/05/2021	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	3.0 days		

**Adjuster:** ADRIAN LING**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

**REPAIR DETAILS****Reference****Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 20 Aug 2021)**Parts:** 143 AUDI A5 2.0 SB TFSI S TRONIC (DESIGN) (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** (Unsubmitted, no print-code for SKV1238D)**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.**Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*REAR BUMPER	Deformed	2,504.00 FS	*2,504.00 FS	
2	1		*REAR BUMPER FIXING PARTS	Not Necessary	165.00 FS	*- FS	
3	1		*REAR BUMPER SECURING STRIP	Necessary	223.00 FS	*222.50 FS	
4	1		*REAR BUMPER CHROME TRIM	Cut	1,016.00 FS	*1,016.00 FS	
5	1		*REAR BUMPER REFLECTOR LH/RH	O/s Damaged	82.00 FS	*40.70 FS	
6	1		*REAR BUMPER CARRIER	Bent	940.00 FS	*940.00 FS	
7	2		*REAR BUMPER CARRIER SEAL	Necessary	28.00 FS	*28.00 FS	
8	2		*REAR BUMPER GUIDE SECTION-LH/RH	Not Necessary	46.00 FS	*- FS	
9	2		*REAR BUMPER PARKING AID SENSOR (NPA)	Not Necessary	0.00 FS	*- FS	
10	4		*REAR BUMPER PARKING AID SENSOR SEAL RING	Not Necessary	14.00 FS	*- FS	
11	1		*SUNDRIES	Not Necessary	200.00 FS	*- FS	
					<b>Total Parts (\$\$)</b>	<b>5,218.00</b>	<b>4,751.20</b>

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR.CHECK FUNCTION	New	360.00	360.00
2	TO DISMANTLE AND RENEW REAR BUMPER.RE-ORGANISE CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	New	1,200.00	800.00
3	TO RESPRAY REAR BUMPER	New	1,000.00	800.00
4	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
<b>Gross Labour Cost (\$)</b>			<b>2,752.00</b>	<b>2,152.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >