

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI21005970/AVF3N2**Date:** 06/09/2021**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNW00071302003	
<b>Claimant Vehicle No :</b>	SMD9229Z	<b>Insured Vehicle No :</b>	GBF2379P	
Date of Loss:	16/05/2021	Nature of Claim:	TP	Claim No: SNM21D202880/C02/TANCHC

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>SMD9229Z</b>		Engine No:	CAV137775
Make & Model:	VOLKSWAGEN SCIROCCO, 1.4 TSI (A)		Chassis No:	WVWZZZ13ZAV421258
Reg. Date:	18/12/2009 (Man. Year: 2009)		Odometer:	169470 km
Colour:	Blue			
Engine Capacity:	1390 cc			
Market Value/New Car Price:	N/A			
Sum Insured (\$\$):	<b>Market Value/New Car Price</b>			

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:	245/35R18	Rear Tyre Size:	245/35R18
Front Left Side:	Goodyear 6 mm	Rear Left Side:	Goodyear 6 mm
Front Right Side:	Goodyear 6 mm	Rear Right Side:	Goodyear 6 mm

*The above values represent the remaining tyre tread depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	5,226.65	2,052.96	3,173.69	60.72
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,810.00	1,080.00	2,730.00	71.65
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>9,036.65</b>	<b>3,132.96</b>	<b>5,903.69</b>	<b>65.33</b>
<b>Approved Total (Overridden) (\$\$)</b>		<b>2,500.00</b>		
<b>(\$\$)</b>	9,036.65	2,500.00	6,536.65	72.33
<b>+ GST 7.00/7.00% (\$\$)</b>	632.57	175.00	457.57	72.34
<b>Nett Amount (\$\$)</b>	<b>9,669.22</b>	<b>2,675.00</b>	<b>6,994.22</b>	<b>72.33</b>

**INSPECTION**

Date of Assignment:	19/05/2021	
Date Inspected:	20/05/2021	Inspected At: Cas Garage Pte Ltd (HQ) No.1, Kaki Bukit Ave 6, #02-22 Autobay Singapore 417883
Estimated Period of Repair:	4.0 days	

**Adjuster:** ADRIAN LING**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

**Part Source:** MRM-SG      Version: 1.0 (Last Synchronised: 06 Sep 2021)

**Parts:** 144      VOLKSWAGEN SCIROCCO 1.4 TSI (A) (Catalogue:Merimen Singapore 1.0)

**Labour:** Repairer's      (Price-denominated Standard List)

**Print Code:** (Unsubmitted, no print-code for SMD9229Z)

**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*RH DOOR	Dented	1,687.20 FL	*1,687.20 FL
2	1		*RH DOOR PROTECTOR	Cut	158.60 FL	*158.60 FL
3	1		*RH DOOR OUTER GLASS MOULDING	Not Necessary	154.80 FL	*- FL
4	1		*RH DOOR OUTER HANDLE	Not Necessary	125.30 FL	*- FL
5	1		*RH DOOR OUTER HANDLE KNOB	Not Necessary	94.20 FL	*- FL
6	1		*RH DOOR LOCK	Not Necessary	375.60 FL	*- FL
7	1		*RH DOOR WEATHERSTRIP-DOOR	Not Necessary	168.90 FL	*- FL
8	1		*RH DOOR WEATHERSTRIP-FRAME	Not Necessary	248.20 FL	*- FL
9	1		*REAR FENDER RH	Repair	1,523.70 FL	*- FL
10	1		*REAR FENDER PROTECTOR RH	Cut	168.60 FL	*168.60 FL
11	1		*REAR FENDER FUEL LIP COVER RH	Not Necessary	218.80 FL	*- FL
12	1		*REAR FENDER GLASS W MOULDING RH	Not Necessary	494.60 FL	*- FL
13	1		*RH DOOR OUTER HANDLE-CARBON FIBRE COVER	Cut	155.00 FS	*155.00 FS
14	1		*RH DOOR OUTER HANDLE KNOB-CARBON FIBRE COVER	Cut	85.00 FS	*85.00 FS
15	1		*REAR FENDER GLASS SEALANT	Not Necessary	80.00 FS	*- FS
16	1		*SET REAR FENDER INNER COWLING CLIPS	Not Necessary	30.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$)</b>	<b>5,768.50</b>	<b>2,254.40</b>
<b>- List Item Discount on L Items 10.00/10.00% (\$)</b>	541.85	201.44
<b>Total Parts (\$)</b>	<b>5,226.65</b>	<b>2,052.96</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO PANEL BEAT/STRAIGHTEN/REALIGN ACCIDENT AFFECTED AREAS	New	1,500.00	500.00
2	TO RESPRAY ACCIDENT AFFECTED PORTION	New	1,500.00	400.00
3	TO TUFF COAT AFFECTED AREAS	New	100.00	50.00
4	TO REMOVE/REFIX RH INTERIOR UPHOLSTERY AND SEATS	New	200.00	50.00
5	TO REMOVE/REFIX REAR RH FENDER GLASS	New	150.00	0.00
6	TO REMOVE/REFIX FUEL NECK	New	150.00	0.00
7	TO REMOVE/REFIX/TRANSFER RH DOOR MECHANISMS	New	150.00	40.00
8	TO PERFORM RESET POWER WINDOW SETTING	New	60.00	40.00
<b>Gross Labour Cost (\$\$)</b>			<b>3,810.00</b>	<b>1,080.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >