

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21005975/DVF3Q2**Date:** 14/03/2022REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNW00156252000
Claimant Vehicle No :	SMN8199E	Insured Vehicle No :	SJA8248B
Date of Loss:	17/05/2021	Nature of Claim:	TP
		Claim No:	SNM21D202841/C02/THAMYL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMN8199E	Engine No:	CAV230795
Make & Model:	VOLKSWAGEN SCIROCCO, 1.4 (A)	Chassis No:	WVWZZZ13ZBV014329
Reg. Date:	25/11/2010 (Man. Year: 2010)	Odometer:	225276 km
Colour:	Grey		
Engine Capacity:	1390 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/40 R18	Rear Tyre Size:	235/40 R18
Front Left Side:	Goodyear 5 mm	Rear Left Side:	Goodyear 5 mm
Front Right Side:	Goodyear 5 mm	Rear Right Side:	Goodyear 5 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	16,139.30	1,802.20	14,337.10	88.83
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,350.00	880.00	4,470.00	83.55
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	21,489.30	2,682.20	18,807.10	87.52
Approved Total (Overridden) (\$\$)		2,000.00		
(\$\$)	21,489.30	2,000.00	19,489.30	90.69
+ GST 7.00/7.00% (\$\$)	1,504.25	140.00	1,364.25	90.69
Nett Amount (\$\$)	22,993.55	2,140.00	20,853.55	90.69

INSPECTION

Date of Assignment:	19/05/2021	
Date Inspected:	18/05/2021 Inspected At:	JWG International Pte Ltd (HQ) Blk 10, Ang Mo Kio Ind Park 2A., #03-08 AMK AutoPoint Singapore 568047
Estimated Period of Repair:	4.0 days	

Adjuster: BRYAN TANI**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 14 Mar 2022)
Parts:	M1-COUPE	VOLKSWAGEN SCIROCCO 1.4 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMN8199E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER LH	Repair	1,272.00 FL	*- FL
2	1		*FRONT FENDER INNER SHIELD LH	Serviceable	195.00 FL	*- FL
3	1		*FRONT WHEEL BEARING LH	Not Necessary	394.00 FL	*- FL
4	1		*FRONT WHEEL BEARING HUB LH	Not Necessary	422.00 FL	*- FL
5	1		*FRONT KNUCKLE ARM LH	Not Necessary	782.00 FL	*- FL
6	1		*FRONT LOWER ARM LH	Not Necessary	497.00 FL	*- FL
7	1		*FRONT UPPER ARM LH	Not Necessary	452.00 FL	*- FL
8	1		*FRONT THRUST ARM LH	Not Necessary	471.00 FL	*- FL
9	1		*FRONT ABSORBER LH	Not Necessary	479.00 FL	*- FL
10	1		*FRONT STABILIZER BAR	Not Necessary	501.00 FL	*- FL
11	1		*FRONT STABILIZER LINK LH	Not Necessary	209.00 FL	*- FL
12	1		*FRONT TIE ROD LH	Not Necessary	298.00 FL	*- FL
13	1		*FRONT TIE ROD END LH	Not Necessary	369.00 FL	*- FL
14	1		*HEAD LAMP LH	Not Necessary	2,493.00 FL	*- FL
15	1		*HEAD LAMP LOWER BRACKET LH	Not Necessary	193.00 FL	*- FL
16	1		*FRONT BUMPER	Mtg Broken	1,592.00 FL	*1,058.00 FL
17	2		*FRONT BUMPER SIDE RETAINER LH/RH	Serviceable	258.00 FL	*- FL
18	1		*FRONT FENDER INNER SHIELD CLIPS	Not Necessary	50.00 FS	*- FS
19	1		*FRONT FENDER & BUMPER WRAP	Necessary	1,000.00 FS	*400.00 FS
20	1		*FRONT FENDER STICKER	Necessary	500.00 FS	*100.00 FS
21	1		*CARBON FIBRE BONNET	Serviceable	2,400.00 FS	*- FS
22	1		*SPORT RIM	Cut	2,000.00 FS	*350.00 FS
23	1		*TYRE	Not Necessary	400.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	17,227.00	1,908.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	1,087.70	105.80
Total Parts (\$\$)	16,139.30	1,802.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE & PANEL BEAT ALL DAMAGED ABOVE PARTS & PANELS	New	2,000.00	400.00
2	TO RESPRAY NEW PAINTWORK FOR ALL DAMAGED AREAS	New	2,000.00	400.00
3	TO TUFF COAT DAMAGED AREAS	New	150.00	20.00
4	TO RNR FRONT UNDERCARRIAGE TO FACILITATE REPAIRS	New	500.00	0.00
5	TO CONDUCT COMPUTERIZED WHEEL ALIGNMENT	New	200.00	60.00
6	TO CHECK & REFIX ALL ELECTRICAL WIRINGS	New	200.00	0.00
7	TO COMPUTERIZE DIAGNOSE FAULT CODES & CONTROL UNITS ,RESET ALL MEMORIES TO FACTORY DEFAULT SETTINGS	New	300.00	0.00
Gross Labour Cost (\$)			5,350.00	880.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >