

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21005980/T1TCN2**Date:** 10/12/2021**REFERENCE**Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMCVSNW00060332006

Claimant Vehicle No : SJT6863M**Insured Vehicle No :** GW5419P

Date of Loss: 15/05/2021

Nature of Claim: TP

Claim No: SNM21D202843/C02/TANKW

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SJT6863M**

Make & Model: HYUNDAI AVANTE, 1.6 (A)

Engine No: G4FC9U656160

Reg. Date: 27/10/2009 (Man. Year: 2009)

Chassis No: KMHU41BR9U760438

Colour: Maroon

Odometer: 115880 km

Engine Capacity: 1591 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/65 R15

Rear Tyre Size: 185/65 R15

Front Left Side: Bridgestone 6 mm

Rear Left Side: Bridgestone 6 mm

Front Right Side: Bridgestone 6 mm

Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,392.70	3,342.72	5,049.98	60.17
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,850.00	1,240.00	1,610.00	56.49
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	11,242.70	4,582.72	6,659.98	59.24
Approved Total (Overridden) (\$\$)		3,600.00		
Nett Amount (\$\$)	11,242.70	3,600.00	7,642.70	67.98

INSPECTION

Date of Assignment: 08/12/2021

Date Inspected: 19/05/2021

Inspected At:

25 KAKI BUKIT ROAD 4
#01-44 SYNERGY @ KAKI BUKIT
REPAIRER: TSL AUTO GARAGE

Estimated Period of Repair: 5.0 days

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** DENISE TAY KWEE CHENG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 09 Dec 2021)
Parts:	143	HYUNDAI AVANTE 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJT6863M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	758.00 FL	*461.00 FL
2	1		*FRONT BUMPER REINFORCEMENT	Bent	689.00 FL	*254.00 FL
3	1		*FRONT BUMPER SPONGE	Cracked	212.00 FL	*118.00 FL
4	1		*FRONT BUMPER SIDE RETAINER	Deformed	65.00 FL	*65.00 FL
5	1		*FRONT BUMPER FOG LAMP RH	Not Necessary	398.00 FL	*- FL
6	1		*FRONT BUMPER FOG LAMP OUTER COVER RH	Deformed	259.00 FL	*198.00 FL
7	1		*FRONT GRILLE	Not Necessary	569.00 FL	*- FL
8	1		*FRONT GRILLE LOGO	Not Necessary	113.00 FL	*- FL
9	1		*FRONT GRILLE TOP GARNISH	Not Necessary	179.00 FL	*- FL
10	1		*FRONT GRILLE BASE	Not Necessary	298.00 FL	*- FL
11	1		*FRONT SUPPORT PANEL TOP GARNISH	Not Necessary	189.00 FL	*- FL
12	1		*RH FRONT HEADLAMP	Cracked	1,796.00 FL	*680.00 FL
13	1		*RH FRONT HEADLAMP LOWER BRACKET	Bent	159.00 FL	*67.20 FL
14	1		*RH FRONT HEADLAMP SIDE BRACKET	Deformed	65.00 FL	*65.00 FL
15	1		*RH FRONT FENDER	Bent	589.00 FL	*466.50 FL
16	1		*RH FRONT FENDER INNER SHIELD	Torn	259.00 FL	*195.40 FL
17	1		*FRONT SUPPORT PANEL	Cracked	1,159.00 FL	*791.00 FL
18	1		*BONNET	Not Necessary	1,021.00 FL	*- FL
19	1		*WIPER WASHER TANK	Deformed	321.00 FL	*154.70 FL
20	1		*WIPER WASHER TANK MOTOR	Distorted	298.00 FL	*114.60 FL
21	1		*RH AIR DUCT	Not Necessary	55.00 FL	*- FL
22	1		*FRONT FENDER EMBLEM	Necessary	48.00 FL	*48.00 FL
23	1		*FRONT BUMPER CLIPS	Necessary	80.00 FS	*30.00 FS
24	1		*FRONT FENDER INNER SHIELD CLIPS	Necessary	80.00 FS	*20.00 FS
25	1		*FRONT HEADLAMP CLIPS	Not Necessary	8.50 FS	*- FS
26	1		*RH FRONT RIM	Dented	350.00 FS	*350.00 FS
27	1		*RH FRONT TYRE	Not Necessary	195.00 FS	*- FS
28	1		*FRONT GRILLE CLIPS	Not Necessary	80.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	10,292.50	4,078.40
- List Item Discount on L Items 20.00/20.00% (\$\$)	1,899.80	735.68
Total Parts (\$\$)	8,392.70	3,342.72

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR FOR PANEL BEATING	New	1,400.00	600.00
2	LABOUR FOR SPRAYPAINTING	New	1,000.00	500.00
3	TO APPLY TUFF COAT/RUST PROOF ON ACCIDENT AREAS	New	250.00	30.00
4	WIRING CHECK	New	80.00	30.00
5	TO CONDUCT WHEEL ALIGNMENT	New	120.00	80.00
Gross Labour Cost (\$)			2,850.00	1,240.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >