

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/EG121005981/BQF3N2**Date:** 05/10/2021REFERENCE

Handling Insurer: ERGO Insurance Pte. Ltd.

Policy No:

Claimant Vehicle No : FBK7096X**Insured Vehicle No :** YP8960X

Date of Loss: 07/05/2021

Nature of Claim:

TP

Claim No: CDMCG21000880

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **FBK7096X**

Make & Model: YAMAHA YZF-R15, 155cc ABS

Engine No: 2PB2002645

Reg. Date: 17/12/2015 (Man. Year: 2015)

Chassis No: ME1KG0690G2001871

Colour: Red

Odometer: 58733 km

Engine Capacity: 150 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 90/80/17

Rear Tyre Size:

130/70/17

Front Left Side: Dunlop 4 mm

Rear Left Side:

Bridgestone 4 mm

Front Right Side: 0 mm

Rear Right Side:

0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,590.80	4,695.27	4,895.53	51.04
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,795.00	760.00	1,035.00	57.66
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	11,385.80	5,455.27	5,930.53	52.09
Approved Total (Overridden) (S\$)		3,300.00		
(S\$)	11,385.80	3,300.00	8,085.80	71.02
+ GST 7.00/7.00% (S\$)	797.01	231.00	566.01	71.02
Nett Amount (S\$)	12,182.81	3,531.00	8,651.81	71.02

INSPECTION

Date of Assignment: 19/05/2021

Date Inspected: 20/05/2021 Inspected At:

Ms Car Auto Pte Ltd (HQ)

8 KAKI BUKIT AVE 4 #01-07 PREMIER @ KAKI

BUKIT

Singapore 415875

Estimated Period of Repair: 4.0 days

Adjuster: Lim Teow Guan**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 05 Oct 2021)	
Parts:	N/A	YAMAHA YZF-R15 155cc ABS (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FBK7096X)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER	Cut	265.00 FL	*180.00 FL
2	1		*FORK STEM	Not Damaged	235.00 FL	*- FL
3	1		*FORK ASSY	Dented	1,185.00 FL	*924.00 FL
4	1		*FORK BEARING	Necessary	175.00 FL	*45.00 FL
5	1		*HEADLAMP BRACKET	Bent	155.00 FL	*105.00 FL
6	2		*HEADLAMP COWLING L+R	Broken	250.00 FL	*250.00 FL
7	1		*FRONT FAIRING	Cut	185.00 FL	*185.00 FL
8	1		*CLUTCH LEVER	Not Damaged	75.00 FL	*- FL
9	1		*HANDLE BAR	Bent	275.00 FL	*200.00 FL
10	1		*HANDLE BAR GRIP	Cut	75.00 FL	*30.00 FL
11	1		*SET HANDLE BAR BALANCER	Cut	75.00 FL	*50.00 FL
12	1		*HANDLEBAR STEM	Not Damaged	315.00 FL	*- FL
13	1		*FRONT RIGHT FAIRING	Cut	285.00 FL	*255.00 FL
14	1		*FUEL TANK	Dented	875.00 FL	*530.00 FL
15	1		*BRAKE STAND	Not Damaged	85.00 FL	*- FL
16	1		*RIDER STAND	Cut	85.00 FL	*85.00 FL
17	1		*PILLION STAND	Cut	85.00 FL	*85.00 FL
18	1		*CLUTCH COVER	Cut	165.00 FL	*165.00 FL
19	2		*REAR FAIRING R+L	Not Damaged	230.00 FL	*- FL
20	1		*WHEEL SPROCKET	Not Damaged	687.00 FL	*- FL
21	1		*CHAIN COVER	Not Damaged	145.00 FL	*- FL
22	1		*EXHAUST GUARD	Cut	289.00 FL	*160.00 FL
23	1		*EXHAUST ASSY	Dented	1,534.50 FL	*750.00 FL
24	1		*UNDER COVER	Cut	213.70 FL	*213.70 FL
25	1		*OIL FILTER COVER	Dented	127.60 FL	*127.60 FL
26	1		*REAR FAIRING R+H H	Repeated	163.80 FL	*- FL
27	1		*FRONT RIGHT FAIRING INNE	Not Damaged	235.40 FL	*- FL
28	1		*FRONT RIGHT FAIRING	Repeated	285.00 FL	*- FL
29	1		*BRAKE DISC	Bent	185.00 FS	*155.00 FS
30	1		*WHEEL RIMS (FRONT & BACK) (2 Pcs)	Frnt Bent	620.00 FS	*300.00 FS
31	2		*BRAKE FLUID (FRONT & BACK)	Necessary	150.00 FS	*50.00 FS
32	1		*SET SIDE MIRROR	Cut	134.20 FS	*78.00 FS
33	2		*SET SIGNAL LIGHT (FRONT & BACK)	Cut	172.80 FS	*150.00 FS
34	1		*LICENSE PLATE	Bent	30.00 FS	*20.00 FS
35	1		*ENGINE COVER	Not Damaged	186.40 FS	*- FS
36	1		*WINDSHIELD	Not Damaged	164.50 FS	*- FS
37	1		*BRAKE LEVER	Cut	75.00 FL	*40.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	10,473.90	5,133.30
- List Item Discount on L Items 10.00/10.00% (\$\$)	883.10	438.03
Total Parts (\$\$)	9,590.80	4,695.27

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	HELMET (ARAI)	New	285.00	0.00
2	WORKMANSHIP	New	800.00	400.00
3	SPRAY PAINTING	New	500.00	300.00
4	ELECTRICAL	New	80.00	30.00
5	CHECK WHEEL ALIGNMENT	New	50.00	30.00
6	CHECK CHASSIS ALIGNMENT	New	80.00	0.00
Gross Labour Cost (\$\$)			1,795.00	760.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >