

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG21005983/ERS3Q2
Date: 23/07/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800026270
Claimant Vehicle No :	PD1710S	Insured Vehicle No :	SLX729M
Date of Loss:	18/05/2021	Nature of Claim:	TP
		Claim No:	1321418088SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	PD1710S	Engine No:	6HK1472658
Make & Model:	ISUZU LV434R, 7.8 D (M)	Chassis No:	JALLV434C87000006
Reg. Date:	16/10/2009 (Man. Year: 2008)	Odometer:	563935 km
Colour:	Multi-colour		
Engine Capacity:	7790 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	12 R22.5	Rear Tyre Size:	12 R22.5
Front Left Side:	Bridgestone 5 mm	Rear Left Side:	Bridgestone 5 mm
Front Right Side:	Bridgestone 5 mm	Rear Right Side:	Bridgestone 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	14,090.00	6,470.00	7,620.00	54.08
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,000.00	4,050.00	950.00	19.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	19,090.00	10,520.00	8,570.00	44.89
Approved Total (Overridden) (S\$)		8,400.00		

(S\$)	19,090.00	8,400.00	10,690.00	56.00
+ GST 7.00/7.00% (S\$)	1,336.30	588.00	748.30	56.00
Nett Amount (S\$)	20,426.30	8,988.00	11,438.30	56.00
+ Loss of Use (5.0 x S\$120.00/day) (S\$)		600.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		9,590.00		

INSPECTION

Date of Assignment: 19/05/2021

Date Inspected: 19/05/2021

Estimated Period of Repair: 5.0 days

Inspected At: Connect3 (woodlands) (HQ)
566 Woodlands Road
Singapore 728697

Adjuster: CHEN TSUE YEE**Manager:** Jaslin Kok Chin Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*RH SIDE COMPARTMENT COVER 2nd LAST	Dented	1,550.00 F	*1,300.00 F
2	1		*RH SIDE COMPARTMENT COVER 2nd LAST FLOORBOARD	Necessary	840.00 F	*500.00 F
3	1		*RH SIDE COMPARTMENT INNER STRUCTURE 2nd LAST	Dented	780.00 F	*500.00 F
4	4		*RH SIDE COMPARTMENT COVER 2nd LAST HINGES	Not Necessary	1,360.00 F	*- F
5	2		*RH SIDE COMPARTMENT GAS SPRING 2nd LAST	Not Necessary	370.00 F	*- F
6	1		*RH SIDE COMPARTMENT RUBBER MOULDING 2nd LAST	Necessary	450.00 F	*300.00 F
7	1		*RH SIDE COMPARTMENT OUTER LOCK 2nd LAST	Cut	170.00 F	*120.00 F
8	1		*RH SIDE COMPARTMENT OUTER LAMP 2nd LAST	Cut	435.00 F	*250.00 F
9	1		*REAR RH LAMP PC COMPARTMENT COVER	Dented	1,950.00 F	*1,500.00 F
10	1		*REAR RH LAMP PC COMPARTMENT COVER OUTER LOCK	Cut	175.00 F	*120.00 F
11	2		*REAR RH LAST PC COMPARTMENT COVER REFLECTOR LAMP ASSY	Cut	370.00 F	*300.00 F
12	4		*RH SIDE COMPARTMENT COVER LAST HINGES	Not Necessary	1,360.00 F	*- F
13	1		*RH SIDE COMPARTMENT FLOORBOARD	Not Necessary	620.00 F	*- F
14	1		*REAR RH LAST PC COMPARTMENT GRILLE	Not Necessary	550.00 F	*- F
15	2		*REAR RH LAST PC COMPARTMENT GAS SPRING	Not Necessary	370.00 F	*- F
16	1		*REAR RH LAST PC COMPARTMENT RUBBER MOULDING	Necessary	450.00 F	*300.00 F
17	1		*REAR RH LAST PC COMPARTMENT INNER STRUCTURE	Dented	1,530.00 F	*1,200.00 F
18	4		*SEALANT	Necessary	160.00 F	*80.00 F
19	1		*FLOORMAT PVC FOR COMPARTMENT FLOORBOARD	Not Necessary	600.00 F	*- F
					Total Parts (\$\$)	14,090.00
						6,470.00

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	CHECK WIRING	New	100.00	50.00
2	LABOUR CHARGES	New	1,500.00	1,200.00
3	SPRAY PAINTING WITH LINING DESIGN	New	3,400.00	2,800.00
Gross Labour Cost (\$\$)			5,000.00	4,050.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >