

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CS/AIG21005989/EVCE2

Date: 01/07/2021

REFERENCE

Insured/Claimant: NG CHIN HUNG Policy No: 1800026270
Date of Loss: 18/05/2021 Nature of Claim: OD Claim No: 1321418088SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLX729M**
Make & Model: MITSUBISHI OUTLANDER, 2.0 (A) Engine No: 4J11XP1912
Reg. Date: 15/03/2018 (Man. Year: 2017) Chassis No: GF7W0401264
Colour: Blue Odometer: 40761 km
Engine Capacity: 1998 cc
Market Value/New Car Price: S\$87,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/55R18 Rear Tyre Size: 225/55R18
Front Left Side: Goodyear 5 mm Rear Left Side: Goodyear 5 mm
Front Right Side: Goodyear 5 mm Rear Right Side: Goodyear 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	14,141.09	11,685.64	2,455.45	17.36
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,370.00	5,175.00	3,195.00	38.17
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	22,511.09	16,860.64	5,650.45	25.10
- Excess (S\$)	600.00	600.00	0.00	0.00
(S\$)	21,911.09	16,260.64	5,650.45	25.79
+ GST 7.00/7.00% (S\$)	1,533.78	1,138.24	395.54	25.79
Nett Amount (S\$)	23,444.87	17,398.88	6,045.99	25.79

INSPECTION

Date of Assignment: 20/05/2021
Date Inspected: 19/05/2021 Inspected At: Cycle & Carriage Automotive Pte Ltd (Pandan Gardens)
209 Pandan Gardens
Singapore 609339
Estimated Period of Repair: 12.0 days

Adjuster: CHEN TSUE YEE

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*INSULATOR,FR FENDER,LH	Not Necessary	65.00 FL	*- FL
2	1		*FENDER,FR LH	Dented	622.00 FL	*622.00 FL
3	1		*SHIELD,FR WHEELHOUSE,LH	Torn	164.00 FL	*164.00 FL
4	1		*MOULDING,FR BUMPER,LH	Necessary	116.00 FL	*116.00 FL
5	1		*MOULDING,FR BUMPER,RH	Necessary	116.00 FL	*116.00 FL
6	1		*MOULDING,FR WHEEL ARCH,LH	Necessary	199.00 FL	*199.00 FL
7	1		*HOOD	Dented	980.00 FL	*980.00 FL
8	1		*HINGE,HOOD,LH	Bent	68.00 FL	*68.00 FL
9	1		*HINGE,HOOD,RH	Bent	68.00 FL	*68.00 FL
10	1		*LATCH,HOOD	Not Necessary	76.00 FL	*- FL
11	1		*GRILLE ASSY,RADIATOR	Broken	572.00 FL	*572.00 FL
12	1		*COVER,HEADLAMP SUPT PANEL	Not Necessary	50.00 FL	*- FL
13	12		*CLIP,RR BUMPER	Necessary	36.00 FL	*36.00 FL
14	1		*COVER,FR BUMPER	Not Necessary	25.00 FL	*- FL
15	1		*BRACKET,RADIATOR GRILLE,LH	Not Necessary	13.00 FL	*- FL
16	1		*FACE,FR BUMPER	Broken	863.00 FL	*863.00 FL
17	1		*BRACKET,FR BUMPER SIDE,LH	Not Necessary	18.00 FL	*- FL
18	1		*EXTENSION,FR BUMPER	Not Necessary	856.00 FL	*- FL
19	1		*GARNISH,FR BUMPER,LH	Cut	150.00 FL	*75.00 FL
20	1		*GARNISH,FR BUMPER,RH	Cut	150.00 FL	*75.00 FL
21	9		*CLIP,ENG ROOM COVER	Necessary	18.00 FL	*18.00 FL
22	1		*GARNISH,FR BUMPER SIDE (LH)	Broken	224.00 FL	*112.00 FL
23	1		*GARNISH,FR BUMPER SIDE (RH)	Not Necessary	224.00 FL	*- FL
24	1		*GARNISH,FR BUMPER SIDE (LH)	Broken	440.00 FL	*220.00 FL
25	1		*GARNISH,FR BUMPER SIDE (RH)	Not Necessary	440.00 FL	*- FL
26	1		*GARNISH,FR BUMPER SIDE (LH)	Broken	96.00 FL	*48.00 FL
27	1		*GARNISH,FR BUMPER SIDE	Not Necessary	96.00 FL	*- FL
28	1		*COVER,FR BUMPER	Broken	295.00 FL	*295.00 FL
29	2		*BRKT,FR BUMPER SIDE,LWR LH	Not Necessary	12.00 FL	*- FL
30	1		*REINFORCEMENT,FR BUMPER	Bent	505.00 FL	*505.00 FL
31	1		*REINFORCEMENT,FR BUMPER	Bent	135.00 FL	*135.00 FL
32	1		*REINF,FR BUMPER SIDE,LH	Bent	60.00 FL	*60.00 FL
33	1		*BAR,FR BUMPER GUARD	Not Necessary	130.00 FL	*- FL
34	1		*HINGE HOOD,RH	Not Necessary	68.00 FL	*- FL
35	2		*CLIP,ENG ROOM COVER	Not Necessary	4.00 FL	*- FL
36	1		*HEADLAMP ASSY,LH	Broken	2,135.00 FL	*2,135.00 FL
37	1		*LAMP ASSY,FOG,FR LH	Broken	350.00 FL	*350.00 FL
38	1		*GARNISH,FR DECK	Broken	173.00 FL	*173.00 FL
39	1		*COVER,FR DECK,LH	Not Necessary	19.00 FL	*- FL
40	1		*COVER,FR DECK,RH	Not Necessary	19.00 FL	*- FL
41	1		*PNL,HEADLAMP SUPT,UPR LH	Bent	58.00 FL	*58.00 FL
42	1		*PANEL,HEADLAMP SUPPORT,UPR	Not Necessary	230.00 FL	*- FL
43	1		*PANEL,HEADLAMP SUPPORT,LWR	Not Necessary	107.00 FL	*- FL
44	1		*TANK ASSY,RADIATOR COND	Not Necessary	103.00 FL	*- FL
45	1		*LLC 4L	Necessary	26.00 FL	*26.00 FL
46	1		*AERO KIT-OUTLANDER	Broken	1,554.00 FS	*1,554.00 FS
47	1		*SUNDRIES	Necessary	50.00 FS	*20.00 FS
48	1		*FRT NUMBER PLATE WITH FRAME	Not Necessary	50.00 FS	*- FS
49	1		*ENGINE HOOD EMBLEM (Supplementary)	Necessary	80.00 FL	*80.00 FL
50	1		*SHIELD,FR WHEELHOUSE,RH (Supplementary)	Necessary	164.00 FL	*164.00 FL

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
51	1		*MOULDING, FR WHEEL ARCH,RH (Supplementary)	Necessary	199.00 FL	*199.00 FL
52	1		*EXTENSION,FR BUMPER (Supplementary)	Broken	428.00 FL	*428.00 FL
53	1		*PNL,HEADLAMP SUPT,UPR RH (Supplementary)	Bent	58.00 FL	*58.00 FL
54	1		*PANEL,HEADLAMP SUPPORT,LH (Supplementary)	Bent	58.00 FL	*58.00 FL
55	1		*PANEL HEADLAMP SUPPORT,RH (Supplementary)	Bent	58.00 FL	*58.00 FL
56	1		*PLATE,FR SIDEMEMBER,RH (Supplementary)	Bent	60.00 FL	*60.00 FL
57	1		*PLATE,FR SIDEMEMBER,LH (Supplementary)	Bent	60.00 FL	*60.00 FL
58	1		*REINF, FR BUMPER SIDE,RH (Supplementary)	Bent	69.00 FL	*69.00 FL
59	1		*HEADLAMP ASSY, RH (Supplementary)	Broken	2,135.00 FL	*2,135.00 FL
60	1		*COVER,ENG ROOM UNDER,FR (Supplementary)	Broken	349.00 FL	*349.00 FL
61	1		*COVER,ENG ROOM UNDER,FR (Supplementary)	Missing	150.00 FL	*150.00 FL
62	1		*HARNES,FOG LAMP (Supplementary)	Torn	130.00 FL	*130.00 FL
63	16		*CLIPS (Supplementary)	Necessary	48.00 FL	*48.00 FL
64	10		*CLIPS (Supplementary)	Necessary	20.00 FL	*20.00 FL
65	1		*DRIVER A,A/T O/PMP & MOTOR (Supplementary)	Broken	829.00 FL	*829.00 FL
66	1		*O-RING,A/T OIL SUMP (Supplementary)	Necessary	3.00 FL	*3.00 FL
67	10		*RIVET,FR BUMPER (Supplementary)	Necessary	50.00 FL	*50.00 FL
68	1		*COVER,ENG ROOM SIDE,LH (Supplementary)	Cut	92.00 FL	*92.00 FL
69	1		*O-RING,A/T OIL SUMP (Supplementary)	Necessary	3.00 FL	*3.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	17,871.00	14,706.00
- List Item Discount on L Items 23.00/23.00% (\$\$)	3,729.91	3,020.36
Total Parts (\$\$)	14,141.09	11,685.64

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REPLACE FRT BUMPER,BONNET,FRT LH FENDER & BODY KIT,REPAIR FRT RH FENDER,FRT RH DOOR & AFFECTED AREAS	New	3,150.00	1,125.00
2	SPRAY PAINT WORK ON FRT BUMPER,BONNET,LHF FENDER,RHF FENDER,RHF DOOR,LHF DOOR,FRT SUPPORT,BODYKIT & AFFECTED AREAS	New	3,150.00	2,100.00
3	REMOVE & INSTALL RADIATOR & CONDENSER TO FACILITATE REPAIR	New	100.00	100.00
4	TO TOP UP A/C GAS & CHECK A/C SYSTEM CONDITION	New	80.00	80.00
5	TO APPLY BODY SEALANT ON AFFECTED AREAS	New	80.00	40.00
6	TO PERFORM RUST PREVENTION ON AFFECTED AREAS	New	120.00	40.00
7	CHECK ON WIRING & CHASSIS ELECTRICAL SYSTEM	New	30.00	30.00
8	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST	New	120.00	120.00
9	TO RE-APPLY ZERTONA ON AFFECTED AREAS	New	240.00	240.00
10	REPLACE FRONT SUPPORT PANEL (Supplementary)	New	450.00	450.00
11	RESPRAY FRONT SUPPORT PANEL (Supplementary)	New	350.00	350.00
12	FLOOR PULLING & RE-ADJUST BOTH FRONT CHASSIS (Supplementary)	New	500.00	500.00
			Gross Labour Cost (S\$)	8,370.00
				5,175.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >