

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG21005990/APS3Q2
Date: 12/07/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070107237
Claimant Vehicle No :	SLE7546C	Insured Vehicle No :	GBK4047H
Date of Loss:	12/05/2021	Nature of Claim:	TP
		Claim No:	9535621685SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLE7546C	Engine No:	CZC550499
Make & Model:	AUDI A3, 1.4 TFSI S-TRONIC (A)	Chassis No:	WAUZZZ8V9G1097184
Reg. Date:	29/07/2016 (Man. Year: 2016)	Odometer:	61479 km
Colour:	Grey		
Engine Capacity:	1395 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	225/40 R18	Rear Tyre Size:	225/40 R18
Front Left Side:	Goodyear 6 mm	Rear Left Side:	Goodyear 6 mm
Front Right Side:	Goodyear 6 mm	Rear Right Side:	Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,670.90	3,037.50	2,633.40	46.44
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,000.00	1,000.00	2,000.00	66.67
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,670.90	4,037.50	4,633.40	53.44
Approved Total (Overridden) (S\$)		3,200.00		

(S\$)	8,670.90	3,200.00	5,470.90	63.09
+ GST 7.00/7.00% (S\$)	606.96	224.00	382.96	63.09
Nett Amount (S\$)	9,277.86	3,424.00	5,853.86	63.09
+ Loss of Use (4.0 x S\$60.00/day) (S\$)		240.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		3,666.00		

INSPECTION

Date of Assignment: 17/05/2021

Date Inspected: 17/05/2021

Inspected At:

Lee Sheng Auto Pte Ltd (HQ)
 1 Kaki Bukit Avenue 6, #01-58/60 AutoBay@Kaki Bukit
 Singapore 417883

Estimated Period of Repair: 4.0 days

Adjuster: ADRIAN LING**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	1,650.00 FL	*1,650.00 FL
2	1		*FRONT BUMPER REINFORCEMENT	Dented	680.00 FL	*680.00 FL
3	2		*FRONT BUMPER RETAINER	Not Necessary	136.00 FL	*- FL
4	1		*GRILLE	Cracked	850.00 FL	*850.00 FL
5	1		*GRILLE EMBLEM	Necessary	195.00 FL	*195.00 FL
6	1		*SUPPORT ASSY ,HOOD	Not Necessary	680.00 FL	*- FL
7	1		*REAR BUMPER	Repair	1,550.00 FL	*- FL
8	1		*REAR END PANEL	Repair	560.00 FL	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$)	6,301.00	3,375.00
- List Item Discount on L Items 10.00/10.00% (\$)	630.10	337.50
Total Parts (\$)	5,670.90	3,037.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	KNOCKING ,CUTTING ,JACKING WELDING ETC	New	1,500.00	500.00
2	SPRAY PAINTING ON AFFECTED AREA	New	1,500.00	500.00
Gross Labour Cost (S\$)			3,000.00	1,000.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >