



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. YN 8075L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	REAR FREEZER BOX STEEL PANEL	TO REPAIR SEE LABOUR	980.00	-
1	REAR FREEZER BOX HANDLE BAR N/S	BENT	250.00	250.00
1	FRONT WINDSCREEN GLASS	CRACKED	870.40	870.40
1	FRONT WINDSCREEN GLASS RUBBER	NECESSARY	506.50	506.50
1	FRONT WIPER PANEL GARNISH	DISTORTED / CRACKED	395.30	395.30
1	FRONT WIPER ARM N/S	BENT / DAMAGED	215.40	215.40
1	FRONT WIPER BLADE N/S	NOT NECESSARY	66.50	-
1	FRONT WIPER MOTOR	DAMAGED	680.50	680.50
1	FRONT PANEL	TO REPAIR SEE LABOUR	2,494.90	-
1	FRONT PANEL "FUSO" EMBLEM	NOT NECESSARY	92.50	-
1	FRONT PANEL "CORPORATE" ADVERTISEMENT & ARTWORK	NOT NECESSARY	150.00	-
1	FRONT GRILLE	NOT NECESSARY	1,123.40	-
1	FRONT DASHBOARD	DEFORMED / TWISTED	945.90	945.90
1	FRONT DASHBOARD FRAME	NOT NECESSARY	625.40	-
1	FRONT BUMPER (DENTED)	NOT CONSISTENT WITH THE IMPACT	991.80	-
1	FRONT WIPER INNER PANEL	DENTED / TWISTED	845.11	845.11
1	FRONT HEATER UNIT ASSY	CRACKED	2,525.52	2,525.52
1	FRONT AIRCON BLOWER ASSY	SERVICEABLE	914.42	-
	LESS 25% DISCOUNT		-	-1,808.66
			14,673.55	5,425.97
	<b><u>LABOUR</u></b>			
	TO CHECK ALL WIRING & ELECTRICAL COMPONENT FOR PROPER FUNCTION.		50.00	30.00
	REMOVE & REINSTALL WINDSCREEN GLASS TO FACILITATE REPAIRS & PERFORM WATER.		120.00	100.00
	REMOVE & REINSTALL DASHBOARD,METER INSTRUMENTS,DISCONNECT WIRING & ETCS.		280.00	200.00

Report Ref No. CS/SMO21005994/Uqf3n2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REMOVE & REFIX AIR CON,RE-FILL AIR CON GAS & TEST FOR LEAKAGES.		120.00	100.00
	LABOR FOR PANEL BEATING,CUT,WELD,STRAIGHTEN & REPLACING PARTS ETC.S.INCLUSIVE OF THE REPAIR OF REAR FREEZER BOX STEEL PANEL AND FRONT PANEL.		1,200.00	1,000.00
	TO PUTTY & SPRAY PAINTING & INCLUDING TOUCH UP PAINT ON ACCIDENT AFFECTED AREA.		1,000.00	600.00
	TO APPLY RUST PROOFING,RESEAL TUFF-COATING TREATMENT ON ACCIDENT AREA.		100.00	50.00
			2,870.00	2,080.00
<b>GRAND TOTAL</b>			<b>17,543.55</b>	<b>7,505.97</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>6,000.00</b>

Report Ref No. CS/SMO21005994/Uqf3n2

CHUA KANG SENG

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.