

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
	SOMPO INSURAN	CE SINGAPORE PL	Ref:	CS3/SMO21002863/GKtf3e2-	
	50 RAFFLES PLAC SINGAPORE LAND	CE #03-03 O TOWERSINGAPORE 048623	Date:	1 02/06/2021	
			Code	SMO	
1.	Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	YN 5910X	Veh. Inspected	SJD 7614T	
	Policy No.	D21MTPCVE000272	Coverage (\$)	0.00	
	Claim No.	CMTD2100633/AGC	Excess (\$)	0.00	
	Assign From	AGNES CHAN	Assign Date	18/05/2021	
2. Vehicle Particulars & Condition					
	Make & Model	HONDA CROSSROAD 1.8	c.c	1799	
	Engine No.	HIDDEN	Year of Reg.	2008	
	Chassis No.	RT11005042	Colour	BLACK	
	Odometer	224300 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
	General	GOOD			
3.	3. Conditions of Tyres				
		Size	Make	Balance	
	R/H Front Tyre	215/65 R16	YOKOHAMA	6 mm	
	L/H Front Tyre	215/65 R16	YOKOHAMA	6 mm	
	R/H Rear Tyre	215/65 R16	YOKOHAMA	6 mm	
	L/H Rear Tyre	215/65 R16	YOKOHAMA	6 mm	
4.	Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY. THE UNDERCARRIAGE AFFECTED DUE TO COLLISION.				
	DAMAGES SEE DETAILS.				
5.		General Information			
	Accident Date	25/02/2021	Inspection Date	03/03/2021	
	Survey held at	SZE KANG AUTOMOBILE SPRAYING SERVICES			
		BLK 10 ANG MO KIO INDUSTRIAL PARK 2A #03-17 AMK AUTO POINT . SINGAPORE 568047			
5a.	Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR: 5 Working Days				
	ESTIMATED NORMAL FERIOD FOR REPAIR. 3 WORKING Days				