

VEHICLE SURVEY REPORTS

Lee Eng Chye Vincent
C/O See Kang Automobile Spraying Services
10 Ang Mo Kio Ind Park 2A
Ang Mo Kio Auto Point #03-17/09
Singapore 568047

1 Reference
Job Reference No : 21/002241
Claim No : -
Claim Type : Third Party
Accident Date : 25/02/2021
Survey Date : 01/03/2021
Survey Report Date : 12/03/2021

2 Particulars Of Vehicle
Vehicle Registration No : SJD7614T
Make & Model : Honda CrossRoad 1.8 A
Vehicle Registration Date : 01/04/2008
Chassis No : RT11006042
Engine No : Blocked
Colour : Black

3 Condition Of Vehicle And Tyres

<u>Mileage (KM)</u>	<u>Brakes</u>	<u>Steering</u>	<u>Modification</u>
224300	Serviceable	Serviceable	None
<u>Tyres</u>	<u>Make</u>	<u>Size</u>	<u>Balance (MM)</u>
Front RHS	Yokohama	215/65R16	5
Front LHS	Yokohama	215/65R16	5
Rear RHS	Yokohama	215/65R16	6
Rear LHS	Yokohama	215/65R16	6

4 Description Of Damages
The vehicle sustained damages at left hand portion.
(For information of damages please refer to Parts/Labour/Photographs attached)

5 Instruction
This survey was conducted entirely on a "WITHOUT PREJUDICE" basis, and we have not authorised any repair.

AUTO PERFORMANCE APPRAISAL

Annex A

Vehicle Assessment Reports

Ref No : 21/002241

Damage And Repair Cost Adjustment

<u>S/No</u>	<u>Qty</u>	<u>Parts Description</u>	<u>Comments/condition</u>	<u>Workshop Estimate (\$)</u>	<u>Our Assessment (\$)</u>
			<u>List Items</u>		
1	1	Front LH side mirror assy ✓	Broken/cracked	652.80	652.80 529.3
2	1	Front LH door ✓	Distorted	1,209.70	1,209.70 935
3	1	Front LH door lower protector ✓	Broken/deformed	231.00	231.00 ✓
4	1	Front LH door outer handle ✓	Bent/dented	126.00	126.00 ✓
5	1	Front LH door glass ✓	Shattered	528.60	528.60 ✓
6	1	Front LH door glass outer moulding ✓	Deformed/bent	113.40	113.40 ✓
7	1	Front LH door glass regulator ✓	Bent/jammed	163.50	163.50 ✓
8	1	Front LH door glass regulator motor ✓	Malfunction	321.60	321.60 268
9	1	Front LH door glass channel ✓	Bent	114.60	114.60 ✓
10	1	Front LH door inner lock ✓	Bent/jammed	362.50	362.50 ✓
11	1	Front LH door weatherstrip ✓	Necessary	150.00	150.00 ✓
12	1	Front LH door inner trim board ✓	Deformed/broken	385.30	385.30 ✓
13	1 set	Front LH door inner trim board clips ✓	Necessary	60.00	60.00 ✓
14	2	Front LH door hinge (Top & bottom) ✓	Bent	164.00	164.00 123.7
15	1	Front LH door pillar	To repair	498.70	-
16	1	LH rocker panel	To repair	428.60	-
17	1	LH rocker panel outer cover/skirting ✓	Broken	386.70	386.70 ✓
18	1 set	LH rocker panel outer cover/skirting clips ✓	Broken/necessary	60.00	60.00 ✓
19	1	Rear LH door ✓	Buckled	1,107.60	1,107.60 ✓
20	1	Rear LH door lower protector ✓	Deformed	191.80	191.80 ✓
21	1	Rear LH door weatherstrip ✓	Necessary	145.00	145.00 ✓
22	1	Rear LH door inner trim board	Serviceable/reuse	321.40	-
23	1 set	Rear LH door inner trim board clips ✓	Necessary	60.00	60.00 ✓
24	2	Rear LH door hinge (Top & bottom) ✓	1 pcs bottom bent	134.00	67.00 ✓
Less discount 20%				7,916.80	6,601.10 6769
				1,583.36	1,320.22
Total :				6,333.44	5,280.88
			<u>Special Nett Items</u>		4935.2
25	1 set	Front/Rear LH door sound proofing insulation ✓	Bent/dented	300.00	300.00 ✓
Total :				300.00	300.00
Total Spare Parts :				6,633.44	5,580.88

AUTO PERFORMANCE APPRAISAL

Vehicle Assessment Reports

Annex B

Ref No : 21/002241

Damage And Repair Cost Adjustment

<u>Items</u>	<u>Job Description</u>	<u>Workshop Estimate (\$)</u>	<u>Adjusted Costs (\$)</u>
1	To remove, jack out, straighten, panel beating, align and renew replaced parts.	1,200.00	800.00 600
2	To putty and respray painting on affected areas.	1,500.00	1,200.00 1000
3	To check & repair wirings.	50.00	30.00 ✓
4	To remove, refix both LH door fittings to facilitate repair.	150.00	120.00 ✓
5	To conduct computerise wheel alignment test.	80.00	60.00 X
6	To supplied and applied anti rust treatments.	100.00	60.00 ✓
Total Labour :		3,080.00	2,270.00 1810
Total Spare Parts :		6,633.44	5,580.88
Total Labour :		3,080.00	2,270.00
Total Repair Costs :		9,713.44	7,850.88

Assessor's Recommendation

Repairer Estimate : 9,713.44
Our Adjustment : 7,850.88

Remarks

The repairer has agreed to undertake the repair on a lump sum basis of \$6,250.00, with a repair period of 6 working days.

Surveyed By:



Lek Boon Hwee
Automobile Appraiser

7045.2
20% = 5600
6 Days.