

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG21006000/ETCE2**Date:** 05/07/2021**REFERENCE**

Insured/Claimant:	TAN CHYE HUAT PETER	Policy No:	1900015551-01	
Date of Loss:	18/05/2021	Nature of Claim:	OD	Claim No: 7069851900SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SGH7373C		
Make & Model:	MITSUBISHI ATTRAGE, 1.2 CVT (A)	Engine No:	3A92UHN9315
Reg. Date:	22/02/2019 (Man. Year: 2018)	Chassis No:	MMBSTA13AKH001237
Colour:	Grey	Odometer:	30008 km
Engine Capacity:	1193 cc		
Market Value/New Car Price:	S\$59,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/55 R15	Rear Tyre Size:	185/55 R15
Front Left Side:	Bridgestone 5 mm	Rear Left Side:	Bridgestone 5 mm
Front Right Side:	Bridgestone 5 mm	Rear Right Side:	Bridgestone 5 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,199.27	6,471.39	1,727.88	21.07
Miscellaneous Items	0.00	0.00	0.00	
Labour	12,585.00	9,165.00	3,420.00	27.18
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	20,784.27	15,636.39	5,147.88	24.77
+ GST 7.00/7.00% (S\$)	1,454.90	1,094.55	360.35	24.77
Nett Amount (S\$)	22,239.17	16,730.94	5,508.23	24.77

INSPECTION

Date of Assignment: 20/05/2021

Date Inspected: 19/05/2021 Inspected At:

Estimated Period of Repair: 20.0 days

Cycle & Carriage Automotive Pte Ltd (Pandan Gardens)
209 Pandan Gardens
Singapore 609339

Adjuster: CHEN TSUE YEE**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	30.00 FS	*30.00 FS
2	1		*FACE, RR BUMPER	Broken	751.00 FL	*751.00 FL
3	1		*BRACKET, RR BUMPER, LH	Broken	28.00 FL	*28.00 FL
4	1		*BRACKET, RR BUMPER, RH	Not Necessary	28.00 FL	*- FL
5	4		*CLIP, RR BUMPER	Necessary	16.00 FL	*16.00 FL
6	1		*PANEL, RR END	Dented	427.00 FL	*427.00 FL
7	1		*MUDGUARD, RR LH	Missing	41.00 FL	*41.00 FL
8	1		*MUDGUARD, RR RH	Not Necessary	41.00 FL	*- FL
9	1		*SHIELD, RR WHEELHOUSE, LH	Crushed	40.00 FL	*40.00 FL
10	1		*SHIELD, RR WHEELHOUSE, RH	Not Necessary	40.00 FL	*- FL
11	1		*DUCT, RR VENTILATOR	Not Necessary	30.00 FL	*- FL
12	1		*COVER, RR VENTILATOR	Not Necessary	40.00 FL	*- FL
13	1		*BUZZER, KEYLESS OPERATIO, RR	Broken	91.00 FL	*91.00 FL
14	1		*ANT, KEYLESS OPERATION, RR	Not Necessary	96.00 FL	*- FL
15	1		*TRIM, RR END	Not Necessary	66.00 FL	*- FL
16	1		*TRIM, TRUNK ROOM SIDE, LH	Not Necessary	158.00 FL	*- FL
17	1		*PANEL, QTR, OTR LH	Dented	759.00 FL	*759.00 FL
18	1		*PANEL, QTR, OTR RH	Dented	767.00 FL	*767.00 FL
19	1		*PANEL, RR COMB LAMP HSG, LH	Bent	60.00 FL	*60.00 FL
20	1		*PANEL, RR COMB LAMP HSG, RH	Not Necessary	60.00 FL	*- FL
21	1		*EXTN, QTR PANEL, UPR OTR LH	Bent	118.00 FL	*118.00 FL
22	1		*EXTN, QTR PANEL, UPR OTR RH	Not Necessary	118.00 FL	*- FL
23	1		*GLASS, RR WINDOW (NPA)	Not Necessary	0.00 FL	*- FL
24	2		*STOPPER, WINDSHIELD GLASS	Necessary	6.00 FL	*6.00 FL
25	3		*SPACER, RR WINDOW	Necessary	27.00 FL	*27.00 FL
26	1		*PANEL, TRUNK LID	Not Necessary	795.00 FL	*- FL
27	1		*WEATHERSTRIP, TRUNK LID	Crushed	157.00 FL	*157.00 FL
28	1		*HINGE, TRUNK LID, LH	Not Necessary	203.00 FL	*- FL
29	1		*HINGE, TRUNK LID, RH	Not Necessary	203.00 FL	*- FL
30	1		*LATCH, TRUNK LID	Not Necessary	218.00 FL	*- FL
31	1		*MARK, THREE-DIA	Necessary	70.00 FL	*70.00 FL
32	1		*MARK, ATTRAGE	Necessary	21.00 FL	*21.00 FL
33	1		*LAMP ASSY, COMB, RR LH	Broken	337.00 FL	*337.00 FL
34	1		*LAMP ASSY, COMB, RR RH	Broken	337.00 FL	*337.00 FL
35	1		*REFLECTOR LH	Not Necessary	23.00 FL	*- FL
36	1		*REFLECTOR RH	Not Necessary	23.00 FL	*- FL
37	1		*PANEL ASSY, RR DOOR, RH	Dented	831.00 FL	*831.00 FL
38	1		*MLDG, R/DR WDO BELT LINE, RH	Not Necessary	66.00 FL	*- FL
39	1		*TAPE, RR DOOR SASH, RH	Necessary	29.00 FL	*29.00 FL
40	1		*UNPAINTED BODYKITS	Broken	1,643.00 FS	*1,643.00 FS
41	1		*DECAL, MIVEC	Not Necessary	36.00 FL	*- FL
42	1		*FLOOR, RR (Supplementary)	Dented	956.00 FL	*956.00 FL
43	1		*GROMMET, TALL LAMP(X4) (Supplementary)	Necessary	12.00 FL	*12.00 FL
44	1		*GROMMET, RR END TRIM (X4) (Supplementary)	Necessary	12.00 FL	*12.00 FL
45	1		*SILENCER, FLOOR (Supplementary)	Necessary	14.00 FL	*14.00 FL
46	1		*EMBLEM MIVEC TECHNOLOGY (Supplementary)	Necessary	30.00 FS	*30.00 FS
47	1		*SET REVERSE PARKING SENSOR (Supplementary)	Broken	220.00 FS	*220.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	10,074.00	7,830.00
- List Item Discount on L Items 23.00/23.00% (\$\$)	1,874.73	1,358.61

Report was unsubmitted during this print-out.

7/5/2021				Adjuster Report		
No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
Total Parts (S\$)					8,199.27	6,471.39
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	RENEW LHR FENDER, RHR FENDER, RR BUMPER, RR BUMPER BODY KIT, BOOTLID & RHR DOOR. REPAIR RR FLR PNL, LHR WHEELHOUSE, RHR WHEELHOUSE & RHF DOOR	New	5,400.00	3,150.00
2	RESPRAY RHF DOOR, RHR DOOR, RHR FENDER, RHR WHEELHOUSE, BOOTLID, RR FLR PNL, RR END PNL, RR BUMPER, RR BUMPER BODY KIT, LHR FENDER & LHR WHEELHOUSE	New	3,850.00	3,150.00
3	REMOVE & REFIT RHR DOOR COMPONENT	New	120.00	120.00
4	REMOVE & REFIT BOOTLID COMPONENT	New	120.00	0.00
5	REMOVE & REFIT FUEL TANK ASSY	New	450.00	450.00
6	REMOVE & REFIT RR FLR BOARD, TRIM, CARPET & SEAT	New	120.00	120.00
7	CHECK WIRING ELECTRICAL SYSTEM	New	30.00	30.00
8	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST	New	120.00	120.00
9	REMOVE & REFIT RR WINDSCREEN GLASS	New	240.00	240.00
10	SUPPLY REAR WINDSCREEN SEALANT	New	80.00	80.00
11	SUPPLY RR NUMBER PLATE WITH CASING	New	50.00	0.00
12	REMOVE & REFIT REVERSE SENSOR	New	60.00	60.00
13	SUPPLY REVERSE SENSOR	New	220.00	0.00
14	APPLY ANTI CORROSION ON AFFECTED AREAS	New	80.00	40.00
15	SUPPLY BODY PNL SEALANT	New	80.00	80.00
16	SUPPLY C&C BADGE	New	40.00	0.00
17	REPLACE REAR FLOOR PANEL, REAR SIDE MEMBER EXTENSION LH, FLOOR PULLING REALIGN LH REAR CHASSIS (Supplementary)	New	1,350.00	1,350.00
18	RESPRAY ON LH CHASSIS FRAME (Supplementary)	New	175.00	175.00
Gross Labour Cost (\$)			12,585.00	9,165.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >