



CYCLE &amp; CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED  
PANDAN GARDENS CUSTOMER SERVICE CENTRE  
209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



Co Reg No : 197701469G

## ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name /Mr PETER TAN Reg No/Reg Date SGH7373C*GPCP/ 22/02/201 Date In/Mileage / 0 Chassis No MMBSTA13AKH001237 Engine No 3A92UHN9315 Make/Model MIT/19MY ATTRAGE 1.2 CVT Colour/Trim U01 TITANIUM GREY M/ BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
KAX00008	Credit	18/05/2021/ 18:48	BLC	261 / Edwin Caina	11083		
Description of Goods / Services				Qty	Unit Price	Disc%	Amount
E PNT88000 RENEW LHR FENDER, RHR FENDER, RR BUMPER, RR BUMPER BODY KIT, rear end panel BOOTLID & RHR DOOR REPAIR RR FLR PNL, LHR WHEELHOUSE, RHR WHEELHOUSE & RHF DOOR				7 X 450			3150 5400.00
E PNT98000 RESPRAY RHF DOOR, RHR DOOR, RHR FENDER, RHR WHEELHOUSE, BOOTLID, RR FLR PNL, RR END PNL, RR BUMPER, RR BUMPER BODY KIT, LHR FENDER & LHR WHEELHOUSE				9 X 350			3150 3850.00
E PNT88000 REMOVE & REFIT RHR DOOR COMPONENT							120.00
E PNT88000 REMOVE & REFIT BOOTLID COMPONENT							120.00
A 13900099 REMOVE & REFIT FUEL TANK ASSY							450.00
E PNT88000 REMOVE & REFIT RR FLR BOARD, TRIM, CARPET & SEAT							120.00
A 54900099 CHECK WIRING ELECTRICAL SYSTEM							30.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST							120.00
E PNT88000 REMOVE & REFIT RR WINDSCREEN GLASS							240.00
SUNDRY SUPPLY RR WINDSCREEN SEALANT							80.00
SUNDRY SUPPLY RR NUMBER PLATE WITH CASING							50.00
PNT88000 REMOVE & REFIT REVERSE SENSOR							60.00
SUNDRY SUPPLY REVERSE SENSOR							220.00
SUNDRY							40 80.00

Confirm &amp; accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED  
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



Co Reg No : 197701469G

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name /Mr PETER TAN Reg No/Reg Date SGH7373C*GPCP/ 22/02/201 Date In/Mileage / 0 Chassis No MMBSTA13AKH001237 Engine No 3A92UHN9315 Make/Model MIT/19MY ATTRAGE 1.2 CVT Colour/Trim U01 TITANIUM GREY M/ BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
KAX00008	Credit	18/05/2021/ 18:48	BLC	261 / Edwin Caina	11083			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
APPLY ANTI CORROSION ON AFFECTED AREAS								80.00
M SUNDRY								40.00
SUPPLY BODY PNL SEALANT								30.00
M SUNDRY								578.27
SUPPLY C&C BADGE								21.56
M SUNDRY								21.56
Sundries					1.00	751.00	23.00	12.32
M FACE,RR BUMPER					1.00	28.00	23.00	328.79
M BRACKET,RR BUMPER,LH					1.00	28.00	23.00	31.57
M BRACKET,RR BUMPER,RH					1.00	28.00	23.00	31.57
M CLIP,RR BUMPER					4.00	4.00	23.00	30.80
M PANEL,RR END					1.00	427.00	23.00	30.80
M MUD GUARD,RR LH					1.00	41.00	23.00	23.10
M MUD GUARD,RR RH					1.00	41.00	23.00	30.80
M SHIELD,RR WHEELHOUSE,LH					1.00	40.00	23.00	30.80
M SHIELD,RR WHEELHOUSE,RH					1.00	40.00	23.00	30.80
M DUCT,RR VENTILATOR					1.00	30.00	23.00	70.07
M COVER,RR VENTILATOR					1.00	40.00	23.00	73.92
M BUZZER,KEYLESS OPERATIO,RR					1.00	91.00	23.00	50.82
M ANT,KEYLESS OPERATION,RR					1.00	96.00	23.00	121.66
M TRIM,RR END					1.00	66.00	23.00	584.43
M TRIM,TRUNK ROOM SIDE,LH					1.00	158.00	23.00	590.59
M PANEL,QTR,OTR LH					1.00	759.00	23.00	46.20
M PANEL,QTR,OTR RH					1.00	767.00	23.00	46.20
M PANEL,RR COMB LAMP HSG,LH					1.00	60.00	23.00	90.86
M PANEL,RR COMB LAMP HSG,RH					1.00	60.00	23.00	90.86
M EXTN,QTR PANEL,UPR OTR LH					1.00	118.00	23.00	0.00
M EXTN,QTR PANEL,UPR OTR RH					1.00	118.00	23.00	4.62
M GLASS,RR WINDOW					2.00	3.00	23.00	20.79
M STOPPER,WINDSHIELD GLASS					3.00	9.00	23.00	612.15
M SPACER,RR WINDOW					1.00	795.00	23.00	120.89
M PANEL,TRUNK LID					1.00	157.00	23.00	
M WEATHERSTRIP,TRUNK LID								

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED  
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



Co Reg No : 197701469G

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name /Mr PETER TAN Reg No/Reg Date SGH7373C*GPCP/ 22/02/201 Date In/Mileage / 0 Chassis No MMBSTA13AKH001237 Engine No 3A92UHN9315 Make/Model MIT/19MY ATTRAGE 1.2 CVT Colour/Trim U01 TITANIUM GREY M/ BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
KAX00008	Credit	18/05/2021/ 18:48	BLC	261 / Edwin Caina	11083			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
M	HINGE, TRUNK LID, LH	X	NN		1.00	203.00	23.00	156.31
M	HINGE, TRUNK LID, RH	X	NN		1.00	203.00	23.00	156.31
M	LATCH, TRUNK LID	X	NN		1.00	218.00	23.00	167.86
M	MARK, THREE-DIA	X	NN	} NEC	1.00	70.00	23.00	53.90
M	MARK, ATTRAGE	X	NN		1.00	21.00	23.00	16.17
M	LAMP ASSY, COMB, RR LH		BR		1.00	337.00	23.00	259.49
M	LAMP ASSY, COMB, RR RH		BR		1.00	337.00	23.00	259.49
M	REFLECTOR LH	X	NN		1.00	23.00	23.00	17.71
M	REFLECTOR RH	X	NN		1.00	23.00	23.00	17.71
M	PANEL ASSY, RR DOOR, RH		BR		1.00	831.00	23.00	639.87
M	MLDG, R/DR WDO BELT LINE, RH		NN		1.00	66.00	23.00	50.82
M	TAPE, RR DOOR SASH, RH		BR		1.00	29.00	23.00	22.33
M	UNPAINTED BODYKITS		BR		1.00	1643.00	20.00	1314.40
M	DECAL, MIVEC	X	NN		1.00	36.00	23.00	27.72

SURVEYOR NAME : Steve CLKK) 19/5/21, 3:00pm

SURVEYOR SIGNATURE : OO-N-1 AL

DATE : EXCISE - ?

REMARKS : PIP, RY BL SM

20 days

LKK Auto Consultants hence notify the Repairer of the following:

To resurvey before/after spray painting

To resurvey damaged part(s) during resurvey

Parts prices are subject to confirmation

Third party survey is on a "Without Prejudice" basis

No illegal modification(s) is allowed

Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Confirm & accepted by

Authorized signatory and company stamp

7% GST on Net 17,915.29  
Total Payable 19,169.36

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.