

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21006004/EPS3Q2
Date: 02/09/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1700013443
Claimant Vehicle No :	GBH9090P	Insured Vehicle No :	GBG9090U
Date of Loss:	19/05/2021	Nature of Claim:	TP
		Claim No:	2214784030SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBH9090P		
Make & Model:	CITROEN BERLINGO, 1.6 D (M)	Engine No:	10JBHW3019068
Reg. Date:	22/03/2018 (Man. Year: 2017)	Chassis No:	VF77FBHYMHJ754774
Colour:	Silver	Odometer:	85214 km
Engine Capacity:	1560 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Falken 4 mm	Rear Left Side:	Falken 4 mm
Front Right Side:	Falken 4 mm	Rear Right Side:	Falken 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,261.20	9,185.60	4,075.60	30.73
Miscellaneous Items	0.00	0.00	0.00	
Labour	13,803.00	6,213.00	7,590.00	54.99
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	27,064.20	15,398.60	11,665.60	43.10
+ GST 7.00/7.00% (S\$)	1,894.49	1,077.90	816.59	43.10

Nett Amount (S\$)	28,958.69	16,476.50	12,482.19	43.10
+ Loss of Use (12.0 x S\$70.00/day) (S\$)		840.00		
Nett Liability (S\$)		17,316.50		

INSPECTION

Date of Assignment: 20/05/2021

Date Inspected: 20/05/2021

Estimated Period of Repair: 9.0 days

Inspected At:

Cycle & Carriage France Pte Ltd (Pandan Gardens) (HQ)
 209 PANDAN GARDENS
 Singapore 609339

Adjuster: CHEN TSUE YEE**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT NUMBER PLATE WITH CASING }	Cut	50.00 FS	*100.00 FS
2	1		*RR NUMBER PLATE WITH CASING }	Cut	50.00 FS	*- FS
3	1		*BODY PNL SEALANT	Necessary	80.00 FS	*80.00 FS
4	1		*C&C BADGE	Necessary	40.00 FS	*40.00 FS
5	1		*SUNDRIES	Necessary	50.00 FS	*40.00 FS
6	1		*HINGE UPPER LEFT & LOWER RIGHT (NPA)	Not Necessary	0.00 FS	*- FS
7	1		*HINGES UPPER RIGH & LOWER LEFT (NPA)	Not Necessary	0.00 FS	*- FS
8	1		*FRONT BUMPER	Broken	831.20 FS	*831.20 FS
9	1		*BUMPER BRACKET SUP	Not Necessary	401.60 FS	*- FS
10	1		*GUARD GRILLE SUPERIEUR	Broken	239.20 FS	*239.20 FS
11	1		*SET BRACKET	Not Necessary	59.20 FS	*- FS
12	1		*BUMPER BRACKET	Broken	203.20 FS	*203.20 FS
13	1		*BADGE	Cut	206.40 FS	*206.40 FS
14	1		*GUARD GRILLE INFERIEUR	Cut	412.00 FS	*412.00 FS
15	1		*FIXING SPACER	Not fitted	84.80 FS	*- FS
16	1		*GRILLE MOULDING	Broken	134.40 FS	*134.40 FS
17	1		*BUMPER ABSORBER INF	Not Necessary	184.00 FS	*- FS
18	1		*GRILLE MOULDING SUPERIEUR	Not Necessary	134.40 FS	*- FS
19	1		*BUMPER MOULDING	Cut	191.20 FS	*191.20 FS
20	1		*BUPR RUBBR BOOT	Not Necessary	239.20 FS	*- FS
21	1		*FRONT WING LH	Repair	568.80 FS	*- FS
22	1		*MUDGUARD LH	Not Necessary	132.00 FS	*- FS
23	1		*ENGINE BONNET	Not Necessary	801.60 FS	*- FS
24	1		*BONNET HINGE LH	Not Necessary	85.60 FS	*- FS
25	1		*BONNET HINGE RH	Not Necessary	85.60 FS	*- FS
26	1		*BONNET LOCK	Not Necessary	55.20 FS	*- FS
27	1		*HEADLIGHT ASSY LH	Broken	447.20 FS	*447.20 FS
28	1		*FRONT LIGHT DRL	Not Necessary	176.00 FS	*- FS
29	1		*REAR BUMPER	Broken	463.20 FS	*463.20 FS
30	1		*REAR BUMPER LH ENS	Crushed	213.60 FS	*213.60 FS
31	1		*REAR BUMPER RH ENS	Not Necessary	213.60 FS	*- FS
32	1		*RECESS DOOR	Cut	54.40 FS	*54.40 FS
33	1		*SET BRACKET	Broken	110.40 FS	*110.40 FS
34	1		*BUMPER BRACKET	Dented	318.40 FS	*318.40 FS
35	1		*LOW RR PAN FIX	Necessary	88.80 FS	*88.80 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
36	1		*SIDE DOOR LH	Dented	1,231.20 FS	*1,231.20 FS
37	1		*SIDE DOOR RH	Dented	1,007.20 FS	*1,007.20 FS
38	1		*DOOR STOP	Not Necessary	108.00 FS	*- FS
39	1		*WEATHERSTRIP	Crushed	159.20 FS	*159.20 FS
40	1		*DOOR SEAL RH	Not Necessary	112.80 FS	*- FS
41	1		*WATER JET SEAL	Not Necessary	63.20 FS	*- FS
42	1		*DOOR FIXING AV	Not Necessary	94.40 FS	*- FS
43	1		*BADGE -CITROEN	Necessary	46.40 FS	*46.40 FS
44	1		*BADGE -BERLINGO	Necessary	46.40 FS	*46.40 FS
45	1		*LATCH CONTROL	Not Necessary	104.00 FS	*- FS
46	1		*HANDLE HOLDER LH	Not Necessary	67.20 FS	*- FS
47	1		*DOOR LOCK RH SUP	Not Necessary	74.40 FS	*- FS
48	1		*DOOR LOCK RH INF	Bent	74.40 FS	*74.40 FS
49	1		*LOCKING RACK LH INE	Broken	60.80 FS	*60.80 FS
50	1		*HANDLE BASE LH	Not Necessary	3.20 FS	*- FS
51	1		*DOOR HANDLE LH	Not Necessary	82.40 FS	*- FS
52	1		*TAIL LIGHT LH	Broken	134.40 FS	*134.40 FS
53	1		*TAIL LIGHT RH	Not Necessary	134.40 FS	*- FS
54	2		*LICEN PLATE LAMP	Broken	46.40 FS	*46.40 FS
55	1		*SENSOR	Broken	195.20 FS	*195.20 FS
56	1		*SENSOR SUPPORT ENS	Necessary	128.80 FS	*128.80 FS
57	1		*BADGE	Necessary	47.20 FS	*47.20 FS
58	1		*DOOR TRIM RH	Crushed	96.00 FS	*96.00 FS
59	1		*REAR PANEL	Dented	603.20 FS	*603.20 FS
60	1		*BLIND RIVET 7.5 X21 (X3)	Necessary	9.60 FS	*9.60 FS
61	1		*ESPAGN STRIKER RH INF	Broken	33.60 FS	*33.60 FS
62	1		*ESPAGN STRIKER LH INF	Broken	33.60 FS	*33.60 FS
63	1		*EXTENSION	Dented	453.60 FS	*453.60 FS
64	1		*INNER FRAME	Dented	604.80 FS	*604.80 FS

F=Franchise part. S=SpcNett.

Total Parts (S\$)**13,261.20****9,185.60**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REPLACE REAR FLOOR PANEL & REAR END PANEL	New	1,000.00	1,000.00
2	RESPRAY REAR FLOOR PANEL & REAR END PANEL	New	760.00	760.00
3	SUPPLY 6 PAX STICKER & 70KM/H STICKER	New	38.00	38.00
4	RENEW (FRT PORTION) FRT BUMPER ,BONNET & LHF FENDER REPAIR FRT SUPPORT PNL	New	2,500.00	500.00
5	RENEW (RR PORTION) TAILGATE LH/RH ,RR BUMPER & RR END PNL REPAIR RR FLR PNL ,LHR FENDER & RHR FENDER	New	4,000.00	1,000.00
6	RESPRAY FRT BUMPER ,BONNET ,LHF FENDER ,TAILGATE LH ,TAILGATE RH ,RR FLR PNL ,RR END ,LHR FENDER & RHR FENDER	New	3,800.00	1,520.00
7	REMOVE & REFIT TAILGATE LH COMPONENT	New	120.00	120.00
8	REMOVE & REFIT TAILGATE RH COMPONENT	New	120.00	120.00
9	REMOVE & REFIT RR FLR BOARD ,TRIM & CARPET	New	120.00	120.00
10	CHECK WIRING ELECTRICAL SYSTEM & ADJUST HEADLAMP AIM	New	50.00	50.00
11	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST	New	275.00	225.00
12	TO CONDUCT COMPUTERIZE FULL WHEEL ALIGNMENT	New	180.00	0.00
13	REMOVE & REFIT TAILGATE LH GLASS	New	240.00	240.00
14	REMOVE & REFIT TAILGATE RH GLASS	New	240.00	240.00
15	SUPPLY RR WINDSCREEN SEALANT	New	80.00	80.00
16	REMOVE & REFIT REVERSE SENSOR	New	80.00	80.00
17	APPLY ANTI CORROSION ON AFFECTED AREAS	New	120.00	40.00
18	REMOVE & REFIT FRT PARKING ASSIST SENSOR	New	80.00	80.00
Gross Labour Cost (\$\$)			13,803.00	6,213.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >