

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG21006005/T1GS3Q2
Date: 19/11/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1700089766
Claimant Vehicle No :	SMJ8454P	Insured Vehicle No :	SLV5266J
Date of Loss:	18/05/2021	Nature of Claim:	TP
		Claim No:	3165466687SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMJ8454P		
Make & Model:	NISSAN SYLPHY, 1.6 (A)	Engine No:	HR16940292C
Reg. Date:	22/03/2019 (Man. Year: 2019)	Chassis No:	MNTBBAB17Z0034754
Colour:	Grey	Odometer:	39132 km
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/60 R16	Rear Tyre Size:	195/60 R16
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,622.25	1,531.50	90.75	5.59
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,830.00	730.00	1,100.00	60.11
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	3,452.25	2,261.50	1,190.75	34.49
Approved Total (Overridden) (S\$)		1,800.00		

(S\$)	3,452.25	1,800.00	1,652.25	47.86
+ GST 7.00/7.00% (S\$)	241.66	126.00	115.66	47.86
Nett Amount (S\$)	3,693.91	1,926.00	1,767.91	47.86
+ Car Rental (5.0 x S\$100.00/day + 7.00% GST) (S\$)		535.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		2,463.00		

INSPECTION

Date of Assignment: 20/05/2021

Date Inspected: 20/05/2021

Estimated Period of Repair: 3.0 days

Inspected At:

Premier Automotive Services Pte Ltd (HQ)
 23 Changi South Ave 2, #01-02
 Singapore 486443

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	620.00 FL	*620.00 FL
2	1		*FRONT BUMPER O/S SIDE BRACKET	Not Necessary	35.00 FL	*- FL
3	1		*FRONT O/S HEADLAMP	Cut	950.00 FL	*950.00 FL
4	1		*FRONT O/S FENDER	Bent	740.00 FL	*740.00 FL
5	1		*SET FRONT BUMPER CLIPS	Necessary	48.00 FS	*30.00 FS
6	1		*SUNDRY	Not Necessary	50.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	2,443.00	2,340.00
- List Item Discount on L Items 35.00/35.00% (\$)	820.75	808.50
Total Parts (\$)	1,622.25	1,531.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO DISMANTLE /REFIT THE INNER GARNISHES ,INNER LININGS ,INNER TRIMS ,CUSHION SEAT ,CARPET,ETC TO FACILITATE REPAIRS	New	180.00	0.00
2	TO LABOUR CHARGE FOR DISMANTLE AND RENEW THE ACCIDENT DAMAGED PARTS .INCLUDING KNOCK-OUT ,STRAIGHTEN ,REPAIR,RESHAPE AND ADJUST OF THE SUPPORT PANEL ETC	New	800.00	300.00
3	TO PUTTY AND SPRAY PAINTING ON FRONT BUMPER ,FRONT O/S FENDER ,SUPPORT PANEL	New	750.00	400.00
4	TO APPLY RUSTPROOFING ON THE REPAIRED AND REPLACED PANELS	New	100.00	30.00
Gross Labour Cost (S\$)			1,830.00	730.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >