

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/GRB21006014/UEA3Q2**Date:** 17/05/2022REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D21MFL0000447
Claimant Vehicle No :	FBN8687T	Insured Vehicle No :	SLJ7186G
Date of Loss:	14/05/2021	Nature of Claim:	TP
		Claim No:	MFL2021D0002084

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FBN8687T	Engine No:	G3J1E0305964
Make & Model:	YAMAHA AEROX GDR155A, 155cc CVT ABS	Chassis No:	MH3SG4620JJ050131
Reg. Date:	27/12/2018 (Man. Year: 2018)	Odometer:	0 km
Colour:	Blue		
Engine Capacity:	155 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	110/80-14	Rear Tyre Size:	140/70-14
Front Left Side:	Maxxis 7 mm	Rear Left Side:	Maxxis 7 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,374.80	1,606.50	3,768.30	70.11
Miscellaneous Items	0.00	0.00	0.00	
Labour	970.00	300.00	670.00	69.07
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,344.80	1,906.50	4,438.30	69.95
Approved Total (Overridden) (S\$)		1,500.00		
Nett Amount (S\$)	6,344.80	1,500.00	4,844.80	76.36
+ Loss of Use (6.0 x S\$20.00/day) (S\$)		120.00		
Nett Liability (S\$)		1,620.00		

INSPECTION

Date of Assignment:	20/05/2021	Erofia Motor Trading Pte Ltd - (kaki Bukit) (HQ)
Date Inspected:	21/05/2021 Inspected At:	1 Kaki Bukit Avenue 6, #02-62 AutoBay @ Kaki Bukit
Estimated Period of Repair:	4.0 days	Singapore 417883

Adjuster: MARCUS CHUA**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 26 Apr 2022)	
Parts:	N/A	YAMAHA AEROX GDR155A 155cc CVT ABS (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FBN8687T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FORK ASSY	Not Necessary	980.00 FL	*- FL
2	1		*FORK UNDER BRACKET	Not Necessary	190.00 FL	*- FL
3	1		*FRONT SPORT RIM	Not Necessary	550.00 FL	*- FL
4	1		*FRONT BRAKE DISC	Not Necessary	180.00 FL	*- FL
5	1		*FRONT RIM SHAFT	Not Necessary	52.00 FL	*- FL
6	1		*HEADLAMP	Serviceable	550.00 FL	*- FL
7	1		*SET SIDE MIRROR	Cut	120.00 FL	*120.00 FL
8	1		*HANDLE -BAR	Serviceable	135.00 FL	*- FL
9	1		*BRAKE LEVER -R/H	Cut	52.00 FL	*52.00 FL
10	1		*FOOTSTEP PANEL	Cut	255.00 FL	*150.00 FL
11	1		*FOOTSTEP PANEL LOWER COVER	Cut	170.00 FL	*115.00 FL
12	1		*BELT COVER (CUT)	Not Consistent With The Impact	175.00 FL	*- FL
13	1		*AIR FILTER COVER (CUT)	Not Consistent With The Impact	125.00 FL	*- FL
14	1		*EXHAUST ASSY	Repair	680.00 FL	*- FL
15	1		*EXHAUST PROTECTOR	Cracked	48.00 FL	*48.00 FL
16	1		*SET FAIRING COVER	Cut / Damaged	1,450.00 FL	*1,300.00 FL
17	1		*SET NUMBER PLATE	Not Necessary	28.00 FS	*- FS
18	2		*FORK OILS	Not Necessary	30.00 FS	*- FS
19	2		*FORK OIL SEALS	Not Necessary	56.00 FS	*- FS
20	1		*SET STEERING CONE	Not Necessary	120.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	5,946.00	1,785.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	571.20	178.50
Total Parts (\$\$)	5,374.80	1,606.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO PROVIDE TOWING SERVICE	New	60.00	0.00
2	TO PROVIDE WIRING AND RESET HEADLAMP FOCUSING	New	80.00	0.00
3	TO REPAIR BODY FRAME	New	380.00	0.00
4	TO PROVIDE LABOUR	New	450.00	300.00
Gross Labour Cost (\$\$)			970.00	300.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >