6/16/2021 Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CS3/AIG21006018/T1VF3Q2

Date:

16/06/2021

REFERENCE

Date of Loss:

Reg. Date:

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:

2070105697 SMT7058D

Claimant Vehicle No:

SMM7879M 14/05/2021

Insured Vehicle No: Nature of Claim:

TP

Claim No:

1317841073SG

LEB5621469

GB71084177

93568 km

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SMM7879M

Make & Model: HONDA ACCORD, 1.6 (M)

10/07/2019 (Man. Year: 2018)

Colour: Grey

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable): Yes

Footbrake (Serviceable):

Engine No:

Chassis No:

Odometer:

Yes

Handbrake (Serviceable): **Engine Modification:** Pre-accident Condition: Yes No

CONDITION OF TYRES

Front Tyre Size: Rear Tyre Size: 185/65 R15 185/65 R15

Front Left Side: GREEN-MAX 6 mm Rear Left Side: GREEN-MAX 6 mm Front Right Side: GREEN-MAX 6 mm Rear Right Side: GREEN-MAX 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		0.00	0.00	0.00	
Miscellaneous Items		0.00	0.00	0.00	
Labour		0.00	0.00	0.00	
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

6/16/2021 Adjuster Report

Date of Assignment: 20/05/2021

Ky Auto Pte Ltd (HQ) Date Inspected: Inspected At: 25 KAKI BUKIT ROAD 4 SYNERGY@KB #05-23 24/05/2021

Singapore 417800

Estimated Period of Repair: 6.0 days

Adjuster: MOHD TAUFIKH BIN HAMID Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly

MARKET VALUE: \$98,000.00

REPAIR DETAILS

Recommended Parts

No.	Qty Part No.	Particulars	Condition	Repairer's	Amount
1	1	*REAR BUMPER	Deformed	0.00 F	*- F
2	1	*REAR BUMPER CLIPS	Necessary	0.00 F	*-F
3	1	*REAR BUMPER SIDE RETAINER	Necessary	0.00 F	*-F
4	1	*REVERSE SENSOR	Not Working	0.00 F	*-F
5	1	*REAR BUMPER REFLECTOR LH	Cracked	0.00 F	*- F
6	1	*TAILGATE	Bent	0.00 F	*-F
7	1	*TAILGATE LAMP LH	Cracked	0.00 F	*- F
8	1	*TAILGATE INNER BOARD	Cracked	0.00 F	*-F
9	1	*TAILGATE LOCK	*Check	0.00 F	*- F
10	1	*TAILGATE WINDSCREEN SEALANT	Necessary	0.00 F	*-F
11	1	*TAILLAMP LH	Cracked	0.00 F	*- F
12	1	*REAR END PANEL	Repair	0.00 F	*-F
13	1	*REAR FENDER INNER SHIELD LH	Deformed	0.00 F	*- F
14	1	*REAR FENDER LH	Repair	0.00 F	*- F
F=Fran	nchise part.				
			Total Parts (S\$)	0.00	0.00
		Damant was was the	mitted during this print out		

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

6/16/2021

Report was unsubmitted during this print-out.

< END OF ESTIMATES >