



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## PRE-REPAIR INSPECTION REPORT

MS FIRST CAPITAL INSURANCE LTD  
36 ROBINSON ROAD  
#16-01 CITY HOUSESINGAPORE 068877

Ref: CS3/FCI21006026/Gtf3e2

Date: 11/06/2021

Code: FCI2

### 1. Policy Particulars :- (THIRD PARTY CLAIM)

|                     |                 |                       |            |
|---------------------|-----------------|-----------------------|------------|
| <b>Insured Veh.</b> | GBJ 9265S       | <b>Veh. Inspected</b> | SKQ 362K   |
| <b>Policy No.</b>   |                 | <b>Coverage (\$)</b>  | 0.00       |
| <b>Claim No.</b>    | D21001562MFCV/1 | <b>Excess (\$)</b>    | 0.00       |
| <b>Assign From</b>  | ESTHER          | <b>Assign Date</b>    | 20/05/2021 |

### 2. Vehicle Particulars & Condition


|                         |                   |                     |            |
|-------------------------|-------------------|---------------------|------------|
| <b>Make &amp; Model</b> | HONDA CITY 1.5    | <b>c.c</b>          | 1497       |
| <b>Engine No.</b>       | HIDDEN            | <b>Year of Reg.</b> | 2014       |
| <b>Chassis No.</b>      | MRHGM6660EP000130 | <b>Colour</b>       | BROWN      |
| <b>Odometer</b>         | 100432 KM         | <b>Steering</b>     | IN ORDER   |
| <b>Brakes</b>           | IN ORDER          | <b>Modification</b> | SPORTS RIM |
| <b>General</b>          | GOOD              |                     |            |

### 3. Conditions of Tyres

|                       | Size       | Make   | Balance |
|-----------------------|------------|--------|---------|
| <b>R/H Front Tyre</b> | 185/55 R16 | PETLAS | 6 mm    |
| <b>L/H Front Tyre</b> | 185/55 R16 | PETLAS | 6 mm    |
| <b>R/H Rear Tyre</b>  | 185/55 R16 | PETLAS | 6 mm    |
| <b>L/H Rear Tyre</b>  | 185/55 R16 | PETLAS | 6 mm    |

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR AND N/S REAR PORTION. THE UNDERCARRIAGE AFFECTED DUE TO COLLISION.



### 5. General Information

|                       |   |                            |                         |
|-----------------------|---|----------------------------|-------------------------|
| <b>Accident Date</b>  | 18/05/2021  | <b>Inspect Date / Time</b> | 21/05/2021 ( 04:30 PM ) |
| <b>Survey held at</b> | KIM MOTORING<br>BLK C3 391A WOODLANDS ROAD YEW TEE INDUSTRIAL ESTATE SINGAPORE 677964 |                            |                         |

### 5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.  
B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.  
C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.  
D) MARKET VALUE:\$39,000.00

Report Ref No. CS3/FCI21006026/Gtf3e2

#### Inspected By

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.