

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG21006027/T1VF3Q2
Date: 14/06/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	0999993591
Claimant Vehicle No :	SGG4848A	Insured Vehicle No :	GBL3210D
Date of Loss:	18/05/2021	Nature of Claim:	TP
		Claim No:	2986126689SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SGG4848A	Engine No:	A9060665N20B20B
Make & Model:	BMW 520I, 2.0 (A)	Chassis No:	WBA5A32040D335057
Reg. Date:	28/08/2014 (Man. Year: 2013)	Odometer:	85269 km
Colour:	White		
Engine Capacity:	1997 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	245/40 R19	Rear Tyre Size:	245/40 R19
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

6/14/2021

Adjuster Report

Date of Assignment: 20/05/2021

Date Inspected: 21/05/2021

Estimated Period of Repair: 5.0 days

Inspected At:

Hup Ley Huat Motor Spray Painting Services
BLK 1 KAKI BUKIT AVE 6 #01-35
Singapore 409793

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

6/14/2021

Adjuster Report

MARKET VALUE: \$75,000.00

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT BUMPER	Deformed	0.00 F	*- F
2	1		*FRT BUMPER CLIPS	Necessary	0.00 F	*- F
3	1		*FRT BUMPER SIDE RETAINER	Necessary	0.00 F	*- F
4	1		*FRT BUMPER REINFORCEMENT	*Check	0.00 F	*- F
5	1		*FRT BUMPER SPONGE	*Check	0.00 F	*- F
6	1		*BONNET	Bent	0.00 F	*- F
7	1		*FRT LH HEADLAMP	Cut	0.00 F	*- F
8	1		*FRT LH FOGLAMP GARNISH	Deformed	0.00 F	*- F
9	1		*FRT LH FENDER	Repair	0.00 F	*- F
10	1		*FRT SUPPORT PANEL	*Check	0.00 F	*- F
11	1		*FRT GRILLE	*Check	0.00 F	*- F
12	1		*FRT HEADLAMP WASHER	*Check	0.00 F	*- F

F=Franchise part.

Total Parts (S\$)
0.00
0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >