

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21006028/T1VF3N2**Date:** 04/01/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNW00020682100

Claimant Vehicle No : GBD7330G **Insured Vehicle No :** GBL269E

Date of Loss: 19/05/2021 Nature of Claim: TP Claim No: SNM21D202913/C02/TANKL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBD7330G**

Make & Model: TOYOTA DYNA 150, 3.0 D (M) Engine No: 1KD2477608

Reg. Date: 08/04/2015 (Man. Year: 2014) Chassis No: JTFAT35Y30K204234

Colour: Silver Odometer: 300159 km

Engine Capacity: 2982 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/75 R15 Rear Tyre Size: 155R12 (D)

Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6/6 mm

Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6/6 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	44,743.00	3,160.87	41,582.13	92.94
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,700.00	1,670.00	6,030.00	78.31
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	52,443.00	4,830.87	47,612.13	90.79
Approved Total (Overridden) (\$\$)		3,800.00		
(\$\$)	52,443.00	3,800.00	48,643.00	92.75
+ GST 7.00/7.00% (\$\$)	3,671.01	266.00	3,405.01	92.75
Nett Amount (\$\$)	56,114.01	4,066.00	52,048.01	92.75

INSPECTION

Date of Assignment: 20/05/2021

Date Inspected: 21/05/2021 Inspected At: 56 LOYANG WAY
#04-04
REPAIRER: AP AUTOMOTIVE SERVICES PTE LTD

Estimated Period of Repair: 6.0 days

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 03 Jan 2022)	
Parts:	N/A	TOYOTA DYNA 150 3.0 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBD7330G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Dented	1,128.00 FL	*1,128.00 FL
2	1		*TAILGATE SIDE LOCK BOTTOM L+R	N/s Bent/O/s Not Necessary	612.00 FL	*231.80 FL
3	1		*TAILGATE STICKER-TOYOTA	Necessary	262.00 FL	*115.00 FL
4	1		*TAILGATE STICKER-DYNA	Necessary	91.00 FL	*35.00 FL
5	4		*TAILGATE HINGE SET	Bent	524.00 FL	*432.40 FL
6	2		*SIDE GATE L+R	Not Necessary	2,984.00 FL	*- FL
7	1		*END PANEL	Repair	479.00 FL	*- FL
8	1		*FLOOR PANEL	Not Necessary	4,757.00 FL	*- FL
9	1		*REAR LOWER BRACKET L+R	N/s Bent/O/s Not Necessary	326.00 FL	*163.00 FL
10	1		*REAR LOWER BRACKET STOPPER SET L+R (4 Pcs)	N/s Cut/O/s Not Necessary	184.00 FL	*46.00 FL
11	1		*REAR NUMBER PLATE BRACKET	Bent	161.00 FL	*79.30 FL
12	2		*TAIL LAMP L+R	Cracked	464.00 FL	*464.00 FL
13	2		*TAIL LAMP BRACKET L+R	Not Necessary	264.00 FL	*- FL
14	1		*SPARE TYRE BRACKET	Not Necessary	326.00 FL	*- FL
15	1		*REAR EXHAUST PIPE	Not Necessary	530.00 FL	*- FL
16	2		*REAR EXHAUST MOUNTING L+R	Not Necessary	192.00 FL	*- FL
17	1		*TAILGATE STICKER-70KM/H	Necessary	80.00 FS	*30.00 FS
18	1		*TAILGATE STICKER-6PAX	Necessary	80.00 FS	*30.00 FS
19	1		*TAILGATE STICKER-COMPANY	Necessary	600.00 FS	*300.00 FS
20	1		*TAILGATE SCUFF PLATE	Necessary	3,000.00 FS	*400.00 FS
21	1		*TAILGATE SCUFF PLATE RIVET	Necessary	150.00 FS	*50.00 FS
22	2		*SIDE GATE SCUFF PLATE L+R	Not Necessary	8,000.00 FS	*- FS
23	2		*SIDE GATE SCUFF PLATE RIVET L+R	Not Necessary	300.00 FS	*- FS
24	1		*END PANEL SEALANT	Not Necessary	120.00 FS	*- FS
25	1		*REAR NUMBER PLATE	Bent	100.00 FS	*30.00 FS
26	1		*REAR STEP BRACKET	Bent	500.00 FS	*100.00 FS
27	1		*REVERSE SENSOR SET	Not Working	300.00 FS	*200.00 FS
28	1		*REVERSE SENSOR HOLDER SET	Not Necessary	300.00 FS	*- FS
29	1		*FLOOR PANEL SCUFF PLATE	Not Necessary	5,000.00 FS	*- FS
30	1		*FLOOR PANEL SCUFF PLATE RIVET	Not Necessary	200.00 FS	*- FS
31	1		*FLOOR PANEL TOP BOARD	Not Necessary	4,000.00 FS	*- FS
32	1		*REVERSE SENSOR SET	Not Necessary	300.00 FS	*- FS
33	1		*REVERSE SENSOR HOLDER SET	Not Necessary	300.00 FS	*- FS
34	1		*REVERSE CAMERA	Not Necessary	850.00 FS	*- FS
35	1		*REAR CANOPY	Not Necessary	6,000.00 FS	*- FS
36	2		*REAR CANOPY GATE L+R	Not Necessary	4,000.00 FS	*- FS
37	1		*REAR CHASSIS EXTENSION	Not Necessary	600.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) **48,064.00** **3,834.50**
- List Item Discount on L Items 25.00/25.00% (\$\$) **3,321.00** **673.63**

Total Parts (\$\$) **44,743.00** **3,160.87**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING ON AFFECTED AREAS	New	1,600.00	800.00
2	SPRAY PAINT ON AFFECTED AREAS	New	1,200.00	750.00
3	TO CHECK WIRING AND TAIL LAMP FUNCTION	New	150.00	30.00
4	TO CHECK WIRING AND RNR REVERSE CAMERA	New	200.00	30.00
5	TO RNR TAILGATE SCUFF PLATE	New	1,600.00	0.00
6	TO RNR TAILGATE STICKER	New	400.00	0.00
7	TO RNR REAR CANOPY	New	800.00	0.00
8	TO RNR REAR CANOPY GATE	New	600.00	0.00
9	TO RNR REAR EXHAUST	New	400.00	0.00
10	TO RNR REAR REVERSE SENSOR AND CHECK FUNCTION	New	150.00	30.00
11	TO PERFORM RUST PROOFING	New	600.00	30.00
Gross Labour Cost (\$\$)			7,700.00	1,670.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >