

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG21006030/AGA3Q2
Date: 30/09/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800122595	
Claimant Vehicle No :	SJM9802G	Insured Vehicle No :	SCW1288Z	
Date of Loss:	12/05/2021	Nature of Claim:	TP	Claim No: 0130048456SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJM9802G		
Make & Model:	HONDA FIT, 1.3 G (A)	Engine No:	L13A4131898
Reg. Date:	22/01/2009 (Man. Year: 2008)	Chassis No:	GE61120352
Colour:	Red	Odometer:	148138 km
Engine Capacity:	1339 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	205/50 R16	Rear Tyre Size:	205/50 R16
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,414.90	957.76	2,457.14	71.95
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,650.00	730.00	920.00	55.76
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,064.90	1,687.76	3,377.14	66.68
Approved Total (Overridden) (S\$)		1,350.00		

Nett Amount (S\$)	5,064.90	1,350.00	3,714.90	73.35
+ Loss of Use (4.0 x S\$50.00/day) (S\$)		200.00		
Nett Liability (S\$)		1,550.00		

INSPECTION

Date of Assignment: 18/05/2021

Date Inspected: 18/05/2021

Estimated Period of Repair: 3.0 days

Inspected At:

Polymath Garage Pte Ltd - Kaki Bukit (HQ)
 10 KAKI BUKIT ROAD 2, #01-21 FIRST EAST CENTRE
 Singapore 417868

Adjuster: ADRIAN LING**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	486.30 F	*486.30 FL
2	1		*FRONT BUMPER CLIPS	Necessary	30.00 FS	*30.00 FS
3	1		*FRONT BUMPER SIDE HOLDER LH	Cracked	24.40 F	*24.40 FL
4	1		*HEADLAMP LH	Cracked	649.00 F	*649.00 FL
5	1		*FRONT FENDER LH	Repair	386.60 F	*- FL
6	1		*FRONT FENDER INNER SHIELD LH	Not Necessary	96.20 F	*- FL
7	1		*FRONT FENDER INNER SHIELD CLIPS LH	Not Necessary	30.00 FS	*- FS
8	1		*FRONT LH WHEEL RIM	Not Necessary	600.00 FS	*- FS
9	1		*FRONT LH KNUCKLE ARM	Not Necessary	348.00 F	*- FL
10	1		*FRONT LH LOWER ARM	Not Necessary	253.30 F	*- FL
11	1		*FRONT LH WHEEL HUB C/W BEARING	Not Necessary	189.70 F	*- FL
12	1		*FRONT LH SHOCK ABSORBER	Not Necessary	321.40 F	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	3,414.90	1,189.70
- List Item Discount on L Items 0.00/20.00% (\$\$)	0.00	231.94
Total Parts (\$\$)	3,414.90	957.76

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	500.00	300.00
2	SPRAY PAINTING	New	600.00	400.00
3	WIRING	New	50.00	30.00
4	TO DISMANTLE FRONT UNDERCARRIAGE	New	350.00	0.00
5	TO PERFORM WHEEL ALIGNMENT	New	150.00	0.00
Gross Labour Cost (S\$)			1,650.00	730.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >