

SJM9802G.

Harder Fit.

TPA1G.

GE61120352

Caulia.

Front Bumper	Deformed	486.30 ✓
Front Bumper Clips.	re	30.(sn) ✓
Front Bumper Side Holder	LH. ^{cauled}	24.40 ✓
Headlamp	LH. ^{cauled}	649 ✓
Front Fender	LH. ^{Regr}	386.60 .+
Front Fender Inner Shield	LH. ^{re}	76.20 .+
Front Fender Inner Shield Clips	LH ^{re}	30(sn) ✓
Front LH Wheel Rim.	^{re} 600(sn).	X
Front LH Knuckle Arm	^{re}	348 +
Front LH Lower Arm.	^{XHP} Nec	253.30+
Front LH Wheel Hub c/w Bearing.	^{Nec}	189.70 +
Front LH Shock Absorber	^{XHP} Nec	321.40 .+

SJM98026.

Panel Beating.

~~500~~ 300

Spray Painting.

~~600~~ 400

Wiring.

~~50~~ 30

To dismantle front undercarriage. 350 X

To perform wheel alignment. 150 X

List: 1159.70

Labour: 730.

Len 20%: 927.76

Total: 1687.76.

S.N: 30

L/s: 1350

03 Days.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: