

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CS/AIG21006033/KVF3N2**Date:** 29/12/2021**REFERENCE**

Insured/Claimant:	Keong Industries Pte Ltd	Policy No:	1900156362	
Date of Loss:	19/05/2021	Nature of Claim:	OD	Claim No: 6897717322SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBH8888L		Engine No:	ZD30001311N
Make & Model:	NISSAN CABSTAR, 2.0 (M)		Chassis No:	JN1SC2F24Z0857577
Reg. Date:	17/09/2015 (Man. Year: 2015)		Odometer:	144552 km
Colour:	White			
Engine Capacity:	2953 cc			
Market Value/New Car Price:	S\$35,000.00			
Sum Insured (S\$):	Market Value/New Car Price			

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195R15X8	Rear Tyre Size:	155R12X8(D)
Front Left Side:	OHTSU 7 mm	Rear Left Side:	Yokohama 2/2 mm
Front Right Side:	OHTSU 7 mm	Rear Right Side:	Yokohama 4/4 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	23,375.85	5,942.51	17,433.34	74.58
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,390.00	1,540.00	2,850.00	64.92
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	27,765.85	7,482.51	20,283.34	73.05
Approved Total (Overridden) (S\$)		6,000.00		
- Excess (S\$)	600.00	600.00	0.00	0.00
(S\$)	27,165.85	5,400.00	21,765.85	80.12
+ GST 7.00/7.00% (S\$)	1,901.61	378.00	1,523.61	80.12
Nett Amount (S\$)	29,067.46	5,778.00	23,289.46	80.12

INSPECTION

Date of Assignment: 21/05/2021

Date Inspected: 21/05/2021 Inspected At:

Yee Auto Pte Ltd (HQ)
160 SIN MING DRIVE, #02-17 SIN MING
AUTOCITY
Singapore 575722

Estimated Period of Repair: 7.0 days

Adjuster: KENNETH KONG**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*AIR CON CONDENSER PRESSURE PIPE	Bent	464.40 F	*361.10 FL
2	1		*AIR CON CONDENSER SUCTION PIPE	Bent	513.90 F	*404.20 FL
3	1		*DIESEL TANK	Bent	1,500.85 F	*1,500.85 FL
4	1		*DIESEL TANK HOLDER BRACKET	Repair	275.15 F	*- FL
5	1		*FRONT BUMPER	Bent	556.30 F	*556.30 FL
6	1		*SET FRONT BUMPER CLIPS	Not Necessary	80.00 F	*- FL
7	1		*FRONT BUMPER REINFORCEMENT	Bent	328.10 F	*328.10 FL
8	1		*FRONT GRILLE	Cracked	669.50 F	*438.40 FL
9	1		*FRONT GRILLE LOGO	Necessary	65.00 F	*65.00 FL
10	1		*FRONT HEADLAMP-LH	Broken	602.50 F	*473.40 FL
11	1		*FRONT HEADLAMP-RH	Broken	602.50 F	*473.40 FL
12	1		*FRONT HEADLAMP LOWER GARNISH-LH	Serviceable	268.00 F	*- FL
13	1		*FRONT HEADLAMP LOWER GARNISH-RH	Serviceable	268.00 F	*- FL
14	1		*FRONT PANEL	Repair	1,979.50 F	*- FL
15	1		*FRONT SIDE PANEL-LH	Repair	118.10 F	*- FL
16	1		*FRONT SIDE PANEL-RH	Repair	118.10 F	*- FL
17	1		*FRONT WINDSCREEN GLASS	Cracked	1,178.75 F	*991.80 FL
18	1		*FRONT WINDSCREEN MOULDING	Necessary	384.50 F	*180.00 FL
19	1		*FRONT WIPER ARM-LH	Serviceable	287.50 F	*- FL
20	1		*FRONT WIPER ARM COVER-LH	Serviceable	30.00 F	*- FL
21	1		*FRONT WIPER BLADE-LH	Serviceable	40.00 F	*- FL
22	1		*FRONT WIPER BLADE-RH	Serviceable	40.00 F	*- FL
23	1		*FRONT WIPER MOTOR	Serviceable	729.00 F	*- FL
24	1		*FRONT WIPER NOZZLE-LH	Serviceable	85.00 F	*- FL
25	1		*FRONT WIPER PANEL COVER	Repair	681.20 F	*- FL
26	1		*WATER COOLANT	Serviceable	50.00 F	*- FL
27	1		*FRONT BUMPER TOW HOOK	Repair	320.25 F	*- FL
28	1		*FRONT CROSS MEMBER	Serviceable	750.00 F	*- FL
29	1		*FRONT KNUCKLE ARM-RH	Not Necessary	641.70 F	*- FL
30	1		*FRONT LOWER ARM-LH	Not Necessary	320.00 F	*- FL
31	1		*FRONT LOWER ARM-RH	Not Necessary	320.00 F	*- FL
32	1		*FRONT SHOCK ABSORBER-LH	Not Necessary	285.90 F	*- FL
33	1		*FRONT SHOCK ABSORBER-RH	Not Necessary	285.90 F	*- FL
34	1		*FRONT STEERING RACK	Not Necessary	2,800.00 F	*- FL
35	1		*FRONT STEP GARNISH-LH	Cracked	185.00 F	*185.00 FL
36	1		*FRONT STEP GARNISH-RH	Serviceable	185.00 F	*- FL
37	1		*FRONT STEP INNER PANEL-LH	Repair	265.00 F	*- FL
38	1		*FRONT STEP INNER PANEL-RH	Repair	265.00 F	*- FL
39	1		*FRONT UPPER ARM-LH	Not Necessary	475.20 F	*- FL
40	1		*FRONT UPPER ARM-RH	Not Necessary	475.20 F	*- FL
41	1		*FRONT WHEEL BEARING-LH	Not Necessary	375.20 F	*- FL
42	1		*FRONT WHEEL BEARING-RH	Not Necessary	375.20 F	*- FL
43	1		*FRONT STEERING BOX (LOWER)	Not Necessary	880.15 F	*- FL
44	1		*FRONT WINDSCREEN SEALANT	Necessary	60.00 FS	*40.00 FS
45	1		*ERP IU BRACKET	Necessary	40.00 FS	*26.00 FS
46	1		*FRONT EMBLEM CABSTAR	Necessary	62.00 FS	*62.00 FS
47	1		*FRONT NUMBER PLATE	Bent	60.00 FS	*20.00 FS
48	1		*REAR NUMBER PLATE	Serviceable	60.00 FS	*- FS
49	1		*FRONT KNUCKLE ARM-LH	Bent	641.70 F	*480.80 FL
50	1		*LOWER ARM BALL JOINT -LH (Supplementary)	Not Necessary	265.15 F	*- F
51	1		*LOWER ARM BALL JOINT-RH (Supplementary)	Not Necessary	265.15 F	*- F
52	1		*STEERING COUPLING (Supplementary)	Not Necessary	255.85 F	*- F
53	1		*ENGINE MOUNTING-LH (Supplementary)	Not Necessary	185.15 F	*- F

Report was unsubmitted during this print-out.

12/29/21, 9:38 AM

Adjuster Report

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
54	1		*ENGINE MOUNTING-RH (Supplementary)	Not Necessary	185.15 F	*- F
55	1		*GEAR BOX MOUNTING (Supplementary)	Not Necessary	175.15 F	*- F
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (S\$)					23,375.85	6,586.35
- List Item Discount on L Items 0.00/10.00% (S\$)					0.00	643.84
Total Parts (S\$)					23,375.85	5,942.51

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	AIRCON GAS	New	80.00	80.00
2	TO DISMANTLE & REPLACE DAMAGED PARTS,PANEL BEAT WHERE NECESSARY	New	1,600.00	500.00
3	TO PUTTY,APPLY PRIMER & SPRAY-PAINT ON THE AFFECTED PORTION	New	1,200.00	600.00
4	TO APPLY RUST-PROOFING ON REPAIRED,REPLACED PANEL	New	100.00	0.00
5	TO REMOVE/REFIX FRONT WINDSCREEN TO FACILITATE REPAIRS	New	250.00	120.00
6	TO REMOVE/RENEW AIRCON CONDENSER & REFILL GAS	New	300.00	100.00
7	TO REMOVE/REPLACE FRONT UNDER & REPLACE LABOUR	New	400.00	0.00
8	TO TOW VEHICLE TO WORKSHOP	New	180.00	120.00
9	WHEEL ALIGNMENT	New	180.00	0.00
10	TO CHECK WIRING FUNCTIONS	New	100.00	20.00
Gross Labour Cost (S\$)			4,390.00	1,540.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >