

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.  
3 Anson Road, #16-00 Springleaf Tower  
Singapore 079909

**Our File No:** CS/CTI21006037/KQCE2

**Date:** 18/06/2021

### REFERENCE

Insured/Claimant: LIN YUANJIE Policy No: DMPCSNW00049552100  
Date of Loss: 15/05/2021 Nature of Claim: OD Claim No: SNM21D202856/C01/TAYHP

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SFX7006R**  
Make & Model: HONDA STREAM, 1.8 L (A) Engine No: R18A13860120  
Reg. Date: 20/10/2010 (Man. Year: 2009) Chassis No: JHMRN6860AC200120  
Colour: Red Odometer: 0 km  
Engine Capacity: 1799 cc  
Market Value/New Car Price: S\$56,000.00  
Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 225/45Z R17 Rear Tyre Size: 225/45Z R17  
Front Left Side: Toyo 8 mm Rear Left Side: Toyo 8 mm  
Front Right Side: Toyo 8 mm Rear Right Side: Toyo 8 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	200.00	0.00	200.00	100.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>200.00</b>	<b>0.00</b>	<b>200.00</b>	<b>100.00</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>14.00</b>	<b>0.00</b>	<b>14.00</b>	<b>100.00</b>
<b>Nett Amount (S\$)</b>	<b>214.00</b>	<b>0.00</b>	<b>214.00</b>	<b>100.00</b>

### INSPECTION

Date of Assignment: 21/05/2021

Date Inspected: 21/05/2021

Estimated Period of Repair: 0.0 days

Inspected At:

Cheng Hoe Motor Pte Ltd  
10 Ang Mo Kio Ind Park 2A  
#01-04 Ang Mo Kio Autopoint  
Singapore 568047

**Adjuster:** KENNETH KONG

**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

**TOTAL LOSS ASPECT**

Market Value :	\$56,000.00
OMV :	\$25,509.00
PARF Rebate (1) :	\$ 0.00
Quota Premium Paid :	\$38,216.00
COE Rebate (2) :	\$36,007.00
Total Rebate (1) + (2) = :	\$36,007.00

The total amount incurred will be Market Value \$56,000.00 minus Total Rebate \$36,007.00 = \$19,993.00 before excess.

In view of the above, the vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

# REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 18 Jun 2021)
Parts:	M1-MPV	HONDA STREAM 1.8 L (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SFX7006R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.
-----------------------------------------------

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TOWING (CRANE UP )	New	200.00	0.00
<b>Gross Labour Cost (\$\$)</b>			<b>200.00</b>	<b>0.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >