



Your Ref : SNM21D202856/C01/TAYHP

Date: 18th June 2021

Our Ref : CS/CTI21006037/Kqce2

M/s China Taiping Insurance (S) Pte Ltd

3 Anson Road #16-00

Springleaf Tower

Singapore 079909

(The Motor Claims Department)

Dear Sirs/Madam,

**AUTOMOBILE INSPECTION REPORT OF ACCIDENT VEHICLE SFX 7006R
ACCIDENT ON 15/05/2021**

Instruction was received to inspect the vehicle Reg. No. SFX 7006R. The inspection was conducted on 21/05/2021 at the premises of M/s Cheng Hoe Motor Pte Ltd, 10 Ang Mo Kio Ind Park 2A #01-04 Ang Mo Kio Autopoint, Singapore 568047.

The following vehicle information was recorded:

Registration Number	: SFX 7006R
Make/Model	: Honda Stream 1.8L Auto
Year of Registration	: 2010
Body Colour	: Red
Chassis Number	: JHMRN6860AC200120
Engine Capacity	: 1799 cc

The vehicle sustained damages at the front portion. The undercarriage and body structure affected due to collision. (Details see photographs enclosed)

In view of this, we are of the opinion that it would be **uneconomical** to proceed with the repairs due to extensive repair cost and recommend it to be written off as **“Total Loss”**.

Market Value	S\$ 56,000.00 (est)
Less: LTA Reimbursement Value (RV)	(S\$ 36,007.00)
Nett Liability	<u>S\$ 19,993.00</u> =====

Vehicle Inspected By:



KONG SENG CHEONG
Licensed Appraiser



K.K.LAU
MSc(Eng M), B Eng(Hons), Peng(UK),
MASME(USA), B Bus(Aust), MBA(UK),
IEng(UK), MIE(mech), MinstAEA, MFIEA,
MIRTE, MIMI, MSAE, MCIAd, AM, NIJAAR(USA),
AM CATARI(CAN), M.MATA(USA), M.MdATA(USA),
Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.