

AUTO PERFORMANCE APPRAISAL

APA

TAX INVOICE

Mohammad Alif Ridhwan Bin Husni
C/O 833 MotorSports Pte Ltd
160 Sin Ming Drive
Sin Ming AutoCity #02-09
Singapore 575722

INVOICE NO : APA21002183

DATE : 17/04/2021

VEHICLE NO : SLC8686K

JOB REFERENCE NO : 21/002288

ACCIDENT DATE : 07/11/2021

SURVEY DATE : 06/04/2021

<u>DESCRIPTION</u>	<u>AMOUNT</u>
Survey Fees Inclusive Of Transportation	\$540.00
Photographs (\$1) Per Copies : 42	\$42.00

TOTAL AMOUNT : \$582.00

Notes :

All cheque payment should be "Crossed" and made payable to "Auto Performance Appraisal"

Auto Performance Appraisal



AUTO PERFORMANCE APPRAISAL

APA

VEHICLE SURVEY REPORTS																																				
Mohammad Alif Ridhwan Bin Husni C/O 833 MotorSports Pte Ltd 160 Sin Ming Drive Sin Ming AutoCity #02-09 Singapore 575722																																				
1	Reference Job Reference No : 21/002288 Claim No : - Claim Type : Third Party Accident Date : 07/11/2021 Survey Date : 06/04/2021 Survey Report Date : 17/04/2021																																			
2	Particulars Of Vehicle Vehicle Registration No : SLC8686K Make & Model : BMW 523I A Vehicle Registration Date : 30/08/2010 Chassis No : WBAFP32040C543965 Engine No : Blocked Colour : Black																																			
3	Condition Of Vehicle And Tyres <table border="1"><thead><tr><th><u>Mileage (KM)</u></th><th><u>Brakes</u></th><th><u>Steering</u></th><th><u>Modification</u></th></tr></thead><tbody><tr><td>165793</td><td>Serviceable</td><td>Affected</td><td>None</td></tr><tr><td colspan="4"> </td></tr><tr><th><u>Tyres</u></th><th><u>Make</u></th><th><u>Size</u></th><th><u>Balance (MM)</u></th></tr><tr><td>Front RHS</td><td>Arivo</td><td>245/40ZR19</td><td>5</td></tr><tr><td>Front LHS</td><td>Arivo</td><td>245/40ZR19</td><td>5</td></tr><tr><td>Rear RHS</td><td>Arivo</td><td>245/40ZR19</td><td>6</td></tr><tr><td>Rear LHS</td><td>Arivo</td><td>245/40ZR19</td><td>6</td></tr></tbody></table>				<u>Mileage (KM)</u>	<u>Brakes</u>	<u>Steering</u>	<u>Modification</u>	165793	Serviceable	Affected	None	 				<u>Tyres</u>	<u>Make</u>	<u>Size</u>	<u>Balance (MM)</u>	Front RHS	Arivo	245/40ZR19	5	Front LHS	Arivo	245/40ZR19	5	Rear RHS	Arivo	245/40ZR19	6	Rear LHS	Arivo	245/40ZR19	6
<u>Mileage (KM)</u>	<u>Brakes</u>	<u>Steering</u>	<u>Modification</u>																																	
165793	Serviceable	Affected	None																																	
<u>Tyres</u>	<u>Make</u>	<u>Size</u>	<u>Balance (MM)</u>																																	
Front RHS	Arivo	245/40ZR19	5																																	
Front LHS	Arivo	245/40ZR19	5																																	
Rear RHS	Arivo	245/40ZR19	6																																	
Rear LHS	Arivo	245/40ZR19	6																																	
4	Description Of Damages The vehicle sustained damages at left hand portion. (For information of damages please refer to Parts/Labour/Photographs attached)																																			
5	Instruction This survey was conducted entirely on a "WITHOUT PREJUDICE" basis, and we have not authorised any repair.																																			

AUTO PERFORMANCE APPRAISAL

Vehicle Assessment Reports

Annex A

Ref No : 21/002288

Damage And Repair Cost Adjustment

<u>S/No</u>	<u>Qty</u>	<u>Parts Description</u>	<u>Comments/condition</u>	<u>Workshop Estimate (\$)</u>	<u>Our Assessment (\$)</u>
			<u>List Items</u>		
1	1	Front bumper	Deformed/broken	1,205.00	1,205.00
2	1	Front bumper side retainer	Deformed	62.10	62.10
3	1	LH headlamp	Cracked	2,360.00	2,360.00
4	1	Front LH fender	Dented	884.00	884.00
5	1	Front LH fender under shield	Serviceable/reuse	161.00	-
6	1 set	Front fender under shield clips	Broken/necessary	40.00	40.00
7	1	Front LH fender signal lamp	Cut/grazed	88.50	88.50
8	1	Front LH shock absorber	Bent	646.00	646.00
9	1	Front LH knuckle arm	Bent	884.00	884.00
10	1	Front LH lower arm	Bent	397.00	397.00
11	1	Front LH wheel hub with bearing	Bent/necessary	321.00	321.00
12	1	Front LH trailing arm	Bent	497.00	497.00
13	1	Front LH door	To repair	1,789.00	-
				9,334.60	7,384.60
Less discount 5%				466.73	369.23
Total :				8,867.87	7,015.37
			<u>Special Nett Items</u>		
14	1	Front LH sports rims	Dented/warped	900.00	900.00
15	1	Front LH tyre	Serviceable/reuse	320.00	-
Total :				1,220.00	900.00
Total Spare Parts :				8,867.87	7,015.37

AUTO PERFORMANCE APPRAISAL

Vehicle Assessment Reports

Annex B

Ref No : 21/002288

Damage And Repair Cost Adjustment

<u>Items</u>	<u>Job Description</u>	<u>Workshop Estimate (\$)</u>	<u>Adjusted Costs (\$)</u>
1	To remove, jack out, straighten, panel beating, align and renew replaced parts.	1,000.00	600.00
2	To putty and respray painting on affected areas.	1,300.00	1,000.00
3	To check wirings and lightings.	50.00	30.00
4	To remove, refix door fittings to facilitate repair.	80.00	-
5	To remove, refix front undercarriage.	280.00	220.00
6	To conduct computerise wheel alignment test.	80.00	60.00
7	To supplied and applied anti rust treatments.	100.00	60.00
Total Labour :		2,890.00	1,970.00
Total Spare Parts :		8,867.87	7,015.37
Total Labour :		2,890.00	1,970.00
Total Repair Costs :		11,757.87	8,985.37

Assessor's Recommendation

Repairer Estimate :	<u>11,757.87</u>
Our Adjustment :	<u>8,985.37</u>

Remarks

The repairer has agreed to undertake the repair on a lump sum basis of \$7,200.00, with a repair period of 5 working days.



Surveyed By:



Lek Boon Hwee
Automobile Appraiser




APA

Job Reference No : 21/002288






APA

Job Reference No : 21/002288





APA

Job Reference No : 21/002288



APA

Job Reference No : 21/002288







APA



Job Reference No : 21/002288



APA

Job Reference No : 21/002288





APA

Job Reference No : 21/002288



APA

Job Reference No : 21/002288



APA

Job Reference No : 21/002288

