



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLC 8686K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT BUMPER	DEFORMED / BROKEN	1,205.00	1,205.00
1	FRONT BUMPER SIDE RETAINER	DEFORMED	62.10	62.10
1	LH HEADLAMP	CRACKED	2,360.00	2,360.00
1	FRONT LH FENDER	DENTED	884.00	884.00
1	FRONT LH FENDER UNDER SHIELD	SERVICEABLE	161.00	-
1	SET FRONT FENDER UNDER SHIELD CLIPS	BROKEN / NECESSARY	40.00	40.00
1	FRONT LH FENDER SIGNAL LAMP	CUT / GRAZED	88.50	88.50
1	FRONT LH SHOCK ABSORBER	SERVICEABLE	646.00	-
1	FRONT LH KNUCKLE ARM	SERVICEABLE	884.00	-
1	FRONT LH LOWER ARM	SERVICEABLE	397.00	-
1	FRONT LH WHEEL HUB WITH BEARING	SERVICEABLE	321.00	-
1	FRONT LH TRAILING ARM	BENT	497.00	497.00
1	FRONT LH DOOR	TO REPAIR SEE LABOUR	1,789.00	-
	LESS 5% DISCOUNT		-466.73	-256.83
			8,867.87	4,879.77
<u>SPECIAL NETT ITEMS</u>				
1	FRONT LH SPORTS RIMS (SN) (DENTED / WARPED)	NOT CONSISTENT WITH THE IMPACT	900.00	-
1	FRONT LH TYRE (SN)	SERVICEABLE	320.00	-
			1,220.00	-
<u>LABOUR</u>				
	TO REMOVE, JACK OUT, STRAIGHTEN, PANEL BEATING, ALIGN AND RENEW REPLACED PARTS. INCLUSIVE OF THE REPAIR OF FRONT LH DOOR.		1,000.00	500.00
	TO PUTTY AND SPRAY PAINTING ON AFFECTED AREAS.		1,300.00	750.00
	TO CHECK WIRINGS AND LIGHTINGS.		50.00	30.00
	TO REMOVE, REFIX DOOR FITTINGS TO FACILITATE REPAIR.	NOT NECESSARY	80.00	-
	TO REMOVE, REFIX FRONT UNDERCARRIAGE.	NOT NECESSARY	280.00	-
	TO CONDUCT COMPUTERISE WHEEL ALIGNMENT TEST.	NOT NECESSARY	80.00	-

Report Ref No. CS3/SMO21003829/QKqf3e2-1



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO SUPPLIED AND APPLIED ANTI RUST TREATMENTS.		100.00	30.00
			2,890.00	1,310.00
GRAND TOTAL			12,977.87	6,189.77
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				4,950.00

Report Ref No. CS3/SMO21003829/QKqf3e2-1

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.