

FormTeam Consultancy Pte Ltd

No.33, Ubi Ave 3
#02-15, Vertex
Singapore 408868

Tel : (65) 6509 1788
Fax : (65) 6509 6221

Email: motorsurvey@fta.com.sg

Co.Reg No: 200819280D

GST Reg No: 200819280D

Our Reference : NTUC18-128723/PRS/CY/ADJ/CY/gh

Your Reference: MT/1025485-002

Date : 22-Feb-2019

Motor Claims Department
NTUC Income Insurance Co-operative Limited
73 Bras Basah Road
#05-01 NTUC Trade Union House
Singapore 189556

Attention : Ms Rajeswary

Dear Sir/Mdm,

SURVEY OF VEHICLE NO. SMA 6298J

Pursuant to your instruction on **19-Feb-2019**.

We recommend a repair cost of **\$8,050.00** (see report) based on lump sum repair and the estimated duration of repairs would take **05 days**.

We also enclosed our note of charges for your consideration.

Thank you for this assignment.

Your faithfully

FormTeam Consultancy Pte Ltd
Adjusters & Surveyors (Licensed Appraiser)



Ong Chung Yang
Automobile Appraiser

(Email : yang@fta.com.sg)

Encl. Survey Report

AUTOMOBILE ASSESSMENT REPORT

Page No. 1

Our Reference : NTUC18-128723/PRS/CY/ADJ/CY/gh

Your Reference: MT/1025485-002

Date : 22-Feb-19

Attention : Ms Rajeswary

TO : Motor Claims Department
NTUC Income Insurance Co-operative Limited
73 Bras Basah Road
#05-01 NTUC Trade Union House
Singapore 189556

Assessment of Vehicle No : **SMA 6298J**
Date of Accident : **27-December-2018**
Date of Inspection : **02-January-2019**
Address of Inspection : **13 Kaki Bukit Road 4 #01-20 S'417807**

We have carried out a physical assessment of **SMA 6298J** at **M/S Motor Intel Automo Pte Ltd** according to your instructions on **31-Dec-2018**, dismantled items on **02-Jan-2019** post repair survey on **08-Jan-2019** and are pleased to submit our report herewith.

1. VEHICLE PARTICULARS

Registration No. : SMA 6298J
Make & Model : Porsche Cayenne
Year of Registration : 2011
Engine Capacity : 3598 cc
Chassis No. : WP1ZZZ92ZCLA03791
Engine No. : C05024
Colour : Black
Mileage (km) : 107542

2. VEHICLE CONDITION

Body Paint : Fair
Steering : Serviceable
Foot Brake : Serviceable
Parking Brake : Serviceable

3. TYRE PARTICULARS & CONDITION

Front

RH Make/Size : Pirelli 265/50R19 - 50%
LH Make/Size : Pirelli 265/50R19 - 50%

Rear

RH Make/Size : Pirelli 265/50R19 - 50%
LH Make/Size : Pirelli 265/50R19 - 50%


Note : % denotes the remaining percentage of the tyre

Our Reference : NTUC18-128723/PRS/CY/ADJ/CY/gh
Your Reference : MT/1025485-002
Vehicle Number : SMA 6298J

Page No. 2

4. DESCRIPTION OF DAMAGE

At the time of inspection, this vehicle sustained damages to the **RH** portion. Please see attached scheduled for details.



5. REMARKS

Market Value : -
Salvage Value : -
Repair Limit (Nett Loss) : -
Repairer's estimate : **Not Provided**
Nett Saving : -
Excess : -
Sum Insured : -
Our adjusted amount : \$ **8,050.00**
Estimated Repair Days : **05 days**

Additional photographs will be submitted upon request by our principal.

Pursuant to your instruction, we have **NOT AUTHORIZED** repair.

The assessment was conducted on a "**Without Prejudice**" basis.

If we are not notified of anything to the contrary within **14 days** from the date hereof, this report shall be treated as correct.

Disclaimer

This report is intended for the exclusive use of the addressee solely in relation to the loss occurrence in which the assessed vehicle is involved. No liability or responsibility whatsoever shall be held by

FormTeam Consultancy Pte Ltd for any reliance on this report by any third party, unless with the permission of the addressee.

FormTeam Consultancy Pte Ltd

Our Reference : NTUC18-128723/PRS/CY/ADJ/CY/gh
Your Reference : MT/1025485-002
Vehicle Number : SMA 6298J

Page No. 3

[illegible]


FormTeam Consultancy Pte Ltd

Our Reference : NTUC18-128723/PRS/CY/ADJ/CY/gh
 Your Reference : MT/1025485-002
 Vehicle Number : SMA 6298J


Page No. 4

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (S\$)	OUR ASSESSMENT (S\$)
	LABOUR		
1	To rewire rear portion.	-	30.00
2	To remove & refit inner garnishes, inner trim to assist repair.	-	-
3	To remove and refit rear reverse sensor.	-	50.00
4	To remove and refit fuel tank assembly with all attachments, pipes and hoses.	-	-
5	To remove and refit rear undercarriage.	-	-
6	To conduct computerized wheel alignment test.	-	80.00
7	To remove and refit doors complete fittings and replace damage parts, transfer all fittings to new door.	-	80.00
8	To apply undersealing.	-	30.00
9	To remove, cut out damage portion, jack out, straighten, panel beating, welding, align and renew replaced parts.	-	1,000.00
10	To putty and respray painting on affected areas.	-	900.00
	Labour Total :	-	2,170.00
	TOTAL (PARTS & LABOUR) :	-	10,097.92

The final adjusted Lump Sum contract amount is **\$8,050.00**
(SINGAPORE DOLLARS EIGHT THOUSAND AND FIFTY ONLY)



Frankie Pang
 AMSAE(AUST), AMIRTE, AMSOE,
 MASPACI, MSAAA
 Licensed Appraiser



Ong Chung Yang
 Automobile Appraiser