

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG21006043/AGS3Q2
Date: 03/01/2022**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7210040225
Claimant Vehicle No :	GBJ5730S	Insured Vehicle No :	SKH1675Z
Date of Loss:	21/05/2021	Nature of Claim:	TP
		Claim No:	4404070914SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBJ5730S		
Make & Model:	TOYOTA DYNA, 3.0 D (M)	Engine No:	1KD2842482
Reg. Date:	31/05/2019 (Man. Year: 2018)	Chassis No:	KDY2318037139
Colour:	Silver	Odometer:	91186 km
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195 R15C	Rear Tyre Size:	165 R13C
Front Left Side:	Maxmiler 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Maxmiler 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,982.92	4,141.52	1,841.40	30.78
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,500.00	1,740.00	760.00	30.40
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,482.92	5,881.52	2,601.40	30.67
Approved Total (Overridden) (S\$)		4,600.00		

(S\$)	8,482.92	4,600.00	3,882.92	45.77
+ GST 7.00/7.00% (S\$)	593.80	322.00	271.80	45.77
Nett Amount (S\$)	9,076.72	4,922.00	4,154.72	45.77
+ Loss of Use (10.0 x S\$90.00/day) (S\$)		900.00		
+ Doc/Search Fee (S\$)		43.90		
Nett Liability (S\$)		5,865.90		
Global Sum Settlement (S\$)		5,850.00		

INSPECTION

Date of Assignment: 21/05/2021

Date Inspected: 21/05/2021

Inspected At:

Ryder Auto Pte Ltd (HQ)
 2 Kaki Bukit Ave 2, #02-19 AutoHub @ Kaki Bukit
 Singapore 417921

Estimated Period of Repair: 6.0 days

Adjuster: ADRIAN LING**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAIL-GATE	Dented	1,584.50 FL	*1,584.50 FL
2	2		*REAR TAIL-GATE O/S & N/S LOCK	Bent	80.00 FL	*80.00 FL
3	2		*REAR TAIL-GATE O/S & N/S LOCK HANDLE	Not Necessary	97.80 FL	*- FL
4	4		*REAR TAIL-GATE HINGES	Bent	60.00 FL	*60.00 FL
5	4		*REAR TAIL-GATE HINGES PINS	Not Necessary	20.00 FL	*- FL
6	1		*REAR TAIL-GATE END PANEL	Dented	455.20 FL	*455.20 FL
7	2		*REAR TAIL-GATE O/S & N/S RUBBER STOPPER	Cut	40.00 FL	*40.00 FL
8	2		*REAR TAIL-GATE O/S & N/S RUBBER STOPPER BRACKET	Bent	180.00 FL	*180.00 FL
9	2		*REAR O/S & N/S TAIL-LAMP	Cracked	540.00 FL	*540.00 FL
10	1		*REAR O/S & N/S TAIL-LAMP PANEL	Dented	220.00 FL	*220.00 FL
11	1		*EXHAUST	Dented	965.00 FL	*585.00 FL
12	4		*REAR EXHAUST PIPE MOUNTING	Torn	24.00 FL	*24.00 FL
13	1		*REAR EXHAUST PIPE (CENTRE)	Not Necessary	798.60 FL	*- FL
14	1		*REAR REG NO.PLATE BRACKET	Bent	120.00 FL	*120.00 FL
15	1		*REAR SPARE WHEEL BRACKET	Not Necessary	798.80 FL	*- FL
16	1		*REAR TAIL-GATE 70KM/H STICKER	Necessary	20.00 FS	*10.00 FS
17	1		*REAR TAIL-GATE 6 PAX STICKER	Necessary	20.00 FS	*10.00 FS
18	1		*REAR 1250KG STICKER	Necessary	10.00 FS	*10.00 FS
19	1		*REAR DYNA STICKER	Necessary	30.00 FS	*30.00 FS
20	1		*REAR TOYOTA STICKER	Necessary	110.00 FS	*110.00 FS
21	2		*REAR TAIL-GATE END PANEL O/S & N/S REFLECTOR	Cracked	40.00 FS	*40.00 FS
22	1		*REAR TAIL-GATE STEP	Bent	200.00 FS	*150.00 FS
23	2		*REAR O/S & N/S TAIL-LAMP REFLECTOR	Cracked	100.00 FS	*100.00 FS
24	20		*RIVETS	Necessary	20.00 FS	*20.00 FS
25	1		*REAR REGN NO.PLATE	Bent	35.00 FS	*35.00 FS
26	1		*REAR REGN NO.PLATE GARNISH	Deformed	30.00 FS	*30.00 FS
27	1		*REAR N/S BOX (+BRACKET)	Distorted	600.00 FS	*480.00 FS
28	1		*REAR REVERSE SENSOR	Damaged	280.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	7,478.90	5,113.70
- List Item Discount on L Items 25.00/25.00% (\$\$)	1,495.98	972.18
Total Parts (\$\$)	5,982.92	4,141.52

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO DISMANTLE REAR PORTION ,STRAIGHTEN ,CUTTING & WELDING	New	1,200.00	800.00
2	TO SPRAY PAINTING	New	800.00	700.00
3	TO REMOVE AND REFIT REAR FLOOR ALUMINIUM TO FACILITATE REPAIR	New	140.00	0.00
4	TO REMOVE & REPLACE EXHAUST	New	120.00	80.00
5	TO REMOVE & REPLACE REAR N/S BOX	New	80.00	60.00
6	TO CHECK WIRING	New	80.00	30.00
7	TO RE-SEAL ANTI-RUST	New	80.00	70.00
Gross Labour Cost (S\$)			2,500.00	1,740.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >