

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way, #09-16  
Singapore 079120

**Our File No:** CS/AIG21006046/EVF3E2

**Date:** 13/08/2021

### REFERENCE

Insured/Claimant: PECK SENG CRANE & TRANSPORT PTE LTD Policy No: 1700013443  
Date of Loss: 19/05/2021 Nature of Claim: OD Claim No: 2214784030SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBG9090U**  
Make & Model: CITROEN BERLINGO, 1.5 D BLUEHDI EAT8 (M) Engine No: 10JBHW3004328  
Reg. Date: 07/06/2017 (Man. Year: 2016) Chassis No: VF77FBHYMGJ767992  
Colour: Grey Odometer: 123724 km  
Engine Capacity: 1560 cc  
Market Value/New Car Price: S\$42,000.00  
Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15  
Front Left Side: Continental 4 mm Rear Left Side: Continental 4 mm  
Front Right Side: Continental 4 mm Rear Right Side: Continental 4 mm

*The above values represent the remaining tyre treads depth*

| COST OF CLAIMS                      | Repairer's      | Adjuster's      | Difference      | Diff %       |
|-------------------------------------|-----------------|-----------------|-----------------|--------------|
| Parts                               | 4,825.60        | 3,942.80        | 882.80          | 18.29        |
| Miscellaneous Items                 | 0.00            | 0.00            | 0.00            |              |
| Labour                              | 2,360.00        | 1,735.00        | 625.00          | 26.48        |
| Paintwork Labour                    | 0.00            | 0.00            | 0.00            |              |
| Towing                              | 0.00            | 0.00            | 0.00            |              |
| <b>Calculated Gross Total (S\$)</b> | <b>7,185.60</b> | <b>5,677.80</b> | <b>1,507.80</b> | <b>20.98</b> |
| <b>- Excess (S\$)</b>               | <b>800.00</b>   | <b>800.00</b>   | <b>0.00</b>     | <b>0.00</b>  |
| <b>(S\$)</b>                        | <b>6,385.60</b> | <b>4,877.80</b> | <b>1,507.80</b> | <b>23.61</b> |
| <b>+ GST 7.00/7.00% (S\$)</b>       | <b>446.99</b>   | <b>341.45</b>   | <b>105.54</b>   | <b>23.61</b> |
| <b>Nett Amount (S\$)</b>            | <b>6,832.59</b> | <b>5,219.25</b> | <b>1,613.34</b> | <b>23.61</b> |

### INSPECTION

Date of Assignment: 21/05/2021

Date Inspected: 21/05/2021 Inspected At:

Cycle & Carriage France Pte Ltd (Pandan Gardens) (HQ)  
209 PANDAN GARDENS  
Singapore 609339

Estimated Period of Repair: 3.0 days

**Adjuster:** CHEN TSUE YEE

**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

| No. | Qty | Part No. | Particulars                         | Condition     | Repairer's                                               | Amount                        |
|-----|-----|----------|-------------------------------------|---------------|----------------------------------------------------------|-------------------------------|
| 1   | 1   |          | *FRT NUMBER PLATE WITH FRAME        | Cut           | 50.00 FS                                                 | *50.00 FS                     |
| 2   | 1   |          | *SUNDRIES                           | Necessary     | 50.00 FS                                                 | *20.00 FS                     |
| 3   | 1   |          | *FRONT BUMPER                       | Broken        | 1,039.00 FL                                              | *1,039.00 FL                  |
| 4   | 1   |          | *BUMPER BRACKET SUP                 | Bent          | 507.00 FL                                                | *507.00 FL                    |
| 5   | 1   |          | *GUARD GRILLE SUPERIEUR             | Broken        | 302.00 FL                                                | *302.00 FL                    |
| 6   | 1   |          | *SET BRACKET                        | Not Necessary | 74.00 FL                                                 | *- FL                         |
| 7   | 1   |          | *BUMPER BRACKET                     | Broken        | 256.00 FL                                                | *256.00 FL                    |
| 8   | 1   |          | *BADGE                              | Broken        | 260.00 FL                                                | *260.00 FL                    |
| 9   | 1   |          | *GUARD GRILLE INFERIEUR             | Broken        | 401.00 FL                                                | *401.00 FL                    |
| 10  | 1   |          | *FIXING SPACER                      | Broken        | 107.00 FL                                                | *107.00 FL                    |
| 11  | 1   |          | *GRILLE MOULDING                    | Not Necessary | 168.00 FL                                                | *- FL                         |
| 12  | 1   |          | *BUMPER ABSORBER INF                | Not Necessary | 230.00 FL                                                | *- FL                         |
| 13  | 1   |          | *GRILLE MOULDING SUPERIEUR          | Not Necessary | 168.00 FL                                                | *- FL                         |
| 14  | 1   |          | *BUMPER MOULDING                    | Cut           | 241.00 FL                                                | *241.00 FL                    |
| 15  | 2   |          | *SET SUPPORTS                       | Cut           | 224.00 FL                                                | *224.00 FL                    |
| 16  | 1   |          | *BMPR RUBBR BOOT                    | Not Necessary | 299.00 FL                                                | *- FL                         |
| 17  | 1   |          | *BUMPR DEFLECTOR                    | Not Necessary | 127.00 FL                                                | *- FL                         |
| 18  | 1   |          | *AIR BULKHEAD LH                    | Broken        | 92.00 FL                                                 | *92.00 FL                     |
| 19  | 1   |          | *AIR BULKHEAD RH                    | Broken        | 92.00 FL                                                 | *92.00 FL                     |
| 20  | 2   |          | *SCREW CBLX RDL DIAM 4.5-20         | Necessary     | 4.00 FL                                                  | *4.00 FL                      |
| 21  | 1   |          | *FOG HEADLIGHT                      | Broken        | 124.00 FL                                                | *124.00 FL                    |
| 22  | 1   |          | *DETECTION LOOM                     | Torn          | 323.00 FL                                                | *323.00 FL                    |
| 23  | 1   |          | *HORN                               | Broken        | 112.00 FL                                                | *112.00 FL                    |
| 24  | 1   |          | *FRAME FACE<br>(Supplementary)      | Broken        | 325.00 FL                                                | *325.00 FL                    |
| 25  | 1   |          | *MOTOR-DRIVN FAN<br>(Supplementary) | Broken        | 432.00 FL                                                | *432.00 FL                    |
|     |     |          |                                     |               | <b>Sub Total (\$)</b>                                    | <b>6,007.00      4,911.00</b> |
|     |     |          |                                     |               | <b>- List Item Discount on L Items 20.00/20.00% (\$)</b> | <b>1,181.40      968.20</b>   |
|     |     |          |                                     |               | <b>Total Parts (\$)</b>                                  | <b>4,825.60      3,942.80</b> |

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                            | Particulars                                                                | Lab.Type | Repairer's      | Amount          |
|-------------------------------|----------------------------------------------------------------------------|----------|-----------------|-----------------|
| <b>Labour Items</b>           |                                                                            |          |                 |                 |
| 1                             | RENEW FRT BUMPER & AFFECTED AREAS                                          | New      | 1,000.00        | 500.00          |
| 2                             | SPRAY PAINT WORK ON FRT BUMPER                                             | New      | 380.00          | 380.00          |
| 3                             | TO REMOVE AND INSTALL PROXIMITY SENSOR TO FACILITATE REPAIR                | New      | 80.00           | 80.00           |
| 4                             | CHECK ON WIRING & CHASSIS ELECTRICAL SYSTEM                                | New      | 120.00          | 50.00           |
| 5                             | TO CARRY OUT DIAGNOSTIC CHEC USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST | New      | 280.00          | 225.00          |
| 6                             | LABOUR TO REMOVE FRAME FACE<br>(Supplementary)                             | New      | 500.00          | 500.00          |
| <b>Gross Labour Cost (\$)</b> |                                                                            |          | <b>2,360.00</b> | <b>1,735.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >