

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933
Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/MSG21006048/UVF3N2
Date: 07/06/2021

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	30001622721
Claimant Vehicle No :	PA6860A	Insured Vehicle No :	SLQ2114K
Date of Loss:	21/05/2021	Nature of Claim:	TP
		Claim No:	257875

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	PA6860A	Engine No:	6HK1450858
Make & Model:	ISUZU LT134P, 7.8 D (A)	Chassis No:	JALLT134P77000082
Reg. Date:	12/06/2007 (Man. Year: 2007)	Odometer:	480595 km
Colour:	Multi-colour		
Engine Capacity:	7790 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	275/80 R22.5	Rear Tyre Size:	275/80 R22.5(D)
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6/6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6/6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	26,150.00	5,323.50	20,826.50	79.64
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,950.00	2,270.00	3,680.00	61.85
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	32,100.00	7,593.50	24,506.50	76.34
Approved Total (Overridden) (S\$)		6,050.00		
(S\$)	32,100.00	6,050.00	26,050.00	81.15
+ GST 7.00/7.00% (S\$)	2,247.00	423.50	1,823.50	81.15
Nett Amount (S\$)	34,347.00	6,473.50	27,873.50	81.15

INSPECTION

Date of Assignment:	25/05/2021		
Date Inspected:	21/05/2021	Inspected At:	Fastech Auto Pte Ltd (HQ) 1 Kaki Bukit Ave 6, #01-46/48/50 Autobay Singapore 417883
Estimated Period of Repair:	4.0 days		

Adjuster: MARCUS CHUA

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 07 Jun 2021)	
Parts:	N/A	ISUZU LT134P 7.8 D (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	LKK Auto Consultants Pte Ltd/PA6860A/07/06/2021 15:36	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER DOME	Cracked	4,850.00 F	*2,050.00 FL
2	1		*FRONT SIGNAL LAMP N/S	Scratched	265.00 F	*185.00 FL
3	1		*FRONT SIDE LAMP N/S	Not Necessary	250.00 F	*- FL
4	1		*HEADLAMP N/S	Not Necessary	980.00 F	*- FL
5	1		*FRONT DOOR N/S	Dented/Warped	4,580.00 F	*3,280.00 FL
6	1		*FRONT DOOR RUBBER N/S (FRT)	Torn	650.00 F	*200.00 FL
			}			
7	1		*FRONT DOOR RUBBER N/S (REAR)	Cut	650.00 F	*- FL
			}			
8	1		*FRONT DOOR PILLAR ALUMINIUM PLATE N/S (FRT)	Distorted	800.00 F	*200.00 FL
9	1		*FRONT DOOR PILLAR ALUMINIUM PLATE N/S (REAR)	Repair	800.00 F	*- FL
10	1		*FRONT DOOR PUMP ASST N/S	Serviceable	2,500.00 F	*- FL
11	1		*FRONT DOOR OPENING LEVEL N/S	Not Necessary	625.00 F	*- FL
12	1		*REAR COMPARTMENT DOOR N/S (CRACKED)	Not Consistent With The Impact	4,650.00 F	*- FL
13	1		*REAR COMPARTMENT DOOR NO 2 N/S	Not Necessary	4,550.00 F	*- FL
						F=Franchise part. L=ListItemDisc.
					Sub Total (S\$)	26,150.00 5,915.00
					- List Item Discount on L Items 0.00/10.00% (S\$)	0.00 591.50
					Total Parts (S\$)	26,150.00 5,323.50

LKK Auto Consultants Pte Ltd/PA6860A/07/06/2021 15:36. Not valid without Reference section.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING	New	50.00	20.00
2	TO SPRAY RUST PROOFING	New	100.00	0.00
3	LABOUR FOR PANEL BEATING & REPLACED PARTS	New	2,800.00	1,400.00
4	TO PUTTY & SPRAY PAINTING	New	3,000.00	850.00
Gross Labour Cost (\$\$)			5,950.00	2,270.00

LKK Auto Consultants Pte Ltd/PA6860A/07/06/2021 15:36. Not valid without Reference section.

< END OF ESTIMATES >