

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/AIG21004744/R1EA3Q2-1
Date: 30/07/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900090667
Claimant Vehicle No :	PA6515Y	Insured Vehicle No :	SMK9100Z
Date of Loss:	09/04/2021	Nature of Claim:	TP
		Claim No:	8340999192SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	PA6515Y		
Make & Model:	ISUZU LT133L, 8.2 D (M)	Engine No:	6HH1416874
Reg. Date:	27/09/2006 (Man. Year: 2006)	Chassis No:	JALLT133P67000047
Colour:	Multi-colour	Odometer:	586537 km
Engine Capacity:	8226 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	11R22.5	Rear Tyre Size:	11R22.5(D)
Front Left Side:	FRONWAY 8 mm	Rear Left Side:	FRONWAY 8/8 mm
Front Right Side:	FRONWAY 8 mm	Rear Right Side:	FRONWAY 8/8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	480.00	400.00	80.00	16.67
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	480.00	400.00	80.00	16.67
+ GST 7.00/7.00% (S\$)	33.60	28.00	5.60	16.67

Nett Amount (\$)	513.60	428.00	85.60	16.67
Global Sum Settlement (\$)		0.00		

INSPECTION

Date of Assignment: 14/04/2021

Date Inspected: 15/04/2021

Estimated Period of Repair: 2.0 days

Inspected At:

Woodlands Transport Service Pte Ltd (HQ)
8 Gul Circle
Singapore 629564**Adjuster:** MOHD RASUL**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO PUTTY AND SPRAY PAINTING AT LHS DOOR PANEL AND LHS CORNER PANEL	New	480.00	400.00
Gross Labour Cost (S\$)			480.00	400.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >