

ASS. P. BY: Taylor

ASSIGNMENT

From: _____

Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: 466K

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: GBL2242T

Yr Regn: 2021 April

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Nissan Cabstar

1998

Colour: Silver

A/C: Insured / Std / NI / NA

Sp. Reading _____

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: _____

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: No / S/Rim / STD A/Rim or

Tyre Size: F: 175/80R15

R: 155R13

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 6 mm

L/Bal. 6 mm

D.O.A. _____

Rear

R/Bal. 6/6 mm

L/Bal. 6/6 mm

D.O.I. 24/5/21 @ 1pm

Survey held at Kuan Kian Motor

Des. of Damages: FR / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure effected due to collision.

Date / Time

Action / Instruction

Battery weak.

**lump sum \$18000, 14days
(red: 15720.9446%)**

Date/Time, File Pass to?



Prel. Report

1)



Final Report

Date/Time, File Return to?

2)

Days Of Repair: 14

Resurvey No. of Trip: _____

Add Fee:



Site Insp (\$ _____)



Interview (\$ _____)



Tech. Insp (\$ _____)



Other (\$ _____)

Survey cost:

Transportation:

S + R \$ _____

Photos

Other

Total

Report Forward:

Large Sheet / 100mm

Hua Kian Motor Workshop

1 Kaki Bukit Avenue 6 #02-37 Autobay @ Kaki Bukit S(417883)

Tel: 6842 5949 Fax: 6509 8396 Mobile: 96618769

21 May 2021

GBL2242T NISSAN CABSTAR – REPAIR ESTIMATE

PARTS –

		\$	Less	\$
Front windscreen glass	1	991.00	10%	891.90 <i>can</i>
Front windscreen moulding	1	205.00	10%	184.50 <i>nei</i>
Front windscreen sealant	1	80.00	0%	80.00 <i>nei</i>
ERP unit bracket	1	26.00	0%	26.00 <i>nei</i>
Front panel	1	1,412.70	10%	1,271.43 <i>bt</i>
Front panel CABSTAR emblem	1	35.30	10%	31.77 <i>nei</i>
Front grille	1	578.60	10%	520.74 <i>mis</i>
Front grille logo	1	48.10	10%	43.29 <i>nei</i>
Front bumper	1	945.10	10%	850.59 <i>dis</i>
Front bumper bracket LH/RH	2	183.00	10%	164.70 <i>RHX LHbt</i>
Front bumper clip	10	50.00	0%	50.00 <i>nei - 50</i>
LHS fog lamp cover	1	28.60	10%	25.74 <i>X</i>
LHS headlamp assy	1	473.40	10%	426.06 <i>can</i>
RHS headlamp assy	1	473.40	10%	426.06 <i>X un</i>
LHS headlamp base panel	1	225.10	10%	202.59 <i>bt</i>
LHS headlamp lower garnish	1	28.60	10%	25.74 <i>mis</i>
Front LH door	1	1,396.50	10%	1,256.85 <i>buc</i>
Front LH door hinge	2	122.20	10%	109.98 <i>bt</i>
Front LH door check	1	39.50	10%	35.55 <i>bt</i>
Front LH door glass	1	760.10	10%	684.09 <i>can</i>
Front LH door glass outer moulding	1	136.20	10%	122.58 <i>de</i>
Front LH door glass inner moulding	1	128.60	10%	115.74 <i>de</i>
Front LH door trim board	1	722.50	10%	650.25 <i>de</i>
Front LH door trim board clip	10	85.00	10%	76.50 <i>nei</i>
Front LH door lock	1	190.60	10%	171.54 <i>bt</i>
Front LH door lock striker	1	23.50	10%	21.15 <i>bt</i>
Front LH door outer handle	1	100.10	10%	90.09 <i>X un</i>
Front LH door weatherstrip	1	151.10	10%	135.99 <i>cut</i>
Front LH ¼ garnish	1	55.30	10%	49.77 <i>mis</i>
Front LH door arc seal	1	85.10	10%	76.59 <i>nei</i>
Front LH wing mirror	1	171.70	10%	154.53 <i>buc</i>
Front LH wing mirror arm	1	191.90	10%	172.71 <i>buc</i>
Front LH wing mirror base cover	1	111.30	10%	100.17 <i>mis</i>
Front LH corner panel	1	389.90	10%	350.91 <i>mis</i>
Front LH corner panel clip	2	7.00	0%	7.00 <i>nei</i>
Front LH door company registration sticker	1	35.00	0%	35.00 <i>nei</i>
Wiper panel outer cover	1	494.60	10%	445.14 <i>bt</i>
Front LH door "A" pillar assy	1	1,646.40	10%	1,481.76 <i>buc</i>
Front LH door "A" pillar inner top cover	1	114.70	10%	103.23 <i>de</i>
Front LH door indicator lamp assy	1	57.10	10%	51.39 <i>mis</i>
Front LH door rear quarter panel	1	589.60	10%	530.64 <i>bt</i>
Front LH door glass run rubber – top	1	185.20	10%	166.68 <i>nei</i>
Front LH door glass run rubber – front	1	48.90	10%	44.01 <i>nei</i>
Front LH door glass run rubber – rear	1	59.10	10%	53.19 <i>nei</i>
Front LH door glass regulator	1	112.00	10%	100.80 <i>bt</i>
Front LH door power window motor	1	524.40	10%	471.96 <i>bt</i>
Front LH step board	1	139.40	10%	125.46 <i>can</i>
Front LH wheelhouse panel	1	485.60	10%	437.04 <i>buc</i>
Front LH wheelhouse panel top cover	1	114.70	10%	103.23 <i>can</i>

GBL2242T NISSAN CABSTAR - REPAIR ESTIMATE

Page 2/2

Front dashboard assy	1	1,329.00	10%	1,196.10
Front dashboard underside support bar	1	869.60	10%	782.64
Front dashboard underside support bar stay LH	1	221.60	10%	199.44
Glove box lid	1	195.20	10%	175.68
Glove box	1	215.80	10%	194.22
Wiring harness set	1	1,501.00	10%	1,350.90
Fuse box assy	1	850.00	0%	850.00
ECU	1	4,500.00	0%	4,500.00
Immobilization unit	1	1,000.00	0%	1,000.00
Wiper washer reservoir	1	206.00	10%	185.40
Aircon blower unit	1	950.10	10%	855.09
Aircon evaporator unit	1	1,041.10	10%	936.99
Body logo sticker set	1	300.00	0%	300.00
Front RH door assy	1	1,396.50	10%	1,256.85
Front RH door company registration sticker	1	35.00	0%	35.00
Subtotal:				27,570.94

LABOUR

To check wiring and lightings.

40.00 30

To renew ECU, fuse box and wiring harness and conduct diagnostic test to reset all electrical systems.

500.00 200? photo

To conduct computerised wheel alignment to check and align wheels.

X
90.00

Labour charges to repair and replace damaged parts and areas.

3,000.00 1800

Spray painting charges to spray paint all affected parts and areas.

1,500.00 1400

To remove and refit aircon evaporator and blower units and affected piping/hoses to facilitate the necessary repairs.

200.00 120

To remove and replace front windscreen glass.

120.00 ✓

To remove and replace front dashboard and related parts.

300.00 100

Towing fee.

100.00 60

To remove and refit passenger seat, floor mat, interior trims and upholstery to facilitate the replacement of the front door rear quarter panel and wheelhouse panel.

300.00 100? photo

Subtotal 2

Total amount

6,150.00

33,720.94

Hua Kian Motor Workshop

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Tanpoh 17415749 16256356
 WP' 24/5/210 1230
 1/3 Resurvey after repair
 Tanpoh & Lukman
 14 days.