

ASS. REC. BY:

REF:

C72/ 21006035/ke

C

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s Trans Cab

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 02 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: S1TD 432X Yr Regn: 04, 17

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Renault Latitude c.c. 1995Colour M. White / Red A/C: Insured / Std / NI / NASp. Reading 311679 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: VIFIABL 15AUC 28 3337Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModl: NI / S/Rim / STD A/Rim orTyre Size: F: 215/60R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or Pirelli

Front

R/Bal. 9 mmL/Bal. 9 mmD.O.A. 18/5/21

Survey held at _____

Rear

R/Bal. 7 mmL/Bal. 7 mmD.O.I. 20/5/2021Des. of Damages: Frt Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

1 Got BZ

2415 11 Lp @ 2150h Corbu

Date/Time, File Pass to?

☐ : Prell. Report

Days Of Repair: _____

1)

☐ : Final Report

Resurvey No. of Trip: _____

Date/Time, File Return to?

2)

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech Invs (\$☐ : Weekend (\$

Survey Fee:

Transportation:

S + RS. \$

Fixtures

Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$) _____

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD432X**AAD2105-***Not Authorized
C/Rep 82150h*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

20 MAY 2021**SHD432X**

VF1ABL15AUC283337

RENAULT

LATITUDE

18/05/2021

CHINA

12/04/2017

PART

- 1 BUMPER COVER REAR
- 1 BUMPER LOWER REAR
- 1 BUMPER BRACKET CTR REAR
- 1 BUMPER BRACKET SIDE RH REAR
- 1 BUMPER RETAINER RH REAR
- 1 BUMPER BRACKET SIDE LH REAR
- 1 BUMPER RETAINER LH REAR
- 1 BUMPER BEAM REAR
- 1 BUMPER BEAM BRACKET LH REAR
- 1 BUMPER BEAM BRACKET RH REAR

LIST	
\$ <i>Dd / um</i>	561.70 ✓
\$ <i>Dd / um</i>	411.90 ✓
\$ <i>sn</i>	98.10 X
\$ <i>sn</i>	82.10 X
\$ <i>sn</i>	59.80 X
\$ <i>sn</i>	80.80 X
\$ <i>sn</i>	54.20 X
\$ <i>R</i>	547.80 ✓
\$ <i>R</i>	114.50 X
\$ <i>R</i>	114.50 X
\$	2,125.40
10% \$	212.54
\$	1,912.86

Specical Nett

- 1SET PARKING AID
- 1SET REAR BUMPER CLIP
- 1SET BUMPER BRACKET CTR CLIP
- 1SET BUMPER BRACKET SIDE CLIP RH RR
- 1SET BUMPER RETAINER RH CLIP RR
- 1SET BUMPER BRACKET SIDE CLIP LH RR
- 1SET BUMPER RETAINER CLIP LH RR
- 1SET BUMPER LOWER REAR CLIP

\$ <i>short</i>	700.00 <i>800.00</i>
\$ <i>sn</i>	66.00 ✓
\$ <i>na</i>	33.00 X
\$ <i>na</i>	10.00 X
\$ <i>na</i>	20.00 X
\$ <i>na</i>	10.00 X
\$ <i>na</i>	20.00 X
\$ <i>na</i>	66.00 ✓
TOTAL \$	925.00
TOTAL PARTS \$	2,837.86

LABOUR

Trans-cab Auto Services Pte Ltd**AAD2105-**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD432X

Putty And Spray Painting Of The Affected Portion.	\$	3,000.00	4401
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	3,000.00	3001
To Rust-Proofing Of The Affected Areas.	\$	nn 170.00	X
To reinstall rear bumper parking sensor.	\$	170.00	601
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	nn 170.00	X
To repair and realign rear exhaust pipe.	\$	4 170.00	X
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	4 170.00	X
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	4 170.00	X
To transfer of rear windscreen fittings and conduct water seepage test.	\$	4 170.00	X
To check steering geometry and computer wheel alignment	\$	4 220.00	X
To Check Electrical Lighting Concerned.	\$	170.00	151

TOTAL \$ 7,580.00**Over All Total \$ 12,330.72****(LUMP SUM)****Repair Days****20 DAYS**

2 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: