

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21006059/KPA3Q2
Date: 15/12/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800142574
Claimant Vehicle No :	SMZ1535B	Insured Vehicle No :	SKT1933R
Date of Loss:	14/05/2021	Nature of Claim:	TP
		Claim No:	2940273368SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMZ1535B		
Make & Model:	MERCEDES-BENZ E250, 1.8 (A)	Engine No:	27186030454101
Reg. Date:	19/10/2012 (Man. Year: 2012)	Chassis No:	WDD2120472A603679
Colour:	Metallic Grey	Odometer:	78310 km
Engine Capacity:	1796 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	245/40 R18	Rear Tyre Size:	265/35 R18
Front Left Side:	Goodyear 8 mm	Rear Left Side:	Goodyear 8 mm
Front Right Side:	Goodyear 8 mm	Rear Right Side:	Goodyear 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,219.32	1,989.57	1,229.75	38.20
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,240.00	500.00	740.00	59.68
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,459.32	2,489.57	1,969.75	44.17
Approved Total (Overridden) (S\$)		1,950.00		

(S\$)	4,459.32	1,950.00	2,509.32	56.27
+ GST 7.00/7.00% (S\$)	312.15	136.50	175.65	56.27
Nett Amount (S\$)	4,771.47	2,086.50	2,684.97	56.27
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment: 20/05/2021

Date Inspected: 21/05/2021

Estimated Period of Repair: 2.0 days

Inspected At:

Ricardo Auto Centre Pte Ltd (HQ)
 160 Sin Ming Drive, #02-02, Sin Ming AutoCity
 Singapore 575722

Adjuster: KENNETH KONG**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Buckled / Cracked	1,716.12 F	*1,716.12 FL
2	2		*REAR BUMPER SIDE MOULDING LH & RH	Necessary	277.66 F	*277.66 FL
3	1		*REAR BUMPER CENTRE MOULDING	Necessary	186.85 F	*186.85 FL
4	1		*REAR BUMPER REINFORCEMENT	*Check	922.37 F	*- FL
5	2		*REAR BUMPER SIDE RETAINER LH & RH	Serviceable	86.32 F	*- FL
6	1		*REAR BUMPER CLIPS	Necessary	30.00 F	*30.00 FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$)**3,219.32****2,210.63****- List Item Discount on L Items 0.00/10.00% (\$)**

0.00

221.06

Total Parts (\$)**3,219.32****1,989.57**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO TUFF COAT REPAIRED AREA	New	60.00	0.00
2	TO CUT ,WELD & STRAIGHTEN REAR PORTION OF CAR CAUSED BY ACCIDENT ,ADJUST & REPLACE DAMAGE PARTS	New	500.00	250.00
3	TO SPRAY PAINT ON REPAIRED AREAS	New	500.00	250.00
4	TO CODING & PROGRAMMING REAR BUMPER SENSOR SYSTEM (*Check)	New	180.00	0.00
Gross Labour Cost (S\$)			1,240.00	500.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >