

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way, #09-16  
Singapore 079120

**Our File No:** CC3/AIG21006060/AQCE2

**Date:** 06/09/2021

### REFERENCE

Insured/Claimant:	TAN TECK LENG	Policy No:	1700033517-03	
Date of Loss:	15/05/2021	Nature of Claim:	OD	Claim No: 9213501505SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLR227B		
Make & Model:	AUDI A4, 1.4 TFSI S TRONIC (A)	Engine No:	CVN039073
Reg. Date:	28/07/2017 (Man. Year: 2017)	Chassis No:	WAUZZZF48HA165499
Colour:	Black	Odometer:	55682 km
Engine Capacity:	1395 cc		
Market Value/New Car Price:	S\$98,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,591.00	2,404.56	4,186.44	63.52
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,722.00	1,242.00	2,480.00	66.63
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>10,313.00</b>	<b>3,646.56</b>	<b>6,666.44</b>	<b>64.64</b>
<b>- Excess (S\$)</b>	<b>600.00</b>	<b>600.00</b>	<b>0.00</b>	<b>0.00</b>
<b>(S\$)</b>	<b>9,713.00</b>	<b>3,046.56</b>	<b>6,666.44</b>	<b>68.63</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>679.91</b>	<b>213.26</b>	<b>466.65</b>	<b>68.63</b>
<b>Nett Amount (S\$)</b>	<b>10,392.91</b>	<b>3,259.82</b>	<b>7,133.09</b>	<b>68.63</b>

### INSPECTION

Date of Assignment:	24/05/2021		
Date Inspected:	21/05/2021	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	3.0 days		

**Adjuster:** ADRIAN LING

**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Distorted	2,111.00 FS	*1,688.80 FS
2	1		*FRONT BUMPER FIXING PARTS (NPA)	Not Necessary	0.00 FS	*- FS
3	2		*FRONT BUMPER SECURING STRIP	Not Necessary	71.00 FS	*- FS
4	1		*FRONT BUMPER LOWER SATIN GRILLE CENTRE	Not Necessary	196.00 FS	*- FS
5	1		*FRONT BUMPER CLOSING ELEMENT LOWER CENTRE	Cracked	210.00 FS	*167.60 FS
6	1		*FRONT BUMPER AIR GUIDE RH	Not Necessary	63.00 FS	*- FS
7	1		*FRONT RADIATOR GRILLE	Not Necessary	1,152.00 FS	*- FS
8	1		*FRONT BUMPER AIR GUIDE GRILLE RH	Cracked	135.00 FS	*108.00 FS
9	1		*FRONT BUMPER FOAM	Cracked	124.00 FS	*99.20 FS
10	1		*FRONT BUMPER REINFORCEMENT BEAM	Not Necessary	846.00 FS	*- FS
11	1		*FRONT BUMPER TOP COVER	Not Necessary	127.00 FS	*- FS
12	1		*FRONT BUMPER GUIDE SECTION RH	Damaged	38.00 FS	*29.84 FS
13	1		*CAUTION SIGN	Not Necessary	14.00 FS	*- FS
14	1		*AIRCON STICKER	Not Necessary	8.00 FS	*- FS
15	1		*FRONT BUMPER LOCK CARRIER BRACKET	Not Necessary	138.00 FS	*- FS
16	2		*FRONT BUMPER SUPPORT LH / RH	Not Necessary	58.00 FS	*- FS
17	1		*WHEEL HOUSING LINER RH	Torn	241.00 FS	*192.80 FS
18	1		*WHEEL HOUSING LINERS ATTACHEMENTS PARTS (NPA)	Not Necessary	0.00 FS	*- FS
19	1		*WHEEL SPOILER RH	Cracked	36.00 FS	*28.56 FS
20	1		*WHEEL SPOILER TRIM RH	Cracked	73.00 FS	*58.40 FS
21	1		*AIR GUIDE COVER INNER RH	Not Necessary	28.00 FS	*- FS
22	1		*AIR GUIDE COVER OUTER RH	Not Necessary	12.00 FS	*- FS
23	1		*AIR GUIDE	Not Necessary	16.00 FS	*- FS
24	1		*AIR GUIDE COVER LOWER	Not Necessary	22.00 FS	*- FS
25	1		*NOISE INSULATION	Not Necessary	572.00 FS	*- FS
26	1		*SUNDRIES	Necessary	300.00 FS	*31.36 FS

F=Franchise part. S=SpcNett.

Total Parts (S\$) 6,591.00 2,404.56

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	0.00
2	TO DISMANTLE AND RENEW FRONT BUMPER. REORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	1,050.00	500.00
3	TO RESPRAY FRONT BUMPER AND RHS FRONT FENDER	New	2,000.00	550.00
4	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
<b>Gross Labour Cost (\$\$)</b>			<b>3,722.00</b>	<b>1,242.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >