

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way, #09-16  
Singapore 079120

**Our File No:** CC3/AIG21006061/ATCE2

**Date:** 11/10/2021

### REFERENCE

Insured/Claimant:	NEO CHIAU YEN	Policy No:	2070032096		
Date of Loss:	02/05/2021	Nature of Claim:	OD	Claim No:	1697386803SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMS6684H		
Make & Model:	AUDI A1 SPORTBACK, 1.0 TFSI S-tronic (A)	Engine No:	DKJ048538
Reg. Date:	09/03/2020 (Man. Year: 2019)	Chassis No:	WAUZZZGB0LR023798
Colour:	Yellow	Odometer:	20692 km
Engine Capacity:	999 cc		
Market Value/New Car Price:	S\$115,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	195/55 R16	Rear Tyre Size:	195/55 R16
Front Left Side:	Hankook 6 mm	Rear Left Side:	Hankook 6 mm
Front Right Side:	Hankook 6 mm	Rear Right Side:	Hankook 6 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	15,685.00	9,844.56	5,840.44	37.24
Miscellaneous Items	0.00	0.00	0.00	
Labour	10,202.00	7,172.00	3,030.00	29.70
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>25,887.00</b>	<b>17,016.56</b>	<b>8,870.44</b>	<b>34.27</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>1,812.09</b>	<b>1,191.16</b>	<b>620.93</b>	<b>34.27</b>
<b>Nett Amount (S\$)</b>	<b>27,699.09</b>	<b>18,207.72</b>	<b>9,491.37</b>	<b>34.27</b>

### INSPECTION

Date of Assignment:	24/05/2021		
Date Inspected:	21/05/2021	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	12.0 days		

**Adjuster:** ADRIAN LING

**Manager:** DENISE TAY KWEE CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

# REPAIR DETAILS

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Distorted	2,179.00 FS	*1,743.20 FS
2	2		*REAR BUMPER ADAPTER - LH / RH	Not Necessary	44.00 FS	*- FS
3	1		*REAR BUMPER DIFFUSER	Distorted	421.00 FS	*336.80 FS
4	1		*REAR BUMPER GRILLE - LH / RH	N/S Cracked	454.00 FS	*181.20 FS
5	1		*REAR BUMPER TRIM - CENTER	Distorted	214.00 FS	*170.80 FS
6	1		*REAR BUMPER GRILLE - CENTER	Distorted	86.00 FS	*68.64 FS
7	2		*REAR BUMPER LIGHT REFLECTOR - LH / RH	Not Necessary	60.00 FS	*- FS
8	1		*REAR BUMPER REINFORCEMENT BEAM	Dented	530.00 FS	*424.00 FS
9	1		*REAR BUMPER SECURING STRIP - CENTER	Cracked	135.00 FS	*108.00 FS
10	1		*REAR BUMPER GUIDE SECTION - LH	Cracked	49.00 FS	*38.56 FS
11	1		*REAR BUMPER GUIDE PROFILE - LH	Cracked	56.00 FS	*44.24 FS
12	2		*REAR PARKING AID SENSOR	Not Necessary	976.00 FS	*- FS
13	4		*REAR PARKING AID SENSOR SEAL RING	Not Necessary	9.00 FS	*- FS
14	1		*SET REAR BUMPER WIRING	Not Necessary	182.00 FS	*- FS
15	1		*REAR BUMPER AERIAL ANTENNA	Not Necessary	71.00 FS	*- FS
16	1		*REAR BOOT LID	Dented	3,061.00 FS	*2,448.80 FS
17	1		*REAR BOOT LID PACKING ADHESIVE	Not Necessary	19.00 FS	*- FS
18	1		*REAR BOOT LID ATTACHMENT PARTS	Not Necessary	387.00 FS	*- FS
19	2		*REAR BOOT LID BALL STUD	Necessary	39.00 FS	*31.20 FS
20	1		*REAR BOOT LID GASKET	Not Necessary	155.00 FS	*- FS
21	1		*REAR BOOT LID LOCK	Not Necessary	178.00 FS	*- FS
22	1		*REAR BOOT LID STRIKER PLATE	Not Necessary	59.00 FS	*- FS
23	1		*REAR BOOT LID LOCK ACTUATOR	Not Necessary	177.00 FS	*- FS
24	2		*REAR BOOT LID BUNGS	Necessary	4.00 FS	*2.88 FS
25	2		*REAR BOOT LID CLIP	Necessary	3.00 FS	*2.40 FS
26	1		*REAR BOOT LID PACKING ADHESIVE	Necessary	19.00 FS	*14.88 FS
27	1		*REAR BOOT LID BUNGS	Not Necessary	4.00 FS	*- FS
28	1		*AUDI EMBLEM	Necessary	138.00 FS	*110.00 FS
29	1		*A1 EMBLEM	Necessary	99.00 FS	*79.04 FS
30	2		*REAR LICENSE PLATE LIGHT	Not Necessary	202.00 FS	*- FS
31	1		*TAIL LIGHT INNER - LH	Cracked	807.00 FS	*645.60 FS
32	1		*TAIL LIGHT TRIM - LH	Not Necessary	30.00 FS	*- FS
33	1		*TAIL LIGHT OUTER - LH	Cut	807.00 FS	*645.60 FS
34	5		*TAIL LIGHT CLIP	Necessary	8.00 FS	*6.00 FS
35	2		*REAR BUMPER SPOILER CLIP	Necessary	15.00 FS	*12.00 FS
36	1		*REAR WINDOW	Necessary	776.00 FS	*620.40 FS
37	4		*REAR WINDOW PACKING ADHESIVE	Necessary	61.00 FS	*48.80 FS
38	1		*REAR WINDOW BONDING AGENT	Necessary	49.00 FS	*38.48 FS
39	1		*REAR CROSS PANEL	Dented	271.00 FS	*216.80 FS
40	1		*REAR CROSS PANEL REINFORCEMENT	Dented	637.00 FS	*510.00 FS
41	2		*REAR VENT TRIM - CENTRE	Cracked	135.00 FS	*107.52 FS
42	1		*REAR SILENCER	Not Necessary	466.00 FS	*- FS
43	1		*REAR SILENCER DUAL CLIP	Not Necessary	59.00 FS	*- FS
44	1		*REAR SILENCER RETAINER	Not Necessary	55.00 FS	*- FS
45	1		*WINDSCREEN SEALANT	Necessary	200.00 FS	*200.00 FS
46	1		*ACRYLIC SEALER	Necessary	180.00 FS	*180.00 FS
47	1		*CAVITY WAX	Necessary	140.00 FS	*140.00 FS
48	1		*STONE CHIP	Necessary	180.00 FS	*180.00 FS
49	1		*REAR NUMBER PLATE WITH HOLDER	Dented	60.00 FS	*60.00 FS
50	1		*SUNDRIES	Necessary	300.00 FS	*70.72 FS
51	1		*REAR WHEEL HOUSING LINER - LH (Supplementary)	Torn	183.00 FS	*146.00 FS
52	1		*REAR UNDERCARRIAGE TRIM - KH (Supplementary)	Torn	47.00 FS	*39.36 FS
53	1		*WEBBING ADHESIVE TAPE (Supplementary)	Necessary	127.00 FS	*104.80 FS

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
54	1		*REAR END PANEL CONNECTING PLATE - LH/RH (Supplementary)	Necessary	82.00 FS	*67.84 FS
F=Franchise part. S=SpcNett.						
					<b>Total Parts (\$\$)</b>	<b>15,685.00      9,844.56</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE AND TRANSFER DATA REAR PARKING AID. CHECK FUNCTION AND RENEW ACCORDING TO FUNCTION	New	280.00	280.00
2	TO REMOVE AND TRANSFER REAR LIDS CONVENIENCE LOCK SYSTEM, WIRE HARNESS FOR TAIL LIGHTS AND REAR REVERSE CAMERA	New	360.00	360.00
3	TO DISLodge AND REINSTALL REAR WIRE HARNESS FOR TAIL LIGHTS, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO COMPONENTS	New	480.00	480.00
4	TO DISMANTLE REAR BUMPER AND REAR LID. CUT OUT AND WELD REAR OUTER AND INNER CROSS PANELS. RENEW REAR BUMPER AND REAR LID. RE-ORGANISE REAR CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	3,500.00	2,500.00
5	TO RESPRAY REAR BUMPER, REAR LID AND END PANELLING. TO CARRY OUT JOINT SEALER WORKS AND STONE CHIP TREATMENT	New	2,600.00	1,650.00
6	TO RENEW REAR WINDSCREEN	New	360.00	360.00
7	TO INSTALL 3M REAR WINDSCREEN SOLAR FILM	New	0.00	400.00
8	TO REMOVE AND RENEW REAR EXHAUST SILENCER. ALIGN TO POSITION	New	480.00	0.00
9	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
10	TO REPAIR SPARE WHEEL HOUSING (Supplementary)	New	700.00	250.00
11	TO RESPRAY SPARE WHEEL HOUSING (Supplementary)	New	1,050.00	550.00
12	TO CARRY OUT WATER SEEPAGE TEST FOR REAR WINDSCREEN (Supplementary)	New	200.00	150.00
<b>Gross Labour Cost (\$\$)</b>			<b>10,202.00</b>	<b>7,172.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >