

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG21006062/AQCE2

Date: 11/08/2021

REFERENCE

Insured/Claimant: ACW HOLDINGS P/L Policy No: 2070149996
Date of Loss: 21/04/2021 Nature of Claim: OD Claim No: 5800247876SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMV9077A**
Make & Model: AUDI Q5, 2.0 TFSI Quattro (A) Engine No: DAX061683
Reg. Date: 27/10/2020 (Man. Year: 2019) Chassis No: WAUZZZFYL2005422
Colour: White Odometer: 14767 km
Engine Capacity: 1984 cc
Market Value/New Car Price: S\$200,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/55 R19 Rear Tyre Size: 235/55 R19
Front Left Side: Continental 6 mm Rear Left Side: Continental 6 mm
Front Right Side: Continental 6 mm Rear Right Side: Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	31,910.00	7,155.20	24,754.80	77.58
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,072.00	2,122.00	3,950.00	65.05
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	37,982.00	9,277.20	28,704.80	75.57
- Excess (S\$)	1,000.00	1,000.00	0.00	0.00
(S\$)	36,982.00	8,277.20	28,704.80	77.62
+ GST 7.00/7.00% (S\$)	2,588.74	579.40	2,009.34	77.62
Nett Amount (S\$)	39,570.74	8,856.60	30,714.14	77.62

INSPECTION

Date of Assignment: 24/05/2021
Date Inspected: 21/05/2021 Inspected At: Premium Automobiles Pte Ltd (UBI)
55 Ubi Road 1
Singapore 408699
Estimated Period of Repair: 3.0 days

Adjuster: ADRIAN LING

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	2,929.00 FS	*2,342.80 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	293.00 FS	*- FS
3	2		*FRONT BUMPER SECURING STRIP - LH / RH	Not Necessary	56.00 FS	*- FS
4	2		*FRONT BUMPER CLOSING ELEMENT - LH / RH	Not Necessary	226.00 FS	*- FS
5	1		*FRONT BUMPER GRILLE - CENTER	Not Necessary	144.00 FS	*- FS
6	1		*FRONT BUMPER SPOILER	Not Necessary	763.00 FS	*- FS
7	1		*FRONT BUMPER UNDERRUN BAR	Not Necessary	518.00 FS	*- FS
8	1		*FRONT BUMPER CLOSING ELEMENT	Not Necessary	173.00 FS	*- FS
9	1		*FRONT RADIATOR GRILLE	Cracked	3,530.00 FS	*2,824.00 FS
10	1		*QUATTRO EMBLEM	Necessary	106.00 FS	*84.80 FS
11	1		*FRONT BUMPER STRIKER PLATE	Not Necessary	244.00 FS	*- FS
12	1		*FRONT BUMPER AIR GUIDE GRILLE - LH / RH	O/S Missing	1,162.00 FS	*464.40 FS
13	1		*FRONT BUMPER END CAP - LH / RH	O/S Missing	184.00 FS	*73.20 FS
14	4		*FRONT BUMPER LOCKING CLIP	Not Necessary	16.00 FS	*- FS
15	1		*FRONT BUMPER FOAM FILLER PIECE	Cracked	177.00 FS	*141.60 FS
16	1		*FRONT BUMPER CARRIER	Not Necessary	981.00 FS	*- FS
17	2		*FRONT BUMPER GUIDE SECTION - LH / RH	Not Necessary	78.00 FS	*- FS
18	1		*FRONT BUMPER COVER	Not Necessary	129.00 FS	*- FS
19	1		*CAUTION STICKER	Not Necessary	14.00 FS	*- FS
20	1		*AIR CONDITIONER STICKER	Not Necessary	20.00 FS	*- FS
21	2		*FRONT INNER PARKING AID SENSOR	Not Necessary	488.00 FS	*- FS
22	4		*FRONT INNER PARKING AID SENSOR SEAL RING	Not Necessary	14.00 FS	*- FS
23	2		*FRONT HORN LOW / HIGH TONE - LH / RH	Not Necessary	390.00 FS	*- FS
24	1		*HEADLIGHT MOUNTING - LH / RH	O/S Cracked	236.00 FS	*94.40 FS
25	2		*HEADLIGHT - LH / RH	Not Necessary	16,382.00 FS	*- FS
26	2		*HEADLIGHT LIFT CYLINDER - LH / RH	Not Necessary	280.00 FS	*- FS
27	1		*HEADLIGHT HOSE	Not Necessary	125.00 FS	*- FS
28	2		*FRONT WHEEL SPOILER - LH / RH	Not Necessary	324.00 FS	*- FS
29	2		*FRONT WHEEL COVER - LH / RH	Necessary	1,264.00 FS	*1,011.20 FS
30	2		*FRONT RADIATOR AIR GUIDE - UPPER / LOWER	Not Necessary	96.00 FS	*- FS
31	1		*FRONT RADIATOR AIR GUIDE - CENTER	Not Necessary	42.00 FS	*- FS
32	1		*FRONT RADIATOR AIR GUIDE LONG - LH / RH	O/S Deformed	116.00 FS	*46.32 FS
33	1		*FRONT NUMBER PLATE	Dented	60.00 FS	*60.00 FS
34	1		*SUNDRIES	Necessary	350.00 FS	*12.48 FS

F=Franchise part. S=SpcNett.

Total Parts (S\$) 31,910.00 7,155.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO REMOVE AND TRANSFER BOTH HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	800.00	0.00
3	TO DISMANTLE AND RENEW FRONT BUMPER BOTH HEADLIGHT. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	1,200.00	500.00
4	TO RESPRAY FRONT BUMPER, FRONT BUMPER LOWER SPOILER. BONNET AND FRONT WHEEL ARCH TRIMS	New	3,400.00	950.00
5	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
			Gross Labour Cost (\$\$)	2,122.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >