



TAX INVOICE

Precise Auto Service
1 Kaki Bukit Ave 6,
#02-34/36 Autobay @
Kaki Bukit,
Singapore 417883

Invoice Date
9 Dec 2020

Invoice Number
INV-0019463

Reference
SLZ8831L

Complete Evaluation
201500060W

Complete Evaluation Pte
Ltd
c/o STA Evaluation
13 Kaki Bukit Road 4,
#01-02, Bartley Biz Centre
SINGAPORE 417807
Phone: 6264 0606

Description	Quantity	Unit Price	Tax	Amount SGD
Evaluation Package A - KB	1.00	175.70	7%	175.70
Subtotal				175.70
TOTAL LOCAL SUPPLY OF GOODS AND SERVICES 7%				12.30
TOTAL SGD				188.00
Less Amount Paid				188.00
AMOUNT DUE SGD				0.00

Due Date: 9 Dec 2020

Cheque payable to "Complete Evaluation Pte Ltd"

Payment Mode Available at Centres: PayNow / Cheque

TIP

PAYMENT ADVICE

To: Complete Evaluation Pte Ltd
c/o STA Evaluation
13 Kaki Bukit Road 4, #01-02, Bartley Biz Centre
SINGAPORE 417807
Phone: 6264 0606

Customer
Invoice Number

Precise Auto Service
INV-0019463

Amount Due
Due Date

0.00
9 Dec 2020

Amount Enclosed

Enter the amount you are paying above

PRECISE AUTO SERVICE

NO 1 KAKI BUKIT AVE 6 #02-33/34/36 AUTOBAY SINGAPORE 417883

TEL : 6745 7367 FAX : 6841 3390

CO. REG. NO. : 35766600C GST REG. NO. : 35766600C

=====

Accident Date : 30-11-20

OUR REF : SLZ 8831L/T/20

Chen Jian Rong, Jeremy



TAX INVOICE

Invoice No. : TP2102-007

DATE : 28-02-21

FINAL BILL ON VEH. NO. : SLZ 8831L
VEHICLE MODEL : MAZDA 3

LUMP SUM REPAIR

INCLUDING SUPPLY OF PARTS & LABOUR

PANEL BEATING & SPRAY PAINTING

11,750.00

SUB-TOTAL	:	11,750.00
ADD GST 7%	:	822.50
TOTAL AMOUNT SGD	:	12,572.50

This is a computer generated document and requires no signature.

Precise Appraiser Pte Ltd

Reg no. 201924041Z

Receipt

To: Chen Jianrong, Benny

Invoice No: 2021/INV/0037

CC: Precise Auto Service

Your Reference:

1 Kaki Bukit AVE. 6 #02-3/36

Our Reference: 2020/0216

Kaki Bukit Autobay

Date : 19/4/2021

Singapore 417883

Description	Amount S\$
Particulars	
Vehicle No: SLZ8831L	
Accident Date : 30/11/2020	
Date of Inspection: 3/12/2020	
Service:	
Assessment with report (inclusive of photographs and transport charges etc)	\$822
Total Amount:	\$822

Payment Details:

- 1) Cheque: Kindly make all cheques crossed and payable to **PRECISE APPRAISER PTE LTD**
- 2) Online Banking: **Maybank 041-9107653-9**



Precise Appraiser Pte Ltd

Precise Appraiser Pte Ltd

Reg no. 201924041Z

Invoice

To: Chen Jianrong, Benny

Invoice No: 2021/INV/0037

CC: Precise Auto Service

Your Reference:

1 Kaki Bukit AVE. 6 #02-3/36

Our Reference: 2020/0216

Kaki Bukit Autobay

Date: 19/4/2021

Singapore 417883

Description	Amount S\$
Particulars	
Vehicle No: SLZ8831L	
Accident Date : 30/11/2020	
Date of Inspection: 3/12/2020	
Service:	
Assessment with report (inclusive of photographs and transport charges etc)	\$822
Total Amount:	\$822

Payment Details:

- 1) Cheque: Kindly make all cheques crossed and payable to **PRECISE APPRAISER PTE LTD**
- 2) Online Banking: **Maybank 041-9107653-9**



Precise Appraiser Pte Ltd

To: Chen Jianrong, Benny

CC: Precise Auto Service
1 Kaki Bukit AVE. 6 #02-3/36
Kaki Bukit Autobay
Singapore 417883

REFERENCES

Ref No	: 2020/0216	Date of Report	: 30/11/2020
Claim Type	: Third Party	Date of Request	: 3/12/2020
Third party vehicle	: SLZ8831L	Date of Accident	: 30/11/2020
Insured Vehicle	:	Date of Inspection	: 3/12/2020
Your Reference No	: -		

DAMAGED VEHICAL PARTICULARS

Registration Plate No	: SLZ8831L	Engine Modification	: NIL
Model / Make	: Mazda 3	Pre-accident damage	: NIL
Colour	: Grey	General Condition	: Good
Manufacturing Year	: 2017	General Paint Work	: Good
Engine No	: P520495238	Steering	: Serviceable
Engine Capacity	: 1500cc	Handbrake	: Serviceable
Chassis No	: JM6BN24A8J0204693	Footbrake	: Serviceable
Odometer No	: 181044		
Transmission	: Auto		

TYRES CONDITION

Front Right		Rear Left	
Make	: Dunlop	Make	: Dunlop
Size	: 215/55 r16 4	Size	: 215/55 r16 4
Front Left		Rear Right	
Make	: Dunlop	Make	: Dunlop
Size	: 215/55 r16 4	Size	: 215/55 r16 4

The above millimetres represent the remaining life of tyre treads

VEHICAL REPAIR COST

<u>Descriptions</u>	<u>Repairer (S\$)</u>	<u>Difference (S\$)</u>	<u>Adjuster (S\$)</u>
Parts	12,481.60		11,176.00
Labour	4,660.00		3,500.00
Calculated Cost (S\$) :	17,141.60	2,465.60	14,676.00


Recommended Lump Sum Repair Cost (S\$)	: 11,750.00
Estimate Repair Duration	: 11
Survey Inspection At	: Precise Auto Service
Survey Inspection Address	: 1 Kaki Bukit AVE. 6 #02-3/36 Kaki Bukit Autobay Singapore 417883

DESCRIPTION OF DAMAGE

At the time of inspection, this vehicle sustained damages to the **Rear portion**.

Rear bumper, tailgate, rear end panel dented. Rear windscreen glass shattered, Taillamp, tailgate reflector base crack etc.

Please see attached scheduled details.



SPECIAL REMARKS

We have not authorised repair. Under normal circumstances, estimated **11** working days are required to repair the vehicle.

We are pleased to advise that the inspection work was carried out accordingly, and hereby submit our Inspection Report and photographs.

Handwritten signature of the Automotive Appraiser and a circular stamp reading "PRECISE APPRAISER PTE LTD".

Automotive Appraiser
MSAAA

Disclaimer:

This survey was conducted by Precise Appraiser Pte Ltd without prejudice basis and we do not authorized repair. Report by Precise Appraiser Pte Ltd is deemed as confidential and provided for the use of clients and appointed agent. *We have inspected thoroughly each and every item on the repairer's estimate against the actual damages found on the vehicle.* All findings and recommendations are listed accordingly and final decision of settlement to your good selves parts thereof accordingly and final. No liability shall be attached to Precise Appraiser Pte Ltd therefore.

Our Reference : 2020/0216

Your Reference:

Vehicle Number : SLZ8831L

S/N	Qty	Description	Condition	Repairer Estimate (S\$)	Our Assessment (S\$)
		<u>Parts</u>			
1	1pcs	Tail Gate	Dented	1,333.00	1,333.00
2	2pcs	Tail Gate Hinge @33/pcs	Bent	66.00	66.00
3	1pcs	Tail Gate Lock	Dented	284.00	284.00
4	1pcs	Tail Gate Lock Striker	Serviceable	61.00	-
5	2pcs	Tail Gate Stopper @16/pcs	Serviceable	32.00	-
6	1pcs	Tail Gate Weatherstripe	Kindred	147.00	147.00
7	1pcs	Tail Gate Outer Garnish	Crack	449.00	449.00
8	4pcs	Tail Gate Outer Garnish Clips @5pcs	Necessary	20.00	20.00
9	1pcs	Tail Gate Badge	Necessary	79.00	79.00
10	1pcs	Tail Gte Emblum "Sky active"	Necessary	67.00	67.00
11	1pcs	Tail Gte Emblum "Mazda 3"	Necessary	57.00	57.00
12	2pcs	Tail Gate Reflector @233/pcs	Base Crack	466.00	466.00
13	4pcs	Tail Gate Reflector Clips @5/pcs	Necessary	20.00	20.00
14	1pcs	Tail Gate Outer Keyless Antenna	Crack	142.00	142.00
15	1pcs	Tail Gate Opener Switch	Shorted	188.00	188.00
16	1pcs	Tail Gate Outer Handle Switch	Deformed	125.00	125.00
17	1pcs	Tail Gate Inner Trim Board	Deep Cut	414.00	414.00
18	8pcs	Tail Gate Inner Trim Board Clips @5/pcs	Necessary	40.00	40.00
19	1pcs	Tail Gate Top Spoiler	Serviceable	1,215.00	-
20	8pcs	Tail Gate Top Spoiler Clips @5/pcs	Necessary	40.00	40.00
21	2pcs	Tail Gate Absorber @128/pcs	Bent	256.00	256.00
22	1pcs	Rear Wiper Arm	Grazed	62.00	62.00
23	1pcs	Rear Wiper Arm Cover	Grazed	13.00	13.00
24	1pcs	Rear Wiper Blade	Torn	24.00	24.00
25	1pcs	Rear Wiper Motor	Bent	383.00	383.00
26	1pcs	Rear Windscreen Glass	Shattered	1,010.00	1,010.00
27	1pcs	Rear Windscreen Glass Inner Seal	Necessary	50.00	50.00
28	2pcs	Rear Windscreen Glass Inner Side Trim @13.9/p	Deep Cut	278.00	278.00
29	1pcs	Rear Windscreen Glass Inner Trim (Top)	Deep Cut	84.00	84.00
30	2pcs	Rear Number Plate Lamp @46/pcs	Holder Torn	92.00	92.00
31	1pcs	Rear Number Plate Lamp Garnish	Serviceable	166.00	-
32	1pcs	Rear Bumper Fascia	Dented	998.00	998.00
33	2pcs	Rear Bumper Tow Cover @16/pcs	Serviceable	32.00	32.00
34	1pcs	Rear Bumper Side Retainer RH	Torn	38.00	38.00
35	10pcs	Rear Bumper Clips @5/pcs	Necessary	50.00	50.00
36	1pcs	Rear Bumper Lower Garnish	Deformed	78.00	78.00
37	4pcs	Rear Bumper Lower Garnish Riverts @5/pcs	Necessary	20.00	20.00
38	1pcs	Rear Bumper Reinforcement	Dented	565.00	565.00
39	4pcs	Rear Bumper Parking Sensor @204/pcs	Shorted	816.00	816.00
40	1pcs	Rear Bumper Parking Sensor Wire Harness	Serviceable	158.00	-
41	2pcs	Rear Bumper Reflector @53/pcs	Holder Torn	106.00	106.00
42	2pcs	Tail Lamp @972/pcs	Base Crack	1,944.00	1,944.00
43	4pcs	Tail Lamp Clips @16/pcs	Necessary	64.00	64.00
44	2pcs	Tail Lamp Sealant @42/pcs	Necessary	84.00	84.00
45	1pcs	Rear End Panel	Dented	656.00	656.00
46	1pcs	Rear End Panel Top Trim	Deformed	101.00	101.00
47	4pcs	Rear End Panel Top Trim Clips @5/pcs	Necessary	20.00	20.00
48	2pcs	Rear Fender Inner Trim RH & LH @482/pcs	Holder Torn	964.00	964.00
49	6pcs	Rear Fender Inner Trim Clips @5/pcs	Necessary	30.00	30.00

50	1pcs	Exhaust Silencer	Dented	1,075.00	1,075.00
51	4pcs	Exhaust Silencer Hook @35/pcs	Torn	140.00	140.00

Total	15,602.00	13,970.00
Less 20%	3,120.40	2,794.00
Parts Sub Total	12,481.60	11,176.00

Special Nett Item

52	1pcs	Rear Windscreen Glass Sealant	Necessary	60.00	50.00
53	1pcs	Rear Windscreen Glass Solar Film	Necessary	180.00	180.00
54	1pcs	Rear Number Plate	Dented	45.00	45.00
55	1pcs	Rear Number Plate Casing	Dented	29.00	29.00
56	1pcs	Reverse Camera	Shorted	756.00	756.00
57	1set	Rear Video Recorder	Dislodge	1,200.00	1,200.00

Total	2,270.00	2,260.00
--------------	----------	----------

Labour

1	Towing	80.00	80.00
2	To check wiring system	80.00	50.00
3	To tuff coat affected areas	200.00	150.00
4	To remove & refix rear windscreen glass	180.00	180.00
5	To remove & refix rear video recorder	180.00	150.00
6	To remove & refix exhaust silencer & straighten exhaust center pipe	280.00	200.00
7	To remove & refix interior upholstery	180.00	150.00
8	To cleaning interior upholstery	180.00	100.00
9	To reset ecu system after repair.	300.00	120.00
10	To renew damaged parts, straighten & repair , rear fender, rear floor panel and aligned all parts	1,500.00	1,200.00
11	To respray affected areas	1,500.00	1,200.00
Labour Total		4,660.00	3,500.00
Sub Total (labour and parts)		19,411.60	14,676.00

Adjustment / Recommendations


Note: For Lump Sum Repair

The workshop has agreed to undertake the repair on a Lump Sum Basis, and/or use of ex-stock/reconditioned parts whichever is possible (having taken into consideration to repair instead of replacements).


The final adjusted Lump Sum contract amount is **S\$11,750.**

Under normal circumstances, the repair period would be about **11** working days.

INSPECTION PHOTOS




INSPECTION PHOTOS




INSPECTION PHOTOS




INSPECTION PHOTOS



INSPECTION PHOTOS




INSPECTION PHOTOS





INSPECTION PHOTOS



INSPECTION PHOTOS





INSPECTION PHOTOS



INSPECTION PHOTOS



INSPECTION PHOTOS




Our Ref: 2020/0217
Vehicle No.: SKU3113Y

RE-INSPECTION PHOTOS




Our Ref: 2020/0217
Vehicle No.: SKU3113Y

RE-INSPECTION PHOTOS



Our Ref: 2020/0217
Vehicle No.: SKU3113Y

RE-INSPECTION PHOTOS



RE-INSPECTION PHOTOS



RE-INSPECTION PHOTOS




RE-INSPECTION PHOTOS



RE-INSPECTION PHOTOS



RE-INSPECTION PHOTOS



Our Ref: 2020/0217
Vehicle No.: SKU3113Y

RE-INSPECTION PHOTOS



RE-INSPECTION PHOTOS



Our Ref: 2020/0217
Vehicle No.: SKU3113Y

RE-INSPECTION PHOTOS



RE-INSPECTION PHOTOS



RE-INSPECTION PHOTOS



Our Ref: 2020/0217
Vehicle No.: SKU3113Y


RE-INSPECTION PHOTOS



RE-INSPECTION PHOTOS



RE-INSPECTION PHOTOS



Our Ref: 2020/0217
Vehicle No.: SKU3113Y

RE-INSPECTION PHOTOS




Our Ref: 2020/0217
Vehicle No.: SKU3113Y


RE-INSPECTION PHOTOS



RE-INSPECTION PHOTOS



RE-INSPECTION PHOTOS



Our Ref: 2020/0217
Vehicle No.: SKU3113Y

RE-INSPECTION PHOTOS

