

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT**

**Our File No:** CS3/MSG21004587/GTF3E2-1  
**Date:** 15/06/2021

**REFERENCE**

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. Policy No: 1001379622  
**Claimant Vehicle No :** GBD3594M **Insured Vehicle No :** WC6103J  
Date of Loss: 31/03/2021 Nature of Claim: TP Claim No: 255453

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No: **GBD3594M**  
Make & Model: TOYOTA DYNA 150 MANUAL 3SEATER, 3.0 D (M) Engine No: 1KD2427179  
Reg. Date: 09/09/2014 (Man. Year: 2014) Chassis No: JTFAT35Y80K203368  
Colour: White/Red Odometer: 232628 km  
Engine Capacity: 2982 cc  
Market Value/New Car Price: N/A  
Sum Insured (S\$): **Market Value/New Car Price**

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size: 195 R15 Rear Tyre Size: 155 R12 (D)  
Front Left Side: Falken 6 mm Rear Left Side: Falken 6/6 mm  
Front Right Side: Falken 6 mm Rear Right Side: Falken 6/6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	13,171.57	5,040.42	8,131.15	61.73
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,440.00	1,520.00	1,920.00	55.81
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>16,611.57</b>	<b>6,560.42</b>	<b>10,051.15</b>	<b>60.51</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>5,250.00</b>		
<b>Nett Amount (S\$)</b>	<b>16,611.57</b>	<b>5,250.00</b>	<b>11,361.57</b>	<b>68.40</b>

**INSPECTION**

Date of Assignment: 12/04/2021  
Date Inspected: 12/04/2021 Inspected At: Lys Engineering (SUNGEI KADUT)  
24 SUNGEI KADUT ST 4  
Singapore 729050  
Estimated Period of Repair: 5.0 days

**Adjuster:** XING GUO QIANG**Manager:** DENISE TAY KWEE CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

**REPAIR DETAILS****Reference**

<b>Part Source:</b>	(Last Synchronised: 15 Jun 2021)	
<b>Parts:</b>	N/A	TOYOTA DYNA 150 MANUAL 3SEATER 3.0 D (M) (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for GBD3594M)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

**Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT WIPER PANEL	Repair	481.95 FL	*- FL
2	2		*FRONT WIPER PANEL SIDE GARNISH	Serviceable	482.90 FL	*- FL
3	1		*FRONT WIDE MIRROR WITH STAY LH	Serviceable	761.90 FL	*- FL
4	1		*FRONT SIDE MIRROR LH	Serviceable	333.25 FL	*- FL
5	1		*FRONT ROUND MIRROR LH	Missing	97.20 FL	*97.20 FL
6	1		*FRONT CAB PANEL	Dented / Buckled	1,378.70 FL	*1,100.00 FL
7	1		*FRONT CAB PANEL INNER SUPPORT	Dented / Twisted (1Pc Only)	194.20 FL	*97.10 FL
8	2		*FRONT CAB PANEL MOULDING	Serviceable	399.50 FL	*- FL
9	2		*FRONT CORNER PANEL	Repair	753.00 FL	*- FL
10	1		*FRONT SUB CHASSIS FRAME CROSS MEMBER	Repair	785.30 FL	*- FL
11	1		*FRONT GRILLE ASSY	Broken	587.65 FL	*481.00 FL
12	1		*FRONT GRILLE EMBLEM LOGO	Necessary	86.90 FL	*75.00 FL
13	2		*FRONT HEADLAMP	Serviceable	1,784.20 FL	*- FL
14	1		*FRONT BUMPER	Dented / Twisted	561.90 FL	*485.00 FL
15	1		*RADIATOR ASSY	Twisted / Leakage	2,660.50 FL	*1,637.00 FL
16	1		*RADIATOR TOP HOSE	Serviceable	51.60 FL	*- FL
17	1		*RADIATOR BOTTOM HOSE	Serviceable	69.80 FL	*- FL
18	1		*AIR INTERCOOLER	Serviceable	1,890.50 FL	*- FL
19	1		*AIR CON BLOWER ASSY	Broken	1,431.90 FL	*1,218.00 FL
20	1		*AIR CON COOLING COIL ASSY	Broken	1,891.25 FL	*885.60 FL
21	1		*FRONT CAB PANEL MOULDING - CTR	Mtg Broken	291.33 FL	*291.33 FL
22	1		*BOT AIR CON OIL	Necessary	65.00 FS	*40.00 FS
23	1		*COMPANY NAME	Necessary	300.00 FS	*200.00 FS
24	1		*FRONT NUMBER PLATE	Warped	40.00 FS	*15.00 FS
25	1		*FRONT FLAMMABLE STICKER	Necessary	35.00 FS	*10.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>17,415.43</b>	<b>6,632.23</b>
<b>- List Item Discount on L Items 25.00/25.00% (\$\$)</b>	4,243.86	1,591.81
<b>Total Parts (\$\$)</b>	<b>13,171.57</b>	<b>5,040.42</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO CHECK FRONT ELECTRICAL WIRING & REFOCUS HEADLAMP	New	40.00	20.00
2	TO RESPRAY UNDERCOATING	New	100.00	60.00
3	TO REMOVE, REFIX FRONT DASHBOARD	New	250.00	220.00
4	TO REMOVE, REFIX A/C COOLING SYSTEM & REFILL GAS	New	150.00	120.00
5	TO RESPRAY PAINTING & ETC	New	1,400.00	500.00
6	PANEL BEATING, CUT, WELD, REMOVE & REPLACING ABOVE PARTS	New	1,500.00	600.00
			<b>Gross Labour Cost (\$)</b>	<b>1,520.00</b>
			<b>3,440.00</b>	<b>1,520.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >