

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #07-16
Singapore 079120

Our File No: CS/AIG21006076/EQF3E2

Date: 16/06/2021

REFERENCE

Insured/Claimant:	TAN GUO HUI	Policy No:	1900038924		
Date of Loss:	23/05/2021	Nature of Claim:	OD	Claim No:	9295328020SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMJ5537D	Engine No:	G4FGJH719421
Make & Model:	KIA CERATO, 1.6 (A)	Chassis No:	KNAF3416MK5030189
Reg. Date:	12/03/2019 (Man. Year: 2018)	Odometer:	42549 km
Colour:	Grey		
Engine Capacity:	1591 cc		
Market Value/New Car Price:	S\$71,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45 R17	Rear Tyre Size:	225/45 R17
Front Left Side:	Kumho 5 mm	Rear Left Side:	Kumho 5 mm
Front Right Side:	Kumho 5 mm	Rear Right Side:	Kumho 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,737.60	1,754.80	1,982.80	53.05
Miscellaneous Items	0.00	0.00	0.00	
Labour	980.00	980.00	0.00	0.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,717.60	2,734.80	1,982.80	42.03
- Excess (S\$)	300.00	300.00	0.00	0.00
(S\$)	4,417.60	2,434.80	1,982.80	44.88
+ GST 7.00/7.00% (S\$)	309.23	170.44	138.79	44.88
Nett Amount (S\$)	4,726.83	2,605.24	2,121.59	44.88

INSPECTION

Date of Assignment:	24/05/2021	
Date Inspected:	24/05/2021 Inspected At:	Cycle & Carriage KIA Pte Ltd (Pandan Gardens) 209 Pandan Gardens Singapore 609339
Estimated Period of Repair:	3.0 days	

Adjuster: CHEN TSUE YEE

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT NUMBER PLATE WITH FRAME	Bent	50.00 FS	*50.00 FS
2	1		*SUNDRIES	Necessary	50.00 FS	*20.00 FS
3	1		*COVER-FR BUMPER	Dented	633.00 FL	*633.00 FL
4	1		*GRILLE ASSY-RADIATOR	Broken	328.00 FL	*328.00 FL
5	1		*GARNISH-RADIATOR GRILLE	Broken	38.00 FL	*38.00 FL
6	1		*GRILLE-FRONT BUMPER	Cut	485.00 FL	*485.00 FL
7	1		*MOULDING-FRONT BUMPER, RH	Not Necessary	216.00 FL	*- FL
8	1		*ABSORBER-FRONT BUMPER ENERGY	Broken	84.00 FL	*84.00 FL
9	1		*ORNAMENT-KIA NO.115	Necessary	32.00 FL	*32.00 FL
10	1		*LAMP ASSY-HEAD, RH	Not Necessary	2,210.00 FL	*- FL
11	1		*COVER-FR BUMPER FOG LAMP, RH	Not Necessary	15.00 FL	*- FL
12	1		*CAP-FRONT HOOK	Crushed	9.00 FL	*9.00 FL
			(Supplementary)			
13	1		*BEAM COMPLETE-FR BUMPER	Dented	497.00 FL	*497.00 FL
			(Supplementary)			

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	4,647.00	2,176.00
- List Item Discount on L Items 20.00/20.00% (\$\$)	909.40	421.20
Total Parts (\$\$)	3,737.60	1,754.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REPLACE FRT BUMPER	New	400.00	400.00
2	SPRAY PAINT WORK ON FRT BUMPER AND AFFECTED AREAS	New	350.00	350.00
3	TO REMOVE AND INSTALL FRT PARKING ASSIST SENSOR	New	80.00	80.00
4	CHECK ON WIRING & CHASSIS ELECTRICAL SYSTEM	New	30.00	30.00
5	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST	New	120.00	120.00
Gross Labour Cost (\$\$)			980.00	980.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >