



CYCLE &amp; CARRIAGE

# CYCLE & CARRIAGE KIA PTE LTD

## PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



### ESTIMATE

Co Reg No : 199405410K

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name	LCV08818/TAN GUO HUI (CHEN GUOHUI)
	Reg No/Reg Date	SMJ5537D*KC17/ 12/03/201
	Date In/Mileage	24/05/2021/ 42549
	Chassis No	KNAF3416MK5030189
	Engine No	G4FGJH719421
	Make/Model	KIA/CERATO 1.6 A SR SX G335
	Colour/Trim	ABT PLATINUM GRAPHI/ WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LAX00000	Credit	24/05/2021/ 11:24	QUK	289 / <del>Patrick Lee</del> KEVIN	33742

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
E PNT88000 REPLACE FRT BUMPER				400.00
E PNT98000 SPRAY PAINT WORK ON FRT BUMPER AND AFFECTED AREAS				350.00
E PNT88000 TO REMOVE AND INSTALL FRT PARKING ASSIST SENSOR				80.00
A 54900099 CHECK ON WIRING & CHASSIS ELECTRICAL SYSTEM				30.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST				120.00
M SUNDRY TO SUPPLY FRT NUMBER PLATE WITH FRAME				50.00
M SUNDRY SUNDRIES				50.00
M COVER-FR BUMPER	1.00	633.00	20.00	506.40
M GRILLE ASSY-RADIATOR	1.00	328.00	20.00	262.40
M GARNISH-RADIATOR GRILLE	1.00	38.00	20.00	30.40
M GRILLE-FRONT BUMPER	1.00	485.00	20.00	388.00
M MOULDING-FRONT BUMPER,RH	1.00	216.00	20.00	172.80
M ABSORBER-FRONT BUMPER ENERGY	1.00	84.00	20.00	67.20
M ORNAMENT-KIA NO.115	1.00	32.00	20.00	25.60
M LAMP ASSY-HEAD,RH	1.00	2210.00	20.00	1768.00
M COVER-FR BUMPER FOG LAMP,RH	1.00	15.00	20.00	12.00

SURVEYOR NAME : \_\_\_\_\_

SURVEYOR SIGNATURE : \_\_\_\_\_

DATE : \_\_\_\_\_

REMARKS : \_\_\_\_\_

Confirm &amp; accepted by \_\_\_\_\_

Nett 4,312.80  
7% GST on 4312.80 301.90

Total Payable 4,614.70

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.