



Service Requests

Messages

Claims



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

General Details

Involving	TPVD YAMAHA FZ16 (FBH3963K)
Date of Loss	17 May 2021
Time of Loss	8:10
Loss Description	SH7646Z (INSD) HIT REAR OF FBH3963K (TP)
Comment	

Workshop Details

Total Rebate Amount	838
Nett Loss Amount	\$0.00
Assigned Workshop	LKK AUTO CONSULTANTS PTE LTD (TP)
Days of work completion *	20



Service Requests

Messages

Claims



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Vehicle & Driver Details



Vehicle Registration#	FBH3963K	Purchase Date	<div>DD/MM/YYYY</div> <div></div>
Registration State	<div>SINGAPORE</div>	Registration Date *	<div>05/06/2013</div> <div></div>
Mileage	<div></div>	Age of Vehicle	7

CATEGORY	POLICY INFORMATION	ASSESSMENT INFORMATION
Manufacturing Year		<div>2013</div>





Driver Details

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
Driver Name	MUHAMMAD TANSIR BIN IDRUS	<div></div>

CATEGORY	POLICY INFORMATION	ASSESSMENT INFORMATION
Make	TPVD YAMAHA	<input type="text" value="YAMAHA"/>
Model	FZ16	<input type="text" value="FZ 16"/>
Type		<input type="text" value=""/>
Type of Paint		<input type="text" value=""/>
Chassis No		<input type="text" value="ME121C0G4D2006951"/>
Engine No		<input type="text" value="21CG006819"/>
Engine Capacity		<input type="text" value="153"/>
Sum Insured		<input type="text" value="0"/>

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
Date of Birth		<input type="text" value="DD/MM/YYYY"/> 
Age	0	
Occupation	Unknown	<input type="text" value=""/>
Education Qualification	Other	<input type="text" value=""/>
Driving Experience	0	
Driver License #		<input type="text" value=""/>
License Type		<input type="text" value=""/>
License Issue Date		<input type="text" value="DD/MM/YYYY"/> 

CATEGORY	POLICY INFORMATION	ASSESSMENT INFORMATION
Market Value		<input type="text" value="0"/>

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
License Expiration Date		<input type="text" value="DD/MM/YYYY"/> 
Address	SG, Singapore	<input type="text"/>
Address type	Personal Correspondence	<input type="text" value=""/> 
Gender	Unknown	<input type="text" value=""/> 
Marital status	Unknown	<input type="text" value=""/> 
Identification #	TBC	<input type="text"/>



Service Requests

Messages

Claims



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Detailed Assessment

Inspection Date *

24/05/2021



Total Loss

Yes

No

Towing Charges

0

Voluntary Excess

0

Compulsory Excess

0

Young/Inexperienced/
Unnamed Driver Excess

0

Condition of Vehicle at time of survey

General condition

Good



Steering (Serviceable)

Yes

No

Footbrake
(Serviceable)

Yes

No

Handbrake
(Serviceable)

Yes

No

Engine Modification

Yes

No

Pre-accident condition

Good



Other Excess

0

Tyre Condition

Age of Tyres

Front Tyre Size

110/70-17

Front left side

PIRELLI6mm

Front right side

Spare wheel

Rear Tyre Size

140/70-17

Rear left side

PIRELLI6mm

Rear right side

[Service Requests](#)[Messages](#)[Claims](#)

Assessment Details

[General & Workshop Details](#)[Vehicle & Driver Details](#)[Vehicle Condition](#)[Taxes & Ratio](#)[Parts & Labour](#)[Miscellaneous](#)[Summary](#)

Tax Eligibility & Additional Deduction for Parts

Depr./Bttr%

0

Salvage%

0

Discount%

10

Settlement%

100

Paint Labour/Material Ratio

Paint Labour Ratio

20

Cash Loss

Yes

No

Paint Material Ratio

80

Part Supplied by AXA

Yes

No

Save



Service Requests

Messages

Claims



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio













Parts & Labour












Miscellaneous




Summary

Parts

Add		Approve		Deny		Submit All								
EDIT	SR NO	QUAN TITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT	REMARKS
	0	1		FRONT FENDER	Cracked	0	105	No	0	10	0	0	94.5	Front fender cracked, replaced with new part.
	0	2		FORK INNER TUBES	Serviceable	0	0	No	0	0	0	0	0	Inner fork tubes are in good condition.
	0	2		FORK OUTER TUBES	Serviceable	0	0	No	0	0	0	0	0	Outer fork tubes are in good condition.
	0	1		FORK UNDER BRACKET	Serviceable	0	0	No	0	0	0	0	0	Fork under bracket is in good condition.
	0	1		FRONT RIM SHAFT	Cut	0	55	No	0	10	0	0	49.5	Front rim shaft is cut, replaced with new part.
	0	1		FRONT RIM BEARING	Serviceable	0	0	No	0	0	0	0	0	Front rim bearing is in good condition.
	0	1		FRONT BRAKE DISC	Serviceable	0	0	No	0	0	0	0	0	Front brake disc is in good condition.

EDIT	SR NO	QUANTITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISCOUNT%	SALVAGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT	FACTOR (%)
	0	1		METER ASSY	Cut	0	520	No	0	10	0	0	468	88.27%
	0	1		SET SIDE MIRROR	Broken	0	140	No	0	10	0	0	126	90.00%
	0	1		SET FRONT SIGNALS	Broken	0	140	No	0	10	0	0	126	90.00%
	0	1		WINDSHIELD	Cracked	0	125	No	0	10	0	0	112.5	90.00%
	0	1		HEADLAMP	Cut	0	350	No	0	10	0	0	315	90.00%
	0	1		LAMPSTAY	Repair	0	0	No	0	0	0	0	0	0.00%
	0	1		HANDLE-BAR	Bent	0	150	No	0	10	0	0	135	90.00%
	0	1		HANDLE-BAR BALANCER N/S	Cut	0	30	No	0	10	0	0	27	90.00%
	0	1		SET HAND GRIP	Serviceable	0	0	No	0	0	0	0	0	0.00%
	0	1		CLUTCH LEVER	Cracked	0	35	No	0	10	0	0	31.5	90.00%
	0	1		FUEL TANK SIDE COVER - L/H	Cut	0	225	No	0	10	0	0	202.5	90.00%
	0	1		FUEL TANK SIDE COVER - R/H	Serviceable	0	0	No	0	0	0	0	0	0.00%

EDIT	SR NO	QUANTITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISCOUNT%	SALVAGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT	FACTOR
	0	1		SIDE BOARD - L/H	Cracked	0	130	No	0	10	0	0	117	Factor
	0	2		HEADLAMP SIDE COVER	Cracked	0	95	No	0	10	0	0	171	Factor
	0	1		SIDE STAND	Repair	0	0	No	0	0	0	0	0	Factor
	0	1		MAIN STAND	Repair	0	0	No	0	0	0	0	0	Factor
	0	1		FRONT FOOTREST N/S	Cut	0	40	No	0	10	0	0	36	Factor
	0	1		FRONT FOOTREST O/S	Serviceable	0	0	No	0	0	0	0	0	Factor
	0	1		FRONT FOOTREST BRACKETS - 2PCS	Bent	0	100	No	0	10	0	0	90	Factor
	0	1		GEAR PEDAL	Bent	0	58	No	0	10	0	0	52.2	Factor
	0	1		REAR HANDLE	Repair	0	0	No	0	0	0	0	0	Factor
	0	1		REAR FOOTREST N/S	Cut	0	52	No	0	10	0	0	46.8	Factor
	0	1		REAR FOOTREST O/S	Serviceable	0	0	No	0	0	0	0	0	Factor

EDIT	SR NO	QUAN TITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT	A (
	0	1		REAR SIGNAL N/S	Cut	0	70	No	0	10	0	0	63	F
	0	1		REAR SIGNAL O/S	Serviceable	0	0	No	0	0	0	0	0	I
	0	1		EXHAUST PROTECTOR (NOT CONSISTENT WITH THE IMPACT)	Cut	0	0	No	0	0	0	0	0	I









Labour

Add

Approve

Deny

Submit All

EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	ESTIMATE LABOUR AMOUNT	ADJUSTED LABOUR AMOUNT	ESTIMATE PAINT AMOUNT	ADJUSTED PAINT AMOUNT	ACTION (LABOUR)	COMMENT	REMOVE
	0		TO PROVIDE TOWING SERVICE (LOD)	0	50	0	0	Reviewing		
	0		TO CHECK WIRING AND RESET HEADLAMP FOCUSING	0	0	0	0	Deny		
	0		TO REPAIR BODY FRAME	0	0	0	0	Deny		
	0		TO PROVIDE LABOUR	0	280	0	0	Reviewing		



Service Requests

Messages

Claims



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition











Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Add		Approve		Deny		Submit All		
EDIT	SR NO	NAME	ACTION	ESTIMATED AMOUNT	ADJUSTED AMOUNT	COMMENT	REMOVE	
	0	DAYS OF REPAIR : 4 DAYS	Reviewing	0	0			
	0	1 SET NUMBER PLATE	Reviewing	0	10	FRONT NECESSARY		
	0	FORK OILS (2PCS)	Deny	0	0	NOT NECESSARY		

EDIT	SR NO	NAME	ACTION	ESTIMATED AMOUNT	ADJUSTED AMOUNT	COMMENT	REMOVE
	0	FORK OIL SEALS (2PCS)	Deny	0	0	NOT NECESSARY	
	0	1 SET STEERING CONE	Deny	0	0	NOT NECESSARY	
	0	REAR BOX	Reviewing	0	400	CUT	
	0	REAR BOX BRACKET	Deny	0	0	REPAIR	
	0	E.R.P. IU	Reviewing	0	165	CUT	

[Service Requests](#)[Messages](#)[Claims](#)

Assessment Details

[General & Workshop Details](#)[Vehicle & Driver Details](#)[Vehicle Condition](#)[Taxes & Ratio](#)[Parts & Labour](#)[Miscellaneous](#)

Summary

Estimated Claim Amount	\$0.00	Adjusted Claim Amount	\$3,168.50
------------------------	--------	-----------------------	------------

CATEGORY	ESTIMATE	ADJUSTED
Spare Parts	\$0.00	\$2,263.50
Labour	\$0.00	\$330.00
Miscellaneous	\$0.00	\$575.00

Submit for Review



Service Requests

Messages

Claims



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Add

Approve

Deny

Submit All

EDIT

SR
NO

NAME

ACTION

ESTIMATED
AMOUNT

ADJUSTED
AMOUNT

COMMENT

REMOVE



0

FINAL
LUMP
SUM

Reviewing

0

2500



[Service Requests](#)[Messages](#)[Claims](#)

Assessment Details

[General & Workshop Details](#)[Vehicle & Driver Details](#)[Vehicle Condition](#)[Taxes & Ratio](#)[Parts & Labour](#)[Miscellaneous](#)

Summary

Estimated Claim Amount	\$0.00	Adjusted Claim Amount	\$2,500.00
------------------------	--------	-----------------------	------------

CATEGORY	ESTIMATE	ADJUSTED
Miscellaneous	\$0.00	\$2,500.00

Submit for Review