



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBQ 8496L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	MIRROR (R)	CUT	38.00	38.00
1	MIRROR (L)	CUT	38.00	38.00
1	BALANCER (R)	CUT	36.00	36.00
1	HANDLE BAR	NOT NECESSARY	140.00	-
1	BRAKE PUMP COVER	CUT	25.00	25.00
1	BRAKE LEVER (R)	CUT	30.00	30.00
1	METER COVER	DEFORMED	65.00	65.00
1	METER COVER FRONT	CRACKED	65.00	65.00
1	FRONT VISOR	CUT	45.00	45.00
1	FRONT COVER INNER	DEFORMED	75.00	75.00
1	FRONT COVER OUTER	CUT	55.00	55.00
1	TOP COVER (R)	CRACKED	155.00	155.00
1	TOP COVER (L)	CRACKED	165.00	165.00
1	HEAD LAMP ASSY	CRACKED	311.00	311.00
1	SIDE LAMP (L)	CUT	55.00	55.00
1	COVER COMPARTMENT (R)	NOT NECESSARY	68.00	-
1	COMPARTMENT COVER	NOT NECESSARY	25.00	-
1	FUAL TANK COVER	NOT NECESSARY	65.00	-
1	FLOOR BOARD (L)	CRACKED	125.00	125.00
1	LOWER SIDE COVER (L)	DEFORMED	72.00	72.00
1	SIDE STAND	NOT NECESSARY	55.00	-
1	MAIN STAND	NOT NECESSARY	110.00	-
1	REAR SIDE COVER (L)	CUT	75.00	75.00
1	AIR BOX COVER	CUT	75.00	75.00
1	GIVI BOX BRACKET	CUT	180.00	180.00
1	GIVI BOX	CUT	150.00	150.00
1	SIDE COVER INNER	CUT	75.00	75.00
1	SIDE COVER (R)	CRACKED	75.00	75.00
1	FLOOR BOARD (R)	CUT	125.00	125.00
1	LOWER COVER (R)	CRACKED	72.00	72.00

Report Ref No. CS/SMR21006079/Auf3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	CHASSIS BEND	TO REPAIR SEE LABOUR	350.00	-
1	UNDER BRACKET	BENT	130.00	130.00
2	MUDGUARD FRONT	CRACKED	110.00	110.00
1	FRONT BRAKE CALIPER	NOT NECESSARY	190.00	-
1	FRONT DIS PLATE	NOT NECESSARY	175.00	-
1	FRONT WHEEL	NOT NECESSARY	235.00	-
1	FRONT TYRE	NOT NECESSARY	110.00	-
1	FOLK ASSY	BENT	399.00	399.00
	LESS 10% DISCOUNT		-	-282.10
			4,344.00	2,538.90
	LABOUR			
	TRANSPORTATION.		60.00	40.00
	WORKMANSHIP. INCLUSIVE OF THE REPAIR OF CHASSIS BEND.		350.00	350.00
			410.00	390.00
GRAND TOTAL			4,754.00	2,928.90
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,300.00

Report Ref No. CS/SMR21006079/Auf3e2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.