

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CS/AIG21006081/ETF3E2

Date: 13/08/2021

REFERENCE

Insured/Claimant: Caslin Lee Hui Ling (Li HuiLing) Policy No: 2100494742
Date of Loss: 19/05/2021 Nature of Claim: OD Claim No: 6206493801SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLJ6923C**
Make & Model: KIA SORENTO, 2.2 (A) Engine No: D4HBGH287577
Reg. Date: 21/12/2016 (Man. Year: 2016) Chassis No: KNAPH81BMG5254852
Colour: Brown Odometer: 66028 km
Engine Capacity: 2199 cc
Market Value/New Car Price: S\$75,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/55 R19 Rear Tyre Size: 235/55 R19
Front Left Side: Yokohama 5 mm Rear Left Side: Yokohama 5 mm
Front Right Side: Yokohama 5 mm Rear Right Side: Yokohama 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,728.40	7,664.80	3,063.60	28.56
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,670.00	3,410.00	1,260.00	26.98
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	15,398.40	11,074.80	4,323.60	28.08
- Excess (S\$)	600.00	600.00	0.00	0.00
(S\$)	14,798.40	10,474.80	4,323.60	29.22
+ GST 7.00/7.00% (S\$)	1,035.89	733.24	302.65	29.22
Nett Amount (S\$)	15,834.29	11,208.04	4,626.25	29.22

INSPECTION

Date of Assignment: 24/05/2021
Date Inspected: 24/05/2021 Inspected At: Cycle & Carriage KIA Pte Ltd (Pandan Gardens)
209 Pandan Gardens
Singapore 609339
Estimated Period of Repair: 10.0 days

Adjuster: CHEN TSUE YEE

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	50.00 FS	*20.00 FS
2	1		*LAMP ASSY-HEAD, LH	Broken	2,210.00 FL	*2,210.00 FL
3	1		*PANEL ASSY-HOOD	Not Necessary	1,654.00 FL	*- FL
4	1		*PANEL-FENDER, LH	Dented	502.00 FL	*502.00 FL
5	1		*CARRIER ASSY-FRONT END MODULE	Broken	760.00 FL	*760.00 FL
6	1		*BEAM COMPLETE- FR BUMPER	Not Necessary	551.00 FL	*- FL
7	1		*GUARD ASSY-FRONT WHEEL, LH	Torn	73.00 FL	*73.00 FL
8	1		*COVER-FR BUMPER UPR	Broken	645.00 FL	*645.00 FL
9	1		*GRILLE ASSY-RADIATOR	Not Necessary	738.00 FL	*- FL
10	1		*COVER-FR BUMPER, LWR	Cut	645.00 FL	*645.00 FL
11	1		*GRILLE-FRONT BUMPER FOG LAMP, LH	Broken	93.00 FL	*93.00 FL
12	1		*LAMP ASSY-FRONT FOG, LH	Broken	297.00 FL	*297.00 FL
13	1		*ABSORBER-FRONT BUMPER ENERGY	Not Necessary	134.00 FL	*- FL
14	1		*SKID PLATE-FR BUMPER	Cut	220.00 FL	*220.00 FL
15	1		*BRACKET-FR BPR SIDE REINF, LH	Missing	22.00 FL	*22.00 FL
16	1		*STIFFENER ASSY-FR BUMPER LWR	Not Necessary	117.00 FL	*- FL
17	1		*BRACKET-FR BUMPER SIDE, LH	Missing	17.00 FL	*17.00 FL
18	1		*LIP-FRONT BUMPER	Not Necessary	65.00 FL	*- FL
19	1		*ULTRASONIC SENSOR - S.P.A.S	Broken	187.00 FL	*187.00 FL
20	1		*ULTRASONIC SENSOR - S.P.A.S	Not Necessary	187.00 FL	*- FL
21	1		*ULTRASONIC SENSOR - S.P.A.S SIDE	Not Necessary	346.00 FL	*- FL
22	1		*WIRING ASSY-FRT (Supplementary)	Broken	2,555.00 FL	*2,555.00 FL
23	1		*WIRING ASSY-FEM (Supplementary)	Broken	538.00 FL	*538.00 FL
24	1		*GARNISH ASSY-DELTA LH (Supplementary)	Torn	109.00 FL	*109.00 FL
25	1		*WIRING HARNESS-FR BUMPER (Supplementary)	Torn	296.00 FL	*296.00 FL
26	1		*TELESCOPE UNIT ASSY-HEAD LAMP (Supplementary)	Broken	213.00 FL	*213.00 FL
27	1		*COVER-TELESCOPE, LH (Supplementary)	Missing	18.00 FL	*18.00 FL
28	1		*GARNISH ASSY-FNDR SIDE, LH (Supplementary)	Torn	88.00 FL	*88.00 FL
29	1		*CLIPS (10PCS) (Supplementary)	Necessary	10.00 FL	*10.00 FL
30	1		*BUZZER ASSY-PIEZO (Supplementary)	Broken	58.00 FL	*58.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	13,398.00	9,576.00
- List Item Discount on L Items 20.00/20.00% (\$\$)	2,669.60	1,911.20
Total Parts (\$\$)	10,728.40	7,664.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REPLACE FRT BUMPER, BONNET, SUPPORT & AFFECTED AREA. REPAIR ON FRT LH FENDER	New	2,000.00	1,600.00
2	PAINT WORK ON FRT BUMPER, BONNET & FRT LH FENDER	New	1,050.00	700.00
3	REMOVE & INSTALL FRT PARKING ASSIST FOR FACILITATE REPAIR	New	150.00	80.00
4	PERFORM RUST PREVENTION	New	80.00	0.00
5	REMOVE & INSTALL RADIATOR, CONDENSER FOR FACILITATE REPAIR	New	120.00	0.00
6	TO TOP UP AIRCON GAS	New	80.00	80.00
7	CHECK WIRING & CHASSIS ELECTRICAL SYSTEM	New	30.00	30.00
8	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST	New	120.00	120.00
9	TO APPLY ZERTONA COATING ON AFFECTED AREA	New	240.00	0.00
10	REMOVE & INSTALL DASHBOARD TO FACILITATE REPAIR (Supplementary)	New	400.00	400.00
11	REPLACE FRONT MAIN WIRING HARNESS AND REMOVE AIRCON BLOWER (Supplementary)	New	400.00	400.00
Gross Labour Cost (\$\$)			4,670.00	3,410.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >