



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD

PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name /CASLIN LEE HUI LING (LI HUILING) Reg No/Reg Date SLJ6923C / 21/12/201 Date In/Mileage / 0 Chassis No KNAPH81BMG5254852 Engine No D4HBGH287577 Make/Model KIA/SORENTO UM 2.2 A DIESEL 2WD ABV Colour/Trim MY3 IMPERIAL BRONZE/ WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LAX00000	Credit	22/05/2021/ 12:00		282 / Kevin Leong	33700
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
E PNT88000	REPLACE FRT ¹ BUMPER, BONNET, SUPPORT & AFFECTED AREA	4 x 400			1600 2000.00
	REPAIR ON FRT LH ¹ FENDER				
E PNT98000	PAINT WORK ON FRT ¹ BUMPER, BONNET & FRT LH ¹ FENDER	2 x 350			700 1050.00
E PNT88000	REMOVE & INSTALL FRT PARKING ASSIST FOR FACILITATE REPAIR				80 150.00
M SUNDRY	PERFORM RUST PREVENTION				7 80.00
E PNT88000	REMOVE & INSTALL RADIATOR, CONDENSER FOR FACILITATE REPAIR				120.00
M SUNDRY	TO TOP UP AIRCON GAS				7 80.00
A 54900099	CHECK WIRING & CHASSIS ELECTRICAL SYSTEM				30.00
A 10028901	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST				120.00
	USING HI-SCAN PRO TEST				
M SUNDRY	TO APPLY ZERTONA COATING ON AFFECTED AREA (Frt Bump, Frt LH Fend) Provide Seta, agent				7 240.00
M SUNDRY	SUNDRIES				20 50.00
M LAMP ASSY-HEAD, LH	BR	1.00	2210.00	20.00	1768.00
M PANEL ASSY-HOOD	X	1.00	1654.00	20.00	1323.20
M PANEL-FENDER, LH	BR	1.00	502.00	20.00	401.60
M CARRIER ASSY-FRONT END MODULE	BR	1.00	760.00	20.00	608.00
M BEAM COMPLETE-FR BUMPER	?	1.00	551.00	20.00	440.80
M GUARD ASSY-FRONT WHEEL, LH	TN	1.00	73.00	20.00	58.40
M COVER-FR BUMPER UPR	BR	1.00	645.00	20.00	516.00
M GRILLE ASSY-RADIATOR	?	1.00	738.00	20.00	590.40
M COVER-FR BUMPER, LWR	CAT	1.00	645.00	20.00	516.00
M GRILLE-FRONT BUMPER FOG LAMP, L	BR	1.00	93.00	20.00	74.40
M LAMP ASSY-FRONT FOG, LH	BR	1.00	297.00	20.00	237.60

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name /CASLIN LEE HUI LING (LI HUILING) Reg No/Reg Date SLJ6923C / 21/12/201 Date In/Mileage / 0 Chassis No KNAPH81BMG5254852 Engine No D4HBGH287577 Make/Model KIA/SORENTO UM 2.2 A DIESEL 2WD ABV Colour/Trim MY3 IMPERIAL BRONZE/ WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LAX00000	Credit	22/05/2021/ 12:00		282 / Kevin Leong	33700
Description of Goods / Services					
		Qty	Unit Price	Disc%	Amount
M ABSORBER-FRONT BUMPER ENERGY	✓	1.00	134.00	20.00	107.20
M SKID PLATE-FR BUMPER	✓ CUT (silver)	1.00	220.00	20.00	176.00
M BRACKET-FR BPR SIDE REINF,LH	✓ mis	1.00	22.00	20.00	17.60
M STIFFENER ASSY-FR BUMPER LWR	✓	1.00	117.00	20.00	93.60
M BRACKET-FR BUMPER SIDE,LH	✓ mis	1.00	17.00	20.00	13.60
M LIP-FRONT BUMPER	✓	1.00	65.00	20.00	52.00
M ULTRASONIC SENSOR-S.P.A.S	✓ OR	1.00	187.00	20.00	149.60
M ULTRASONIC SENSOR-S.P.A.S	✓	1.00	187.00	20.00	149.60
M ULTRASONIC SENSOR-S.P.A.S SIDE	✓	1.00	346.00	20.00	276.80

Estimate

Steve (LKK) 00-MAL
24/5/21, 1.00pm EXPRS -?
PIP
My Bel Sel
7 dys

Confirm & accepted by

	Nett	11,490.40
7% GST on	11490.40	804.33
Total Payable		12,294.73

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.